ACCEL	ERATED	DISTRI	BUTION	DEMONST	RATION	SYSTE	M
4				•			, , , ,*
	- REGU	JLATORY 1	NFORMATL	ON DISTRIBUTIO	N SYSTEM (KID5)	
FACIL:50 AUTH.NA	D-397 WPPSS AME Z	Nuclear AUTHOR AF	Project, FILIATIO Public	: 89/06/23 NO Unit 2, Washi N Power Supply S Power Supply S TION	ngton Publ vstem		
RECIP.1	NAME · · · ·	RECIPIENT	AFFILIA	TION .	•	· ·	R
		•				a due te	I.
SUBJECT	: LER 89-02] RPS EPA bi	L-00:on 8 ceaker ti	190527,ES ip - cau	F [°] isolations & se unknown.			D
		. •			W/8		
DISTRIB	JTION CODE:	IE22T C	OPIES RE	CEIVED:LTR / port (LER), In	ENCL (S		S
TTTLE:	50.73/50.9 1	PTCEUPEE:	Evenc Re			, , , , , , , , , , , , , , , , , , , ,	/
NOTES:							A
	RECIPIEN ID CODE/N PD5 LA SAMWORTH,R	NAME	COPIES LTTR ENC 1 1 1 1			COPIES MTR ENCL 1 1	ם ס ס
·	ACRS MICHEI ACRS WYLIE AEOD/DSP/TI DEDRO NRR/DEST/AI NRR/DEST/CI NRR/DEST/CI NRR/DEST/RS NRR/DEST/RS NRR/DLPQ/HI NRR/DOEA/EI NUDOCS-ABS RES/DSIR/EI RGN5 FILI	PAB DE 8H EB 8H CSB 7 TB 9H SB 8E FB 10 AB 11 TRACT	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	NRR/DEST/A	DSP AB DS 7E SB 8D EB 9H SB 8D SB 8D EB 10 PB 10 PB 10 02	2 1 2 1 1 1 1 1 1 1 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 1 2 1 1 2 1 2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	S R
	EG&G WILLIA L ST LOBBY	AMS,S WARD	4 4 [.] 1 1	FORD BLDG LPDR	HOY,A	1 1 1 1	I;
,	NRC PDR NSIC MURPHY		1 1 1 1	NSIC MAYS,	G	īī	D
	Cal 6	•	6~~78	3777			S

Cent NO p043078777

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42 D D S



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

June 23, 1989

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2 LICENSEE EVENT REPORT NO. 89-021

Dear Sir:

Transmitted herewith is Licensee Event Report No. 89-021 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,

C.M. Powers (M/D 927M) WNP-2 Plant Manager

CMP:1g

Enclosure: Licensee Event Report No. 89-021

cc: Mr. John B. Martin, NRC - Region V Mr. C.J. Bosted, NRC Site (M/D 901A) INPO Records Center - Atlanta, GA Ms. Dottie Sherman, ANI Mr. D.L. Williams, BPA (M/D 399)

(Int No Po43078717 IE22

3906300101 PDR ADOCK 050

NRC For 9-83) 1	•			ik.	LIC	ENSE	e eve	NT RE	PORT	(LER)		A	LEAR REGULAT PPROVED OMB KPIRES: 8/31/88		
	Y NAME (1											KET NUMBER (2			E (3)
				Plant - U Fety Featu			latio	ons an	d Act	uations	0 Due	5 0 0 to a Re	<u>0 3 9 /</u> actor Pr	1 OF	
-	Syst	em (F	PS) E	Electrical	Protec	tion	Assen	nbly (EPA)	Breaker	Trip	p - Cause	e Unknow	n	••••
EV	ENT DATE	(5)		LER NUMBER (PORT DAT	rE (7)		-		ILITIES INVOLV			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR		FACILITYN		C			<u> </u>
0 5	2 7	89	8 9	- 0 2 1	— o o	0 6	23	8 9					0 5 0 0	101	
OP1 M	ERATING	5		PORT IS SUBMITTE	D PURSUANT	r		ENTS OF 1	CFR §:			• following) (11)	22.74(5)		
POWE				402(b) 405(a)(1)(i)	-	20,405) 50,36(c			^	50,73(a)(2)(iv) 50,73(a)(2)(v)		-	73,71(b)		
LEVE (10)		0,0		405(a)(1)(ii)		50.36(c				50.73(a)(2)(vii))	-	OTHER /S	ecify in Abs	tract
			20.	405(a)(1)(iii)		50,73(a)(2)(i)			50,73(s)(2)(viii	i){A}	Γ	below and i 366A1	n Text, NRC	Form
			20.	405(a)(1)(iv)		60,73(a	1(2)(#)			50,73(e)(2)(viii	i)(B)				
			20,	405(a)(1)(v)		50,73(a		FOR THIS	1 60 (12)	50,73(a)(2)(x)					
AME							CONTACT		LEN (12/			т	ELEPHONE NUM	18ER	
			_									AREA CODE			
J	.D. A	rbuck	:le, (Compliance	v							^	3 7 7 -	211	Ш
CAUSE	SYSTEM	СОМР	ONENT	MANUFAC- TURER	REPORTABLE	EACH CI	OMPONEN		SYSTEM	COMPONENT		3) MANUFAC- TURER	REPORTABLE TO NPROS		
Х	JIC	۱ E	KIR	G10180	Y				<u> </u>	1 1 1					
		1	II						. 		•				
		÷		SUPPLEME	NTAL REPORT	EXPECT	ED (14)		_		_	EXPECTED		1 DAY	YEAF
ΥE	S (11 yes, c	omplete E	XPECTED	SUBMISSION DATE	,	x	NO					SUBMISSION DATE (15)			
On 1 (RPS- The Engin	May -EPA-3 loss neere	27, 3D) t of t d Saf	1989 trippo power fety f	at 1038 ed causing on RPS Feature (E for the a	hours g a los Bus B SF) act	an s of cause uatic	Ele powe eda ons.	r to half- At th	React scram le tim	n in RPS ne of the	ecti S D [.] e ev	on Syste ivision /ent the	em (RPS) B and	Bus multip	B. Dle
Inbo Plen ESF Emerg Opera	ard a um Rad actua gency ators	nd Ou diati ation Filt res	tboan on Mo s in tratic ponde	power can rd Isolati onitor "Z" cluding t on System, od by res to pre-eve	ons for signal he Sta and a toring	Grou (a r ndby Reac all	ups] non-N: Gas tor [syst	,2,5,6 SSSS E Treat Buildi ems,	and SF th tment ng Ve inclu	7; and rip signa (SGT) entilatio ding Res	a R al) Sys on S	eactor E which in tem, th ystem is	Building nitiates e Contr solation	Exhau sever ol Ro . Pla	ist al bom int
a p MS-DI cons [.]	otent PIS-8 ists (ial B), b of in	caus out th stall	event is r e (work ne cause c ing an up g capabili	in pro an not grade t	ogres be co o the	s or onclu e EPA	n Dif sively break	feren dete er ec	itial Pr ermined.	ess Fu	ure Ind Irther co	dicating prrective	Swit e acti	ch on
requ	iring	the	Eng	significa ineered S ations oc	afety	Featu	ire i	solat							
						×									, ,

.

4

•

ۍ <u>ج</u>

NRC Form 366A 9-83)	LICENSEE EVENT REP	ORT (LER) TEXT CONTI	NUATION		ULATORY COMMISSIO MB NO. 3150-0104 /83	
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NU	LER NUMBER (6)		
	,		YEAR SEQU	UENTIAL		
Washington	Nuclear Plant - Unit 2	0 15 10 10 10 1 3 19 1	7 8 9 0	2 1 - 0 0) 12 OF 0 14	

Plant Conditions

- a) Power Level 0%
- b) Plant Mode 5 (Refueling)

Event Description

On May 27, 1989 at 1038 hours an Electrical Protection Assembly (EPA) breaker (RPS-EPA-3D) tripped causing a loss of power to Reactor Protection System (RPS) Bus B. The loss of power on RPS Bus B caused a half-scram in RPS Division B and multiple Engineered Safety Feature (ESF) actuations. At the time of the event the Plant was in a shutdown condition for the annual maintenance and refueling outage.

The loss of RPS Bus B power causes Nuclear Steam Supply Shutoff System (NSSSS) Containment Inboard and Outboard Isolations for Groups 1 (Main Steam Line Drain Valves only), Group 2 (Reactor Water Sample Valves), Group 5 [Residual Heat Removal (RHR) and Traversing In-Core Probe (TIP) Systems], Group 6 (RHR Shutdown Cooling), and Group 7 [Reactor Water Cleanup (RWCU) System]. At the time of the event, both the TIP and RWCU Systems were already out of service for maintenance.

In addition, the loss of RPS Bus B power causes an NSSSS Group 3 (Primary and Secondary Containment Ventilation and Purge System) and partial Group 4 [Miscellaneous Balance of Plant (6-Valves)] isolation. These isolations occurred because RPS Bus B is the power supply for Reactor Building Exhaust Plenum Radiation Monitors (Channels B and D). Loss of RPS Bus B power de-energizes these monitors, causing a "Z" signal - a non-NSSSS ESF trip signal. All required Group 3 and 4 actions occurred as designed, including the automatic start of the Standby Gas Treatment (SGT) System and the Control Room Emergency Filtration System, and a Reactor Building HVAC Isolation.

Plant Operators responded by investigating the situation and, finding no immediate cause, shut EPA breaker RPS-EPA-3D and returned RPS Bus B to the normal power supply.

Immediate Corrective Action

As previously stated, Plant Operators responded by investigating the situation and, finding no immediate cause, returned RPS Bus B to the normal power supply. All systems were restored to pre-event lineup status within 22 minutes.

Further Evaluation and Corrective Action

- A. Further Evaluation
 - This event is reportable under 10CFR 50.73(a)(2)(iv) as "an event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS)."
 - 2. There were no structures, components or systems that were inoperable at the start of the event that contributed to the event.

NRC Form 366A (9-83) LICENSEE EVENT R	EPORT (LER) TEXT CONTIN		GULATORY COMMISSION DMB NO. 3150-0104 1/88
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION	
Washington Nuclear Plant - Unit	2 0 5 0 0 3 97	819 - 0 2 1 - 010	0 13 0F 0 14

- 3. The cause of this event is not known. A potential cause was identified following the trip but the cause cannot be conclusively determined. Immediately following the breaker trip, a review of all work in progress was conducted to identify any activities having the potential of causing a Work on Differential Pressure Indicating Switch MS-DPIS-8B (Main trip. Steam Line A High Flow) was in progress at the time of the trip which consisted of splice inspections and lug replacement. [MS-DPIS-8B is a flow switch in the logic circuit for relay RPS-RLY-K3B (Main Steam Isolation Valve Closed) which is utilized in the Nuclear Steam Supply Shutoff System actuation logic]. If during the work on MS-DPIS-8B a short occurred, it would be sensed on RPS Bus B and the EPA breaker might trip on undervoltage before a protective fuse on RPS-RLY-K3B opened. No method is available to confirm the probable cause; however, there have been no spurious trips during the last year of operation and none since this event.
- 4. Visual inspections of the breaker have also provided no indication of probable cause of the trip.
- 5. The EPA Breaker (RPS-EPA-3D) is manufactured by General Electric Company (Part No. TFJ226175W6).
- Β. Further Corrective Action
 - 1. The EPA Breaker Assembly (RPS-EPA-3D) was replaced with a spare component.
 - 2. An upgrade to the EPA breaker equipment has recently been developed that provides enhanced operating characteristics, including modifications to reduce susceptability to spurious trips, a "first-in, seal-in" indicator and improved output voltage control. This upgrade will be procured and installed, subject to availability of the modified components, by the end of the next maintenance and refueling outage.

Safety Significance

There is no safety signficance associated with this event because no Plant condition requiring the ESF isolations and actuations existed, and all ESF actuations occurred as designed.

In addition, at the time of the event reactor water level was greater than 22 feet above the reactor vessel flange with the fuel pool gate removed which provided a large heat sink for core cooling. Plant Operators responded by restoring all systems, including RHR Shutdown Cooling, to pre-event lineup status within 22 minutes.

Accordingly, this event posed no threat to the health and safety of either the public or Plant personnel.

Similar Events

LERs 87-019 and 87-025

NRC FORM 366A

LICENSEE EVENT REPO	ORT (LER) TEXT CONTIN		NUCLEAR REGULATORY COMMISS APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88
CILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	. PAGE (3)
Washington Nuclear Plant - Unit 2 CT (If more space is required, use additional NRC Form 388A's) (17)	0 5 0 0 0 3 9	YEAR SEQUENTIAL 7 8 9 0 2 1	
EIIS Information			
Text Reference		EIIS	Reference
		System	Component
EPA Breaker (RPS-EPA-3D)	JC	BKR	
Reactor Protection System (RPS)	JC		
RPS-Bus-B	JC	BU	
Nuclear Steam Supply Shutoff Syst	BD		
Main Steam Line Drain Valves	SN	LOV	
Reactor Water Sample Valves	AD	ISV	
Residual Heat Removal (RHR) Syste	BD		
Traversing In-Core Probe (TIP) Sy Reactor Water Cleanup (RWCU) Syst	IG CE		
Reactor Bulding Exhaust Plenum Ra		MON	
Standby Gas Treatment (SGT) Syste	BH		
Control Room Emergency Filtration	VH ·		
Reactor Building HVAC		VA	
MS-DPIS-8B		. SB	PDIS
RPS-RLY-K3B	F •	JC	RLY

. . .

• "

2