DOC.DATE: 89/07/14

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

NOTARIZED: NO

DOCKET #

R

FACIL: 50 AUTH.NA DAVISION POWERS: 0	AME AUTHOR A.W.S. mr. Washing	AFFILIATION ton Public Po ton Public Po	nit 2, Washington ; wer Supply System; wer Supply System; ON	re rateol	)5000397
SUBJECT	: LER 89-024-00:o found greater t	n 890614,seco han allowed b	ndary containment l y design basis.	bypass leakage W/8 ltr	
DISTRIBUTITLE 2 5	UTION CODE: IE22T 50.73/50.9 Licens	COPTES RECE	IVED:LTR . ENCL.	SIZE: 6	· ·
NOTES:		; .			
	RECIPIENT ' ID CODE/NAME PD5 LA SAMWORTH,R	COPIES LTTR ENCL 1 1 1 1	RECIPIENT ID CODE/NAME PD5 PD	COPIES LTTR ENCL 1 1	
INTERNAL:	ACRS MICHELSON ACRS WYLIE AEOD/DSP/TPAB DEDRO	1 1 1 1 1 1	ACRS MOELLER AEOD/DOA AEOD/ROAB/DSP IRM/DCTS/DAB	2 2 1 1 2 2 1 1	

NRR/DEST/ADS 7E

NRR/DEST/ESB 8D NRR/DEST/MEB 9H NRR/DEST/PSB 8D NRR/DEST/SGB 8D

NRR/DLPQ/PEB 10

NRR/DREP/RPB 10

RES/DSR/PRAB

REG FILE

RGN5 FILE 01 1 1

EXTERNAL: EG&G WILLIAMS,S 4 4 FORD BLDG HOY,A 1 1
L ST LOBBY WARD 1 1 LPDR 1 1
NRC PDR 1 1 NSIC MAYS,G 1 1
NSIC MURPHY,G.A 1 1

1

#### NOTE TO ALL "RIDS" RECIPIENTS:

NRR/DEST/ADE 8H

NRR/DEST/CEB 8H NRR/DEST/ICSB 7 NRR/DEST/MTB 9H NRR/DEST/RSB 8E

NRR/DLPQ/HFB 10

NRR/DOEA/EAB 11

NUDOCS-ABSTRACT

RES/DSIR/EIB

ACCESSION NBR:8907190359

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42

glo 4

#### WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

July 14, 1989

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2

LICENSEE EVENT REPORT NO. 89-024

Dear Sir:

Transmitted herewith is Licensee Event Report No. 89-024 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,

℃.M. Powers (M/D 927M)

WNP-2 Plant Manager

CMP:1g

Enclosure:

Licensee Event Report No. 89-024

Mr. John B. Martin, NRC - Region V Mr. C.J. Bosted, NRC Site (M/D 901A) INPO Records Center - Atlanta, GA Ms. Dottie Sherman, ANI

Mr. D.L. Williams, BPA (M/D 399)

(ext No p2724
pn14192724

,				~		•	-	<b>A</b>	• '										-								
IRC Form (9-83)	366				<u>_</u>	•	•	ric	ENSEI	E EVE	NT RE	PORT	Γ (	LEF	t)				U	.s. I	AF	PROV		BNC	Y COM 0. 3150-C		ON
FACILITY	NAME (1	)						•					_				000	KET	NU	MBI	R (2	)			PA	GE (3	3
			luc	:Te	ar Pl	ant -	Uni	t 2									0	5	10	10	0   0	0   3	19 I	7	1 01	Fl 0	16
TITLE (4)	Seco	nda	rv	C	ontai	nment	Byp	ass L	eakag	e Fou	nd To	о Ве	Gr	'ea'	te	r 1	har	ı A	(11	OV	ved	By	Des	sia	n		
	Basi	Sã	ıs	a	Resul	t of	Eaui	pment	Desi	an De	fici	ency			_							Ĭ					
EVI	NT DATE		Ť			ER NUMBE				ORT DAT						OTHE	R FA	CILIT	ries	IN۱	/OLV	ED (8					
MONTH	DAY	YEA	ıR	YE	AR 🎆	SEQUENT	AL S	REVISION	монтн	DAY	YEAR			FA	CIL	ITY N	AMES	•			P	OCKE	T NUM	BER(	5)		
······································			寸																		0	) <sub> </sub> 5	101	0	0 1_		11
			1		1						_																
0 6	1 4	l 81	9	8	او ا	0 2	4	lolo	o  7	1  4	8 9										Q	15	10	0 1	0	1	1_
	RATING			_		IS SUBMI		RSUANT	O THE R	EQUIREME	NTS OF	O CFR §	: <i>(</i> C	heck c	ne e	or mo	re of t	he fo	llow	ing)	(11)						
M	DDE (9)		5		20.402(b	)	-		20,405(	c)			ΧĪ	50.7	3(0)	(2)(iv	)						3.71(ъ)				
POWE	R				20,405(a	){1)(i)			50,36(c)	(1)				50.7	3(e)	(2)(v)						] ;	3.71(c)				
LEVE (10)	۱ lo	ı Oı	0		20,405(a	)(1)(ii)			50,36(c)	(2)				50.7	3(a)	{2}(vi	)					$\square$ :	THER	(Spec	ify in A Text, Ni	bstrec BC Fo	t
			<b>***</b>		20,405(a	)(1)(iii) ,			50.73(*)	)(2)(i)				50,7	3(a)	(2)(vi	i)(A)				Γ		66A)	• ""	• • • • • • • • • • • • • • • • • • • •		****
			▩		20.406(a	)(1)(lv)		X	50,73(a)	)(2)(#)				50.7	3(a)	(2)(vi	i)(B)				1						
					20,405(4	)(1)(v)			50,73(4)	)(2)(iii)				50.7	3(a)	(2)(x)											
								• 1	ICENSEE	CONTACT	FOR TH	S LER (1:	2)													•	
NAME																		L			TELEPHONE NUMBER						
							•											AR	IEA	COE	DE				•		
. w	.s. D	avi	so	n.	Comp	lianc	e_En	ginee	r		•							<u></u>	ملة	11	9	317	17	_1	21	<b>ZL2</b>	<b>1</b> 6.
						COMPLE	TE ONE	LINE FOR	EACH CO	MPONEN'	FAILUR	E DESCR	18E	מו ס	THI	S REP	ORT	(13)				,		122	******	******	********
CAUSE	SYSTEM	co	МРС	NEN	IT N	ANUFAC- TURER		PORTABLE D NPRDS			CAUS	ESYSTE	м	со	MPC	DNEN	T		TUR		;. 		RTABL NPRDS				
														1						L	L						
											· .										_						
					<u> </u>	Ш					<u> </u>				_		$\dashv$	1			L.	<u></u>		88		****	<u></u>
						SUPPL	EMENTA	L REPORT	EXPECT	ED (14)									, E	XPE	CTED	).	мог	HTF	,DAY	+	EAR
YE	S (If yes. a	omple	te E.	XPEC	TED SUB	MISSION D	ATE)		l <sub>v</sub>	) NO									\$U 0	ATE	SS101 E (15)	N			1		ı
						ximately fif		e-spece typ	ewritten lii	nes) (16)			_				1-								<b>!</b>		

On June 14, 1989, during a plant design review for unmonitored containment release paths, a Plant Design Engineer identified a potential path through which radioactive liquid from the primary containment could bypass the leakage collection and filtration systems associated with the secondary containment. The bypass leakage path identified was the Control Rod Drive (CRD) System Hydraulic Control Unit (HCU) control valves. This postulated event was evaluated as having the potential to result in bypass leakage of a quantity large enough to violate the WNP-2 design basis for control room habitability radiation dose limits after a Loss Of Coolant Accident (LOCA). An engineering assessment determined that installation of two check valves in series in the common discharge line of the CRD pumps would provide a barrier sufficient to prvent bypass leakage through the These valves were installed on June 24, 1989, prior to the end of the refueling outage before the plant startup. The immediate cause of this event was equipment design deficiency in that the CRD system design was potentially not capable of preventing post LOCA liquid bypass leakage from exceeding the design basis limit. plant design review to verify that there are no other potential unmonitored release paths will continue as originally described in LER 88-012-00. The probability of occurrence of a LOCA event of sufficient magnitude to cause major fuel damage, concurrent with a seismic event causing failure of the condensate system outside of secondary containment Since no event actually occurred at WNP-2 during the time prior to correction of the CRD system bypass leakage problem, this event posed no threat to the health and safety of Plant personnel or the public.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.\$. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

ACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)						
		YEAR SEQUENTIAL REVISION NUMBER							
Washington Nuclear Plant - Unit 2	0  5  0  0  0   3   9   7	819 - 012 14 - 010	)  2 OF 0  5						

TEXT (If more space is required, use additional NRC Form 368A's) (17)

### Plant Conditions

- a) Plant Mode 5 (Refueling)
- b) Power Level 0%

### **Event Description**

On June 14, 1989, during a plant design review for unmonitored containment release paths, a Plant Design Engineer identified a potential path through which radioactive liquid from the primary containment could bypass the leakage collection and filtration systems associated with the secondary containment. The bypass leakage path identified was the Control Rod Drive (CRD) System Hydraulic Control Unit (HCU) control valves. These valves potentially were capable of allowing backleakage from the reactor vessel through 740 operating lines through the CRD pumps and into the Condensate System which is located outside of the secondary containment. postulated event was evaluated as having the potential to result in bypass leakage of a quantity large enough to violate the WNP-2 design basis for control room habitability radiation dose limits after a Loss Of Coolant Accident (LOCA). evaluation was being performed as part of corrective action for LER 88-012-00 "Potential **Unmonitored** Effluent Release Path Due to Design Architect/Engineer Cause Unknown".

The CRD System connects the Condensate System to the reactor vessel via the suction line for the system pumps CRD-P-1A and CRD-P-1B. The system pump common discharge line is connected to 185 Hydraulic Control Units (HCU) by 370 two inch and 370 one inch CRD system oeprating lines. Each HCU is connected to a CRD Mechanism (attached to the reactor vessl bottom head) by a one inch control rod insert operating line and a three quarter inch control rod withdraw operating line. This design configuration results in 740 parallel leak paths which, after a LOCA, potentially could allow water to flow from the reactor vessel through the CRD System and into the Condesnate System thus bypassing the secondary containment system.

### Immediate Corrective Action

An engineering assessment determined that installation of two check valves in series in the common discharge line of the CRD pumps would provide a barrier sufficient to prevent bypass leakage through the CRD system. These valves were installed on June 24, 1989, and leak tested to confirm compliance with leakage criteria prior to the end of the refueling outage, before the plant startup

# Further Evaluation and Corrective Action

## A. <u>Further Evaluation</u>

- 1. This event is reportable per the following:
  - o 10CFR50.73(a)(2)(ii)(B)- as a condition that was outside the design basis of the plant.

Form	366A

# LICENSEE EVERT REPORT (LER) TEXT CONTINUATION

ILS NUCLEAR REGULATORY COMMISSION APPROVED OMB NO: 3150-0104

Z							
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)				
,		YEAR SEQUENTIAL REVISION NUMBER					
Washington Nuclear Plant - Unit 2	0  5   0   0   0   3   9   7	819 - 012 14 - 010	0  3 OF 0  5				

- TEXT (If more space is required, use additional NRC Form 366A's) (17)
  - 10CFR50.73(a)(2)(v) as a condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to: (C) control the release of radioactive material; or (D) mitigate the consequences of an accident.
  - There were no plant structures, components, or systems inoperable at the 2. start of this event that contributed to the event.
  - The immediate cause of this event was equipment design deficiency in that the CRD system design was potentially not capable of preventing post LOCA liquid bypass leakage from exceeding the design basis limit. The root cause investigation is still in progress. Any substantive information resulting from its completion will be reported in a supplementary LER.
  - 4. The total potential liquid bypass leakage from the CRD System prior to installation of the two check valves was estimated by assuming leakage based on the ASME Section XI leakage criteria as follows:

Valve Designation	Number Of Valves Installed	<u>Leakage Per Valve</u>
CRD-V-126XXXX CRD-V-115XXXX	185	0.018 GPM
CRD-V-120XXXX CRD-V-123XXXX	185	0.018 GPM
CRD-V-122XXXX CRD-V-121XXXX	185	0.018 GPM
CRD-V-138XXXX	185	0.036 GPM
	TOTAL LEAKAGE	16.65 GPM = 134.0 SCFH

# The design basis total allowable bypass leakage rate is 0.74 SCFH

XXXX= CRD NUMBER DESIGNATION-EACH CRD HAS ONE HCU CONTAINING 7 VALVES WHICH ISOLATE FOUR OPERATING LINES FOR A TOTAL OF 1295 VALVES WHICH ISOLATE 740 INDIVIDUAL LINES.

CRD-V-126XXXX = The inlet scram valve for each HCU

CRD-V-115XXXX = Check valve installed on the pump side of the CRD-V-126XXXX valve for each HCU.

CRD-V-120XXXX = Over piston directional control valve for each HCU.

CRD-V-123XXXX = Over piston directional control valve for each HCU.

CRD-V-122XXXX = Under piston directional control valve for each HCU.

CRD-V-121XXXX = Under piston directional control valve for each HCU.

CRD-V-128XXXX = Check valve installed on the cooling water line for each HCU.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

<u> </u>	•				
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
4	1	YEAR SEQUENTIAL REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0  5  0  0  0  3  9  7	819 - 012 14 - 010	0 14 OF 0 15		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

### B. Further Corrective Action

- The plant design review to verify that there are no other potential unmonitored release paths requiring monitoring will continue as originally described in LER 88-012-00.
- 2. General Electric, Inc., the WNP-2 Nuclear Steam Supply System contractor, has been notified of this condition at WNP-2. This condition is not being reported to the NRC as a 10CFR21 violation because, as specified in 10CFR21.1, the Supply System has knowledge that the Commission has been adequately informed of such defects. Correction of this design deficiency was included in granting the Susquehanna and Lasalle plant operating licenses.

### Safety Significance

The maximum potential release of liquid and gaseous radioactive material via bypass leakage paths for WNP-2 is analyzed as 0.74 scfh. This will ensure that control room dose and radioactive release to the environment is within the range allowed by 10CFR100. The potential for leakage as a result of the newly identified CRD system bypass path was analyzed as 134 scfh. This is many times the allowable limit and could potentially have resulted in the release of significantly more radioactive material than predicted by design basis calculations under the worst-case post LOCA assumptions. The probability of occurrence of a LOCA event of sufficient magnitude to cause major fuel damage, concurrent with a seismic event causing failure of the condesate system outside of secondary containment is very low. Since no event actually occurred at WNP-2 during the time prior to correction of the CRD system bypass leakage problem, this event posed no threat to the health and safety of Plant personnel or the public.

## Similar Events

LER 88-012-00 documented a condition in which a potential unmonitored release path for radioactive material was identified which might allow air flow from the Turbine Building through the Diesel Generator Building corridor to the atmosphere. This condition was also caused by equipment design deficiency. This LER (89-024-00) is a direct result of corrective action formulated during the event documented by LER 88-012-00.

#### **EIIS Information**

Text Reference	EIIS	Reference
	System	Component
Primary Containment	NH	
Secondary containment	NG	
Control Rod Drive System	AA	

1FAC Form 388A 9-83) . 2 3	LICENSEE EVE	NT REPORT (LER) TEXT CO	NTINUATION		ULATORY COMMISSION MB NO, 3150-0104 /88
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUM	BER (6)	· PAGE (3)
			YEAR SEQUE	NTIAL REVISION	
Washingto	on Nuclear Plant - U	Unit 2 O IS 10 10 10 3	1917 819 _ 012	14 _ 010	0 15 OF 0 15

TEXT (If more space is required, use additional NRC Form 368A's) (17)

## **EIIS Information**

Text Reference	EIIS Reference				
·	System	Component			
Hydraulic Control Unit	AA	HCU			
Control Valves	AA	XCV			
Reactor Vessel	AC	RP V			
Condensate System	SD				
CRD-P-1A,CRD-P-1B	AA	Р			
CRD Mechanism	. AA	84			
Check Valves	AA	٧			
CRD-V-126XXXX,-115XXXX,-120XXXX,-123XXXX,-122XXXX,	AA	Ý			
-121XXXX,-138XXXX					
Turbine Building	· NM				
Diesel Generator Building	٧J				