

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

Р

ACCESSION NBR:9409190360 DOC.DATE: 94/09/09 NOTARIZED: NO DOCKET # FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397 AUTH.NAME AUTHOR AFFILIATION Washington Public Power Supply System RECIPIENT AFFILIATION PARRISH, J.V. RECIP. NAME Document Control Branch (Document Control Desk) SUBJECT: Informs that Agastat relay robbin failures was not reportable event per requirements of 10CFR21 or 50.73. DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR ENCL TITLE: OR Submittal: General Distribution NOTES: COPIES RECIPIENT COPIES RECIPIENT ID CODE/NAME LTTR ENCL ID CODE/NAME LTTR ENCL PD4-2 LA PD4-2 PD 1 2 CLIFFORD, J INTERNAL: ACRS 6 FILE CENTER 01 1 NRR/DE/EELB NRR/DRCH/HICB 1 NRR/DRPW 1 NRR/DSSA/SPLB 1 NRR/DSSA/SRXB NUDOCS-ABSTRACT 1 OC/LFDCB OGC/HDS3 1

NRC PDR

# NOTE TO ALL "RIDS" RECIPIENTS:

EXTERNAL: NOAC

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083 ) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL



1

, y<sub>3</sub>, •



## WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

September 9, 1994 GO2-94-213

Docket No. 50-397

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

#### Gentlemen:

Subject:

WNP-2, OPERATING LICENSE NPF-21 AGASTAT RELAY BOBBIN FAILURES DUE TO THERMAL BREAKDOWN

References:

- 1) GE SIL 384, dated October 1982, "Connection Failures in Agastat Relay Type CR0095 Bases"
- 2) SER 71-82 (OER 82092A), dated December 1982, "Connection Failures in Agastat Relay Type CR0095 Bases"
- 3) SER 82068 (OER 82100B), dated January 1984, "Problems Encountered with Certain Agastat GP Series Relays"
- 4) IEN 84-20 (OER 84029A), dated March 1984, "Service Life of Relays in Safety Related Systems"
- 5) INP OE 4040, dated July 1990, "Failure of Normally Energized Relays During Safeguards Test"

As discussed below, WNP-2 recently experienced failures of Amerace Corporation Agastat type EGPI relays. This condition was determined to be not reportable per the requirements of either 10 CFR 21 or 10 CFR 50.73. The information provided below is for your use.

Recent failures of Agastat type EGPI relays that were normally energized during power operation prompted an evaluation of the associated failure mechanism. From this evaluation, engineering determined that the nylon bobbin of the EGPI relay deteriorates after prolonged exposure to high temperature. The rate of deterioration depends on relay coil temperature. The

7409190360 940909 PDR ADDCK 05000397 PDR A001

# Page Two AGASTAT RELAY BOBBIN FAILURES DUE TO THERMAL BREAKDOWN

coil temperature generated in a mild environment is high enough to cause deterioration. The failure mode is cracking and structural breakdown of the coil bobbin; in turn, this breakdown can impede the moving relay core's motion and thus preclude the relay contacts from changing state. Other Amerace Corporation relay models having the same bobbin materials and thus potentially being susceptible to this failure mechanism are GPB, GPD, GPI, EGPB, and EGPD. The "E" series relays are nuclear grade. The Supply System uses these nuclear-grade model relays in Nuclear Steam Supply Shutoff and Emergency Core Cooling System actuation instrumentation.

Should you have any questions or desire additional information regarding this matter, please call me or Mr. D. A. Swank at (509) 377-4563.

Sincerely,

1. V. Parrish (Mail Drop 1023)

Assistant Managing Director, Operations

### KEB/bk

cc:

LJ Callan - NRC RIV

KE Perkins, Jr. - NRC RIV, Walnut Creek Field Office

NS Reynolds - Winston & Strawn

JW Clifford - NRC

DL Williams - BPA/399

NRC Sr. Resident Inspector - 927N

. •

•

.

• ů ů

.

•