REGULATOR INFORMATION DISTRIBUTION TEM (RIDS) ACCESSION NBR:8011170577 DOC.DATE: 80/11/05 NOTARIZED: NO DOCKET # FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528 AUTHOR AFFILIATION AUTH, NAME mp VAN BRUNT, E.E. Arizona Public Service Co. 3 RECIPIENT AFFILIATION RECIP.NAME Region 5, San Francisco, Reactor Construction & Engineer SPENCER, G.S. SUBJECT: Final deficiency rept re cable splice on non-Class IE single conductor 350 KCMIL,600v power cable from Rockbestos Reel A-478. Actions implemented to assure that only qualified Rockbestos power cable utilized for Class IE circuits. ENCL SIZE: DISTRIBUTION CODE: B019S COPIES RECEIVED:LIR _

NOTES:Standardized Plant.

COPIES RECIPIENT COPIES RECIPIENT ID CODE/NAME LTTR ENCL LITTR ENCL ID CODE/NAME MIRAGLIA, F. 05 1 1 ACTION: A/D LICENSNG 04 1 1 1 1 LEE, J. 06 1 1 KERRIGAN, J. 07 INTERNAL: AD/RCI/IE 17 1 1 AEOD 18 1 1 ASLBP/J.HARD 1 D/DIR HUM FAC15 1 1 1 EQUIP QUAL BR11 1 1 EDO & STAFF 19 1 1 22 1 1. 18E 09 1 1 HYD/GEO BR 20 1 MPA. 1 LIC QUAL BR 12 1 1 21 NRC PDR OELD 1 1 20 1 1 PROC/IST REV 13 14 1 1 1 1 QA BR RUTHERFORD, W, IE REG FILE 01 1 1 1 1 STANDRDS DEV 21 1 1 1 16 LPDR 03 1 16 16 EXTERNAL: ACRS 80 1 NSIC 1

TITLE: Construction Deficiency Report (10CFR50,55E)

NOV 1 8 1980

05000528

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39



• **A** .

.

Υ.

.

. В с ,

1

* • • • • * •

- - - -

i H

1000

. .

۰ • • • •



PUBLIC SERVICE COMPANY

P. O. BOX 21666 . PHOENIX, ARIZONA 85036

November 5, 1980 ANPP-16691-BSK/JAR

55

Ċ,

S

U. S. Nuclear Regulatory Commission Region V Walnut Creek Plaza - Suite 202 1990 North California Boulevard Walnut Creek, California 94596

Attention: Mr. G. S. Spencer, Chief Reactor Construction and Engineering Support Branch

Subject: A 50.55(e) Potentially Reportable Deficiency Relating to Class 1E, 600V, Power Cable Final Report File: 80-019-026

- Reference:
- (1) Letter ANPP-15090-JAR, dated March 24, 1980 (DER 80-4)
 - (2) Interim Report, ANPP-15507-BSK/JAR, dated May 23, 1980
 - (3) Interim Report, ANPP-16084-BSK/JAR, dated August 4, 1980

Dear Sir:

Attached, is our final written report of the potentially reportable deficiency, under 10CFR50.55(e), relating to Class 1E, 600V, Power Cable supplied by Rockbestos Company. A preliminary written report and subsequent interim reports were transmitted by Reference (1), (2) and (3), respectively.

At the time of discovery, the disposition and/or location of factory repaired cable was not known. However, as a result of extensive investigation, evaluation and testing, Rockbestos has presented documentation demonstrating qualification of repaired and unrepaired 600V Class IE cables. The documentation eliminates any concern that a potential may have existed for a common mode failure on a redundant system because of the presence of unqualified factory repairs. If the condition were to remain undetected, it would not have constituted a significant deficiency; therefore, this condition is considered not reportable.

Very truly/yours

E. E. Van Brunt, Jr. APS Vice President Nuclear Projects ANPP Project Director

8011170577

EEVBJr/BSK:skc Attachments



-/ 5 xer/ €_5 €_5 €_5 . . . ,∎ ↓ ÷

4

n € 3

•

٩ ٠ .

*,

я

۰,

ı

ę

U. S. Nuclear Regulatory Commission Attention: Mr. G. S. Spencer, Chief ANPP-16691-BSK/JAR November 5, 1980 Page 2

cc: Victor Stello, Jr., Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

ţ

A. C. Gehr Snell & Wilmer

R. L. Robb

D. B. Fasnacht

W. E. Ide

J. M. Allen

A. C. Rogers

W. H. Wilson

W: G. Bingham

W. J. Stubblefield R. L. Patterson

R. W. Welcher

R. M. Grant

D. R. Hawkinson

J. A. Brand

J. T. Barrow

1

Ì ł

a state of the state of the

-1 ž ٠

. •

FINAL REPORT

POTENTIAL REPORTABLE DEFICIENCY 50.55(e) ARIZONA PUBLIC SERVICE COMPANY (APS) PVNGS UNIT #1

I. <u>Description of Deficiency</u>

A non-Class 1E, single conductor, 350 KCMIL, 600V power cable from Rockbestos Reel No. A-478, was being prepared for cable pulling on November 16, 1979. A discovery of a discontinuity in the periodic footage marks on the cable jacket led to the removal of this section and revealed an unexpected "Cable Splice", i.e., two lengths of completed cable had been joined to produce one continuous length. The technical specifications for this cable did not address factory repairs in any respect. Investigation of this finding revealed that the insulation repair material utilized by the supplier, Rockbestos, from the inception of production of cables for Palo Verde until November, 1979, was Union Carbide Compound 4201. also known as KXL-420. This material was never specifically tested for the Class 1E qualification.

In addition, the insulation repair material appeared to be undercured, i.e., not cross-linked. It was also found that multiconductor cables were not spliced by joining two lengths of completed cable to produce one continuous length, but individual insulated conductors of multiconductor cables, as required, were spliced and then their insulations and overall jacket repaired. In both cases, the material used in insulation repair by the vendor, was different than the material used in LOCA and fire resistance test samples subjected to qualification testing in compliance to Purchase Specification 10407-13-EM-058.

Stop Work Order 80-SW-1 was initiated by APS and issued by Bechtel on March 5, 1980 to stop the installation of Rockbestos Class 1E cables. Class 1E cables already delivered to PVNGS were quarantimed. On March 7, 1980, NCR E-X-399 was issued against the previously pulled Rockbestos cable in Class 1E circuits.

II. Analysis of Safety Implications

Although this deficiency was discovered in a non-Class lE cable, it was considered a significant issue because all of the 600V power cable is purchased as Class 1E regardless of its application, except that the cable needed for Class 1E application is color coded.

4.

4

. •

-a state of the second state of a local

•

a

.

.

+

Final Report Page 2

> The Class 1E, 600V, cables supplied by Rockbestos are part of the Class 1E, AC 480V and DC 125V power systems and, therefore, supply power to safety-related electrical equipment. The loss of cable due to the failure of one of these repairs before or during a design basis event could result in the degradation of the function of that system.

At the time of discovery, the disposition and/or location of repaired cable was not known. However, as a result of extensive investigation, evaluation and testing, Rockbestos has presented documentation demonstrating qualification of repaired and unrepaired 600V, Class 1E, cables. The documentation eliminates any concern that a potential may have existed for a common mode failure on a redundant system because of the presence of unqualified factory repairs. If the condition were to remain undetected, it would not have constituted a significant deficiency; therefore, this condition is considered not reportable.

III. - Corrective Action

The following specific actions have been implemented by Bechtel to assure that only fully qualified Rockbestos power cable has been utilized for Class IE circuits.

- In the Containment Building, 600V power Class 1. 1E circuits will use cable produced under new Rockbestos procedure for PVNGS which bans splicing and insulation rework, and identifies reels containing jacket rework through traceability records and reel tag coding. Also, cable codes for Class 1E circuits inside the containment will have a "C" designator on construction pull cards and on the reels to assure the usage of proper cables. This conservative policy is being followed even though Rockbestos has presented documentation demonstrating qualification of unrepaired and repaired, cured and uncured, single conductor and multiconductor Class IE cable for use inside and outside containment.
- 2. Outside the Containment Building, 600V power Class 1E circuits will use:
 - a. Cable produced after April 1, 1980 which is not spliced, does not have insulation rework, and jacket reworked reels are identified and traceable. (Bechtel Log No. E-058-13 and E058-40)

•

٠ • 7

é

1

I

-

-

Final Report Page 3

- b. Cable produced prior to October 1, 1979 which may contain cured or uncured KXL-420 insulation repair material. Repaired cables were tested and passed IEEE-383 qualification requirements. (Bechtel Log No. E058-39)
- c. Cable produced October, 1979 to April 1, 1980 which may contain cured KXL-760 repair material were tested and passed IEEE-383 qualification requirements. (Bechtel Log No. E058-39)

5

ł

•

کر ٩

•

• • • .

.

7

ĸ

•

•