

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8802030004 DOC. DATE: 88/01/25 NOTARIZED: NO DOCKET #  
 FACIL: STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Public 05000530  
 AUTH. NAME AUTHOR AFFILIATION  
 HAYNES, J. G. Arizona Nuclear Power Project (formerly Arizona Public Serv  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special Rept 3-SR-87-006: on 880117, loose-part  
 instrumentation for more than 30 days. Calibr will be  
 performed by end of first outage. Periodic audio check will  
 be performed until instrument operable.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Standardized plant.

05000530

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	LICITRA, E	1 1	DAVIS, M	1 1
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADS	1 0	NRR/DEST/CEB	1 1
	NRR/DEST/ELB	1 1	NRR/DEST/ICSB	1 1
	NRR/DEST/MEB	1 1	NRR/DEST/MTB	1 1
	NRR/DEST/PSB	1 1	NRR/DEST/RSB	1 1
	NRR/DEST/SGB	1 1	NRR/DLPQ/HFB	1 1
	NRR/DLPQ/QAB	1 1	NRR/DOEA/EAB	1 1
	NRR/DREP/RAB	1 1	NRR/DREP/RPB	2 2
	NRR/DRIS/SIB	1 1	NRR/PMAS/ILRB	1 1
	<u>REG FILE</u> 02	1 1	RES TELFORD, J	1 1
	RES/DE/EIB	1 1	RES/DRPS DIR	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G GROH, M	5 5	FORD BLDG HOY, A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC HARRIS, J	1 1
	NSIC MAYS, G	1 1		
NOTES:		1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 47





**Arizona Nuclear Power Project**

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00339-JGH/TDS/JEM  
January 25, 1988

U.S. Nuclear Regulatory Commission  
NRC Document Control Desk  
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)  
Unit 3  
Docket No. STN 50-530 (License No. NPF-74)  
Special Report 3-SR-87-006  
File: 88-020-404

Attached please find Special Report 3-SR-87-006 prepared and submitted pursuant to Technical Specification 3.3.3.7. Action Statement "a" and 6.9.2. This report discusses the Loose-Part Detection Instrumentation being inoperable greater than 30 days.

If you have any questions, please contact T. D. Shriver, Compliance Manager at (602) 393-2521.

Very truly yours,

J. G. Haynes  
Vice President  
Nuclear Production

JGH/TDS/JEM/kj

Attachment

cc: O. M. DeMichele (all w/a)  
E. E. Van Brunt, Jr.  
J. B. Martin  
J. R. Ball  
E. A. Licitra  
A. C. Gehr  
INPO Records Center

8802030004 880125  
PDR ADDCK 05000530  
S PDR

IE22  
11



PALO VERDE NUCLEAR GENERATING STATION

LOOSE-PART DETECTION INSTRUMENTATION

License No. NPF-74

Docket No. 50-530

Special Report No. 3-SR-87-006

This Special Report is being submitted pursuant to Technical Specification 3.3.3.7 ACTION "a" and Technical Specification 6.9.2. This report addresses an event where the loose-part detection instrumentation was inoperable for more than 30 days. The 30 day period for returning the system to an operable status was exceeded at approximately 0728 on January 17, 1988.

The loose-part detection instrumentation was originally declared inoperable pending the assimilation and evaluation of base line data. The data was obtained during power ascension testing; however, the instrumentation has remained inoperable due to a high rate of spurious alarms. The alarms have been verified, with a spectrum analyzer, to be spurious. A site modification has been issued which requires modification of selected circuit cards. The modifications are expected to reduce the spurious alarm rate. Additionally, some of the alarms are being cleared by adjusting the setpoints above the background noise. Although this calibration technique is not considered a permanent corrective measure it will permit the indication of a dynamic change in the Reactor Coolant System. Changes such as these may be indicative of a "loose part" and alert the operators to take additional actions as necessary. The instrumentation remains available for data collection.

In order to restore the loose-part detection instrumentation to an operable status the alarm circuitry must be calibrated from the installed sensors. The sensors are located on reactor coolant piping and on the reactor vessel. Therefore, the circuits cannot be calibrated while the unit is operating. It is planned to have the loose-part detection instrumentation calibrated by the end of the first outage of sufficient duration which will permit the required access.

As a prudent measure the Shift Technical Advisors will periodically perform a channel audio check until the instrumentation is returned to an operable status. This check should detect noise changes in the Reactor Coolant System that may be indicative of a loose part.

