

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Venture Lighting International, Inc. 2451 E. Enterprise Parkway Twinsburg, OH 44087</p> <p>REPORT NUMBER(S) 2017001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>030-38541</p>	<p>4. LICENSE NUMBER(S)</p> <p>34-26659-03E</p>	<p>5. DATE(S) OF INSPECTION</p> <p>10/17/17</p>
---	---	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Kevin G. Null	<i>K. G. Null</i>	10/17/17
BRANCH CHIEF	<i>Robert T. McCraw</i>	<i>[Signature]</i>	11/1/17

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Venture Lighting International, Inc. 2451 E. Enterprise Parkway Twinsburg, OH 44087 REPORT NUMBER(S) 2017001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-38541	4. LICENSE NUMBER(S) 34-26659-03E	5. DATE(S) OF INSPECTION October 17, 2017
--------------------------------------	--	--

6. INSPECTION PROCEDURES USED 87128	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03251	2. PRIORITY 5	3. LICENSEE CONTACT Joshua Barry, RSO	4. TELEPHONE NUMBER (234) 212-3841
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: 10/17/2022

Field Office Inspection Glenwillow, OH

Temporary Job Site Inspection

PROGRAM SCOPE

This was a routine, unannounced inspection of Venture Lighting's license that authorized distribution of krypton-85 filled halide lamps to persons exempt from NRC regulations. The exempt distribution license does not authorize possession of byproduct material. The possession of byproduct material was authorized under the licensee's State of Ohio license. The lamps were manufactured in India and shipped to Venture Lighting's distribution warehouse located in Glenwillow, Ohio. Venture Lighting's main office, where the radiation safety officer (RSO) is located, is in Twinsburg, Ohio. This inspection was conducted at the main office in Twinsburg, and at the distribution center in Glenwillow.

PERFORMANCE OBSERVATIONS

The inspector interviewed the RSO at the main office, toured the distribution center in Twinsburg, and examined packaged and labeled product that had been prepared for distribution. The RSO described how they received product from India, and how he verified that lamps did not exceed the radioactive quantity limit specified on the license. The RSO also explained that he visited the production facility in India two times per year to perform QA/QC and verify production processes.

At the request of the inspector, distribution staff at the Glenwillow location opened a box containing several individual lamps. The inspector noted that the box, individual sleeves that contained a lamp, and the individual lamps were all labeled as containing krypton-85. The inspector performed an independent survey at the surface of a box containing lamps, and at the surface of a single lamp. Radiation levels were indistinguishable from background, i.e., 0.06 - 0.08 millirem per hour.

No violations of NRC requirements were identified during this inspection.