ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

| | 1 | | | | | | | |
|-----------------------|------------------------------------------|-----------------|--------------------|--------------------------------------------|----------------------|----------------|----------------|----|
| ACCESSION FACIL:ST | N NBR:9109160294 IN-50-530 Palo Verd | DOC.I e Nuci | DATE: 9 lear St | 91/08/23 NOTARIZED tation, Unit 3, Ari | : NO zona Pub | DO li 05 | CKET # | |
| BRADISH LEVINE, | T.R. Arizona P J.M. Arizona P | ublic ublic | Servio | ce Co. (formerly Ar ce Co. (formerly Ar | izona Nu izona Nu | clear clear | Power Power | |
| RECIP.1 | NAME RECIPIEN | T AFF. | 1114.1.10 | | · | | | R |
| SUBJECT | : LER 91-005-00:on | 91073: | l,ESF a | actuation occurred. | Caused b | y | | I |
| ~ | monitor failure.C verifying that no | orrect | tive ac rmal ra | ction included unit adiation levels exi | 3 perso sted as | nnel | • | D |
| pd | described in sect | ion I | .B.W/9. | 10823 Itr. | | 0 | | S |
| DISTRIB TITLE: | UTION CODE: IE22T 50.73/50.9 Licensee | COPIES | S RECE t Repor | IVED:LTR ENCL ct (LER), Incident | SIZE:_ Rpt, etc | | | / |
| NOTES:S | tandardized plant. | | • | | | 05 | 000530 | A |
| | DECTDIENU | CODTI | 20 | DECTDIEND | CODIE | c | | D |
| | ID CODE/NAME | LTTR | ENCL | ID CODE/NAME | LTTR E | NCL | | n |
| | PD5 LA | 1 | 1 | PD5 PD | 1 | 1 | | υ |
| | IRADIEDD, C | T | Ŧ | THOMPSON, M | Т | T | | S |
| INTERNAL: | ACNW | 2 | 2 | ACRS | 2 | 2 | | |
| | AEOD/DOA | 1 | 1 | AEOD/DSP/TPAB | l | 1 | | |
| | AEOD/ROAB/DSP | 2 | 2 | NRR/DET/ECMB 9H | 1 | 1 | • | |
| | NRR/DET/EMEB 7E | 1 | 1, | NRR/DLPQ/LHFB10 | 1 | 1 | | |
| | NRR/DLPQ/LPEB10 | 1 | 1 | NRR/DOEA/OEAB | 1 | 1 | | |
| | NRR/DREP/PRPB11 | 2 | 2 | NRR/DST/SELB 8D | 1 | 1 | | |
| | NRR/DST/SICB8H3 | 1 | 1 | NRR/DST/SPLB8D1 | 1 | 1 | | |
| | NRR/DST/SRXB 8E | 1 | 1 | REGEFILE 02 | 1 | 1 | | |
| | RES/DSIR/EIB | 1 | 1 | RGN5 FILE 01 | 1 | 1 | | |
| EXTERNAL: | EG&G BRYCE, J.H | 3 | 3 | L ST LOBBY WARD | 1 | 1 | | |
| | NRC PDR | 1 | 1 | NSIC MURPHY, G.A | 1 | 1 | | R |
| | NSIC POORE, W. | 1 | 1 | NUDOCS FULL TXT | 1 | 1 | - | 1/ |

NOTES:

ĩ

Ęÿ

1 Cat NO PS41576627

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

1

Ι

D

S

Α

D

D

S

A0H

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 35 ENCL 35

• k *x* , 1 · ·

\$

Arizona Public Service Company PALO VERDE NUCLEAR GENERATING STATION P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

JAMES M. LEVINE VICE PRESIDENT 192-00736-JML/TRB/KR August 23, 1991

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Mail Station P1-37 Washington, D.C. 20555

Dear Sirs:

Subject:

Palo Verde Nuclear Generating Station (PVNGS) Unit 3 Docket No. STN 50-530 (License No. NPF-74) Licensee Event Report 91-005-00 File: 91-020-404

Attached please find Licensee Event Report (LER) No. 91-005-00 prepared and submitted pursuant to 10CFR50.73. In accordance with 10CFR50.73(d), we are forwarding a copy of the LER to the Regional Administrator of the Region V office.

If you have any questions, please contact, T. R. Bradish, Compliance Manager at (602) 393-2521.

Very truly yours,

Ville R Sele for

JML/TRB/KR/nk

Attachment

cc:

12

(all with attachment)

W. F. Conway J. B. Martin

D. H. Coe

A. C. Gehr

9109160294 905 ADOCK

A. H. Gutterman

INPO Records Center

(1522 1522

• ¥

\$

| • | | | | | | | | | | | | | | | | |
|--------------------------------------------------------------------------------|------------------------------------------------------------------------------|------------|------------------|---------------------------------------|-------------------|---------------|---------|----------|-----------|-----------------|-------|------------------|---------------|----------------------|------------|----------|
| NRC For | m 366 , | 1 | ال الراخ المنتخذ | | | | | | | | | U.S. NL | CLEA | R REGULAT | ORY CON | MISSION |
| (3-03) | | | | | | | | | | | | | APPR | OVED OMB | NO. 3150- | 0104 |
| | | ı | | | LIC | ENSEE | EVER | IT RE | PÔRT | (LER) | | | EXPI | 4ES: #/31/88 | | |
| | | | | · · · · · · · · · · · · · · · · · · · | | | | | | | | | | | - | |
| FACILITY | Y NAME (| | | | - | | | | | | 000 | CKET NUMBER | (2) | | | GE (3) |
| | - | Pa | <u>lo Ve</u> | erde Unit | 3 | r | | | | | 0 | 5 0 0 | 0 | <u>5]3](</u> |) 1 0 | F 0 6 |
| TITLE (4 | 3 | | . . | _ | | | | | | | | | | | | 1 |
| | | ES | F Act | <u>tuation Du</u> | <u>e to Mo</u> | nitor | Fail | ure | | | | | | | | |
| εv | ENT DATE | (5) | | LER NUMBER (| | REPO | RT DATE | (7) | | OTHE | RFA | CILITIES INVO | LVED | (8) | | |
| MONTH | DAY | YEAR | YEAR | NUMBER | NUMBER | MONTH | DAY | YEAR | | FACILITY N | AMES | - | 000 | | H(S) | |
| | | | | | | | | - | •••• | N/A | | | <u> </u> | 500 | 0 | |
| 017 | 211 | 011 | | | | 0 10 2 | 12 | 011 | | M / A | | | ۰ ۱ | E · O · O | | |
| <u>v 1/</u> | 1211 | 31 | | | | | | 9 1 | 050 S. // | N/ A | | ha fallawiaal (* | | 51010 | | |
| | ERATING ODE (9) | 1 | 20 | 402(6) | | 20 405(4) | | | TY | EA 23(A)(2)((w) | | ne ronowingi (1 | " | 77 71(6) | | |
| POWE | B | 1 | 20 | .405(a)(1)(i) | | 50.38(e)(1) | , | | LÊ L | 50 73(a)(2)(v) | | | Н | 73.71(c) | | |
| LEVE (10) | ² 1 | 0.0 | 20 | .405(a)(1)(ii) | | 50.36(c)(2) | } | | ļ. | 50.73(a)(2)(vii | | | \vdash | OTHER ISC | ecity in A | bitract |
| | | | 20. | .405(a){1}{ili} | | 50,73(+)(2) | 80 | | | 50.73(s)(2)(vii |)(A) | | ⊢ | below and i 366AJ | n Text, Ni | RC Form |
| | | | 20. | .405(a)(1)(iv) | | 50.73(+)(2) |)(#) | | | 60,73(a)(2)(vii |)(8) | | | | | |
| | | | 20, | .405(s)(1){v) | | 50.73(a){2) |)(iii) | | | 50.73(a)(2)(x) | | * | | | | |
| | | | | | L | ICENSEE CO | NTACT P | OR THIS | LER (12) | | | | <u> </u> | | | |
| NAME | | | , | | | | | | • | | | | TELE | PHONE NUM | BER | |
| | | Th | | D Duadia | h C | 7 | M | | | | | AREA CODE | 2 | 0 1 | ~ ~ | |
| | | 110 | Jillas | R. Drauis | n, comp | Trance | rian | ager | | | | | 3 | 9131- | 14 | ין צו יי |
| | | | ÷ | COMPLETE | ONE LINE FOR | EACH COM | PONENT | FAILURE | DESCRIBE | D IN THIS REPO | DAT (| 13) | | r | | |
| CAUSE | SYSTEM | COMPO | DNENT | MANUFAC- TURER | REPORTABLE | | | CAUSE | SYSTEM | COMPONENT | | MANUFAC- | RĘ | PORTABLE | | |
| | | | | | | | | | | | | | - <u> </u> -' | U APRUS | | |
| Х | IL | 1 1 | RII | X 1 91 9 19 | NO | | | | | | | + z - i | | 0 | | |
| | | | | | | | | | | | T | | | | | |
| | | | | | | | | <u> </u> | | | | | | | <u>т</u> | |
| | | | | SUPPLEME | VIAL HEPOHI | EXPECTED | (14) | | | | | EXPECT | D | MONTH | DAY | YEAR |
| YE | 5 (If yes, co | ompiete EX | XPECTED | SUBMISSION DATE | I | | NO | | | | | DATE (1 | 5) | | | , |
| ABSTRAC | CT (Limit t | o 1400 spe | | pproximately fifteen | lingle spece type | written lines | (16) | | | | | , | | | | <u></u> |
| | | | | | | | | • | | | | | | | | |
| | 0n | July | , 31, | 1991, at | approx | imatel | y 09: | 12 MS | T, Pa | lo Verde | e U | nit 3 w | as | in Moo | le 1 | |
| | (P | OWER | OPER | ATION) at | approx | imatel | y 100 |) per | cent | power, v | vhe | n a spu | ric | ous Tra | ain'A | . |
| | Co | ntair | ment | Purge Ise | olation | Actua | tion | Sign | al (C | PIAS) wa | as | initiat | ed | on the | 3 | |
| | Balance of Plant Engineered Safety Features Actuation System. The Train A | | | | | | | | | | | | | | | |
| CPIAS resulted in the designed cross trips of Train B CPIAS and Trains A and B | | | | | | | | | | | | | | | | |
| | Control Room Essential Filtration Actuation Signals (CREFAS). The actuations | | | | | | | | | | | | | | | |
| occurred when the Train A Power Access Purge Area Radiation Monitor (RU-37) | | | | | | | | | | | | | | | | |
| | spiked above its high alarm/trip setpoint. At the time of the event, no | | | | | | | | | | | | | | | |
| containment purge was in progress and the Containment Purge System isolation | | | | | | | | | | | | | | | | |
| valves were closed. All components operated as designed. Control Room and | | | | | | | | | | | | | | | | |
| Radiation Protection personnel verified that normal radiation levels existed | | | | | | | | | | | | | | | | |
| | in the area monitored by RU-37. | | | | | | | | | | | | | | | |
| | Th | e can | ise o | f RU-37 s | oiking a | above | its I | nigh | alarm | /trip se | eto | oint wa | s a | n inf: | antil | e |
| | fa | ilure | of | the monit | or's Ge | iger-M | ulle | r tub | e in | the det | ect | or asse | mb] | Ly. | | |
| | A | previ | lous | similar e | vent wa | s repo | rted | in U | nit 1 | LER 52 | 3/9 | 1-005-0 | 0. | | | |
| | | | | | | - | | | | | | | | | | |
| | | | | | | | | | | | | | | ٠ | | ļ |
| | | | | £ | | | | | | | | | | | | |

NRC Form 366

¢

Â,

.



| LICENSEE | EVENT | REPORT | (LER) | TEXT | CONTINUATION |
|----------|-------|--------|-------|------|--------------|
|----------|-------|--------|-------|------|--------------|

| FACILITY NAME | DOCKET NUMBER | LER NUMBER | PAGE |
|-------------------|-----------------------|---------------------------|-----------|
| | | VEAR SEQUENTIAL WIRER | |
| Palo Verde Unit 3 | 0 5 0 0 0 5 3 | 0 91 1 - 0 10 15 - 010 01 | 2 0F 0 16 |

I. DESCRIPTION OF WHAT OCCURRED:

FACSIMILE

A. Initial Conditions:

On July 31, 1991, at 0912 MST, Palo Verde Unit 3 was in Mode 1 (POWER OPERATION) at approximately 100 percent power.

B. Reportable Event Description (Including Dates and Approximate Times of Major Occurrences):

Event Classification:

An event or condition that resulted in an Engineered Safety Feature (ESF)(JE) actuation.

At approximately 0912 MST, on July 31, 1991, a spurious Train A Containment Purge Isolation Actuation Signal (CPIAS) (VA)(JE) was initiated on the Balance of Plant Engineered Safety Features Actuation System (BOP ESFAS) (JE). The Train A CPIAS resulted in the designed cross trips of Train B CPIAS and Trains A and B Control Room Essential Filtration Actuation Signals (CREFAS) (VI). The actuations occurred when the Train A Power Access Purge Area Radiation Monitor (RU-37) (VA)(IL)(RI) spiked above its high alarm/trip setpoint. At the time of this event, no Containment (NH) purge was in progress and all Containment Purge System isolation valves (VA)(ISV) were closed. All components in the Control Room Essential Filtration System (VI) responded properly to the CREFAS. Control Room personnel (utility, licensed) verified that radiation monitors adjacent to RU-37 were indicating normal radiation levels. Radiation Protection personnel (utility, non-licensed) verified that normal radiation levels existed in the area monitored by RU-37 and in the Plant Vent (VL) exhaust.

The BOP ESFAS actuations resulted in close signals being sent to Trains A and B Containment Purge System isolation valves and resulted in the actuation of Trains A and B Control Room Essential Ventilation System (VI), Trains A and B Essential Chilled Water System (KM), Trains A and B Essential Cooling Water System (BI), and Trains A and B Essential Spray Pond System (BS). All components operated as designed.

The BOP ESFAS actuations were identified by Control Room personnel as a result of main control board annunciations (ANN)(MCBD). There were no operator actions which contributed to the cause of the event. No other ESF actuations occurred and none were required. Unit 3 personnel (utility, licensed and non-licensed) verified that the ESF actuations did not occur as a result of high radiation levels in the Containment Purge System. * .

ş

| FACSIMILE | LICENSEE EVENT REPORT (LER) TEXT CONTINUATION | | | | | |
|---------------|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| FACILITY NAME | | | DOCKET NUMBER | | | |
| | | | | YEAR SEQUENTIAL STARVISION | | |
| | | | | NUMBER | | |
| Palo | Verde | Unit 3 | 0 5 0 0 0 5 3 0 | <u> 9 1 - 0 0 5 - 0 0 0 3 0F 0 6</u> | | |
| | | | • | | | |
| | ÷ - | At approximately 1150 remaining actuated equ normal service. | MST, on July 31, 199 ipment were secured | 91, Train A CPIAS and the , reset and returned to | | |
| | | At approximately 1756 returned to normal ser for troubleshooting an | MST on August 1, 199 vice and Train A CP d maintenance on RU | 91, Train B CPIAS was IAS was placed in bypass -37. | | |
| | с. | Status of structures, at the start of the ev | systems, or componen ent that contributed | nts that were inoperable d to the event: | | |
| | | No structures, systems of the event which con CPIAS had been placed maintenance. | , or components were tributed to this eve in bypass prior to | e inoperable at the start ent. However, Train B this event for unrelated | | |
| | D. | Cause of each componen | t or system failure | , if known: | | |
| | | The ESF actuations des Train A Power Access P above its high alarm/t accordance with an app engineering root cause the cause of RU-37 spi monitor's Geiger-Mulle was a new GM tube that the time of the event. assembly were inspecte loose connections, cor detector assembly inte would have caused the | cribed in Section I urge Area Radiation rip setpoint. Trou roved work authoriz of failure investi king was an infanti r (GM) tube in the had been in servic The detector chan d for physical caus rosion, bent pins). rnals discovered no failure. | .B were caused by the Monitor (RU-37) spiking bleshooting performed in ation document and an gation determined that le failure of the detector assembly. This e approximately 6 days at nel and the detector es of failure (e.g., Inspection of the signs of damage that | | |
| | E. | Failure mode, mechanis known: | m, and effect of ea | ch failed component, if | | |
| - | | The infantile failure assembly resulted in t was above the high ala CPIAS and subsequent a I.B. | of the monitor's GM he output of RU-37 rm/trip setpoint fo ctuation signals as | tube in the detector spiking high. The spike r actuating a Train A described in Section | | |
| | F. | For failures of compon systems or secondary f | ents with multiple unctions that were | functions, list of also affected: | | |
| | | Not applicable – the T Monitor (RU-37) does n | rain A Power Access ot have multiple fu | Purge Area Radiation nctions. | | |

ľ

Q

.

`

.

.

٢

ť

| FACSIMILE | LICENSEE EVENT REPOR | T (LER) TEXT CONTINU | IATION | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| FACILITY NAME | | DOCKET NUMBER | LER NUMBER | |
| * | | | YEAR SEQUENTIAL SPARVISION | PAGE |
| Palo Verde Un | it 3 | 0 5 0 0 0 5 3 0 | 911 - 01015 - 010 | |
| TEXT | | | | |
| | 1 14 | • | | |
| G. | For a failure that re- estimated time elapse train was returned to | ndered a train of a d from the discover service: | safety system inoper y of the failure unti | able, 1 the |
| | Not applicable - the magnetic Area Radiation Monito system inoperable. | malfunction in the ' r (RU-37) did not re | Frain A Power Access ender a train of a sa | Purge fety |
| • | RU-37 was declared in 31, 1991 when the act Following replacement evaluation to ensure returned to service a RU-37 was inoperable occurred while obtain | operable at approximuation was determine of the detector ass that there were no of t approximately 113 approximately 15 day ing necessary composition | mately 0912 MST, on J ed to be spurious. sembly, retest, and other problems, RU-37 7 MST, on August 15, ys and 2 hours. Delay ments. | uly was 1991. ys |
| H | Method of discovery of procedural error: The GM tube failure wa | f each component or as discovered during | system failure or g troubleshooting | • |
| | performed in accordance document and an engine There were no procedur | ce with an approved eering root cause of ral errors identific | work authorization f failure investigati ed. | on. |
| I. | Cause of Event: | | | |
| | The cause of the event in the detector assemb Code E: Component Fail work location (e.g., r this event. The event procedural errors. | t was an infantile f oly as described in lure). No unusual c noise, heat, poor li t was not a result c | failure of RU-37's GM Section I.D (SALP Car characteristics of the ghting) contributed of personnel errors of | tube use e to r |
| J. | Safety System Response | e: | | |
| | The following safety s | system responses occ | curred: | |
| | Containment Purge Is Control Room Essenti Essential Chilled Wa Essential Cooling Wa Essential Spray Pond | solation System (VA) Lal Ventilation Syst ater System (KM), Tr ater System (BI), Tr I System (BS), Train | , Trains A and B, em (VI), Trains A and ains A and B, ains A and B, and as A and B. | ġВ, |
| · . | • | ų | | |

.

V

8

, , 1

· .

-

•

ų

| PACSIMILE LICENSEE EVE | LICENSEE EVENT REPORT (LER) TEXT CONTINUATION | | | | | | |
|------------------------|-----------------------------------------------|---------|---------------------|------------|---------|-----|--|
| FACILITY NAME | DOCKET NUMBER | 1 | LER NUMBER | | PAGE | | |
| | | YEAR \$ | SEQUENTIA NUMBER | L AEVISION | | | |
| Palo Verde Unit 3 | 0 15 10 10 10 15 13 10 | 911- | - 0101 | 5 _ 0 10 | 0 5 OF | 0 6 | |
| TEXT | | | | | | | |

K. Failed Component Information:

The failed component is a Geiger-Mueller tube, Model 713, manufactured by LND, Inc. The tube is purchased from ASI, Inc.

II. ASSESSMENT OF THE SAFETY CONSEQUENCES AND IMPLICATIONS OF THIS EVENT:

Trains A and B Power Access Purge Area Radiation Monitors (RU-37 and RU-38) are located outside Containment near the power access purge exhaust ducts (VA) (DUCT) and the refueling purge exhaust ducts. RU-37 and RU-38 monitor the purge exhaust ducts for airborne radioactivity concentrations that could potentially result in off-site doses exceeding 10CFR100 limits. RU-37 and RU-38 perform the safety function of monitoring purge exhaust and, if necessary, initiating a high dose rate alarm initiation signal to BOP ESFAS. BOP ESFAS performs the safety function of shutting the Containment Purge System isolation valves, activating Control Room Essential Ventilation, and starting necessary support systems (see Section I.J). As discussed in Section I.B, Unit 3 personnel verified that no actual high radiation levels existed. In addition. Containment Purge System isolation valves were shut at the time of the event. All components responding to the ESF actuation signals operated as designed. Therefore, there were no safety consequences or implications resulting from this event.

III. CORRECTIVE ACTION:

g

A. Immediate:

As immediate corrective action, Unit 3 personnel verified that no abnormal radiation levels existed as described in Section I.B. The malfunctioning detector was replaced in accordance with an approved work authorization document.

B. Action to Prevent Recurrence:

PVNGS system engineering personnel (utility, non-licensed) are currently monitoring work by the detector assembly vendor (ASI) and the GM tube manufacturer (LND) to determine if action can be taken to reduce the rate of detector failures in these monitors.

4

,

| FACSIMILE LICENSEE EVENT REPORT (LER) TEXT CONTINUATION | | | | | | |
|---------------------------------------------------------|------------------------|--------------------------------------|--|--|--|--|
| FACILITY NAME | DOCKET NUMBER | LER NUMBER PAGE | | | | |
| | | YEAR SEQUENTIAL WINDER | | | | |
| Palo Verde Unit | 3 0 [5 0 0 0 5 | 3 10 9 11 - 0 0 5 - 0 10 0 16 0 0 16 | | | | |

IV. PREVIOUS SIMILAR EVENTS:

TEXT

A previous similar event was reported in Unit 1 LER 528/91-005-00. The LER discussed an event wherein an infantile failure of a GM tube in the detector assembly caused the radiation monitor to spike above its actuation point causing an ESF actuation. There is no testing or action available which will identify infantile detector failure prior to its occurrence. Therefore, actions taken prior to this event would not be expected to prevent this event.

ş -1 1 . . . 11 Party of 11 4 9 ľ.

×