DISTRIBUTION

ERATED

DEMONSTRATION SYSTEM

w - •

. . . .

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSIO FACIL: 50 AUTH.NA KOBER, R RECIP.I RUSSELL	N NBR:8811290047 D-244 Robert Emmet AME AUTHOR A .W. Rochester NAME RECIPIEN ,W.T. Region 1,	DOC.DA Ginna l FFILIA Gas & T AFFII Ofc of	ATE: Nucle FION Elec LIATI f the	88/09/08 ar Plant, tric Corp ON Director	NOTARIZEI Unit 1, I	D: YES Rocheste	r G SEG RP-L	DOCKET # 05000244	
SUBJECT	Responds to NRC E nuclear power pla	Bulletin Ints.	າ 87-	001 re th	inning of	pipe wa	ils :	in ;	R
DISTRIBUTITLE:	UTION CODE: IE11D Bulletin Response (COPIES	RECE	IVED:LTR	/ ENCL /	_ SIZE:	1	<u>S</u>	I
NOTES:L	icense Exp date in	accorda	ance	with 10CF	R2,2.109(9	9/19/72)	•	05000244	D
				-					S
	RECIPIENT	COPIES	5	RECI	PIENT	COPI	ES		,
	ID CODE/NAME	LTTR I	ENCL	` ID CO	DE/NAME	LTTR	ENCL		/
•	PD1-3 LA	1	0	PD1-3 P	D	1	1	x	
	STAHLE, C	1	1						A
TNTERNAT.		7	1	AFOD/DS	Ρ/Ͳ ΡλΒ	1	1		n
	NRR ALEXTON.T	า	ī	NRR/DES	T/ADE 8H	ī	ī		υ
	NRR/DEST/ADS 7E	า	ī	NRR/DES	T/MEB 9H	ī	ī		~
	NRR/DOEA/EAB 11	ī	ī	NRR/DOE	A/GCB 11	ī	ī	l	D
	NRR/DREP/EPB 10	ī	ī	NRR/PMA	S/ILRB12	1	1	•	~
	NUDOCS-ABSTRACT	ī	ī	REG FIL	E 02	1	1	i	S
•	RES/DSIR/EIB	ī	1	RGN1	FTLÉ 01	1	l		,
	,, ,, ,, ,								

NRC PDR .

EXTERNAL: LPDR NSIC

A 0-

1

1

R

I

D S

D

D

Ŝ٢

141.

B

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 19

1 1 1

1





15

ROCHESTER GAS AND ELECTRIC CORPORATION . 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

TELEPHONE AREA CODE 716 546-2700

September 8, 1987

Mr. William T. Russell Regional Administrator U.S. Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, PA 19406

> Subject: Nuclear Regulator Commission Bulletin 87-01 R.E. Ginna Nuclear Power Plant Docket No. 50-244

Dear Mr. Russell:

NRC Bulletin $87 \div 01$ requested information concerning thinning of pipe walls in nuclear power plants. Our responses to the bulletin are attached.

Very truly yours,

Ϋ÷-

for

Subscribed and sworn to me on this <u>8th</u> day of <u>September</u> 1987

LYNN I. HAUCK Notary Public in the State of New York MONROE COUNTY Commission Expires Nov. 30, 19.......

xc: USNRC Document Control Desk
 Desk (Original)

T. Polich, Ginna Resident Inspector

8811290047 880908 PDR ADOCK 05000244 Q PDC

Response to NRC IE Bulletin 87-01

1. Question:

Identify the codes or standards to which the piping was designed and fabricated.

Response:

All safety related and non-safety related piping systems were originally designed and fabricated to the requirements of USAS B31.1 Power Piping Code. Since the original construction, repairs and/or modifications have been made which have been designed and fabricated to later codes, including ASME Section III. Reanalysis of critical safety related piping 2½" and larger was performed under the Seismic Upgrade Program which was reviewed by the NRC under SEP Topic III-6. This program updated the piping analysis basis to criteria consistent with the ANSI 31.1 Code, including Summer 1973 addenda, with some amendments. This code edition remains as the current analysis basis for modifications performed on safety related piping. Non-safety related piping is designed and fabricated in accordance with the appropriate current edition of ANSI B31.1.

2. Question:

Describe the scope and extent of your programs for ensuring that pipe wall thicknesses are not reduced below the minimum allowable thickness. Include in the description the criteria that you have established for:

a. selecting points at which to make thickness measurements
b. determining how frequently to make thickness measurements
c. selecting the methods used to make thickness measurements

d. making replacement/repair decisions

Response:

Although one facet of the pipe wall thickness inspection has been ongoing for more than 10 years, the major portions of the Ginna inspection program have been put into place over the past five years. The various facets of the program were developed in response to either maintenance concerns at the Ginna plant or industry concerns associated with pipe wall thickness degradation. Piping inspections have been performed in areas previously identified as potential problem areas, in areas which had become suspect from inspections or events at other plants, and in areas identified via regulatory information. Information sources used as references were: NRC Bulletins and IE Information Notices, INPO Significant Event Reports or Significant Operating Experience Reports, and industry meetings and contacts.

8811290047

-

,

,

.

.

1 a

In the determination of inspection scopes, no attempt was made to selectively inspect isolated fittings. If an area of concern was identified, pipe and fittings subject to that concern were inspected. This methodology included duplicate trains and downstream piping subject to the same operating parameters. One exception to this approach occurred while performing post Surry event inspections in December 1986. In order to provide the earliest possible information, these inspections were performed while the piping was hot. Due to the difficulty in performing "hot" inspections, the examination locations were selectively determined by using engineering judgement while assuring that the most likely areas of wall thinning were included.

For the '87 outage, the scope of systems to be inspected was expanded to cover the majority of the high energy, carbon steel piping systems (including but not limited to FW Heater & MSR Drains, Main Steam and Steam Generator Blowdown). Since the intent of the '87 outage inspection program was to sample as many of these additional systems as practical, engineering judgement was used in selecting a manageable number of components for inspection. For the December '86 and the '87 outage inspections, the dominant criteria for selection of inspection locations was the piping geometry. Based on experience at Ginna and in the industry, closely coupled fittings (such as combinations of tees, elbows, reducers, and fittings downstream of control valves) were considered to be the most likely place for erosion/corrosion to take place.

The frequency of inspections was determined by analysis of the results of data from previous outages. If inspection locations had yielded indications of significant wear, an engineering evaluation was performed to provide a basis for repair/replacement or an increased surveillance at the next scheduled outage.

Except for the turbine steam crossunder piping, which had been visually examined during a crawl-through, wall thickness measurements were made by UT examinations using current industry-accepted techniques at the time of examination.

Repair or replacement decisions prior to the '87 outage were based on an evaluation of the inspection results. For the '87 outage, a Nonconformance Report (NCR) was written for all components which experienced a greater than 30% reduction from nominal wall thickness. The NCR's were formally dispositioned with replacement/repair and further inspection decisions based on the required minimum wall thickness. Disposition of NCR's considered the piping configuration, extent of thinning, individual component service life, importance to safety and any other relevant conditions. If repair was not required, the next required inspection period was specified.



r u

•

•

,

a

• • •

·



3. <u>Question</u>:

For liquid-phase systems, state specifically whether the following factors have been considered in establishing your criteria for selecting points at which to monitor piping thickness (Item 2a):

- a. piping material (e.g., chromium content)
- b. piping configuration (e.g., fittings less than 10 pipe diameters apart)
- c. pH of water in the system (e.g., pH less than 10)
- d. system temperature (e.g., between 190 and 500°F)
- e. fluid bulk velocity (e.g., greater than 10 ft/s)
- f. oxygen content in the system (e.g., oxygen content less than 50 ppb)

Response:

Prior to the inspections influenced by the Surry pipe failure, the criteria for selection of locations for the wall thickness measurements for liquid-phase systems was the same as that described in Item 2 above. For the inspections performed in December 1986 in response to the Surry incident, an inspection point selection criteria for liquid-phase flow systems was used that accounted for the previous Ginna Station experience and for some of the industry recognized factors affecting erosion/ corrosion. The major factor considered was the piping configuration. From previous Ginna Station and other utility inspection results, tees, elbows, reducers and components downstream of control valves had the highest incidence of degradation. Locations with closely coupled combinations of these fittings were considered to have a greater potential for erosion/corrosion than those fittings having greater than ten diameters of straight pipe between Other considerations which led to selection of them. inspection points were system temperature and fluid bulk velocity.

Inspection points were also chosen which represented a configuration similar to that at Surry or were at a similar point in the system. In addition, the December 1986 inspections included portions of systems with temperatures similar to those at Surry. Since there was limited use of alloy piping materials in the original design of Ginna piping systems, piping material was not a major consideration in the inspection point selection criteria. Based on industry experience and the limited variation of the parameters within the suspect Ginna systems, pH and 0, content in the system were not given major consideration in selecting inspection points.

These same liquid-phase selection criteria were used to determine the locations for the expanded scope of systems inspected during the !87 refueling outage.

•

ti.

•

9

.

4. <u>Question</u>:

Chronologically list and summarize the results of all inspections that have been performed, which were specifically conducted for the purpose of identifying pipe wall thinning, whether or not pipe wall thinning was discovered, and any other inspections where pipe wall thinning was discovered even though that was not the purpose of that inspection.

- a. Briefly describe the inspection program and indicate whether it was specifically intended to measure wall thickness or whether wall thickness measurements were an incidental determination.
- b. Describe what piping was examined and how (e.g., describe the inspection instrument(s), test method, reference thickness, locations examined, means for locating measurement point(s) in subsequent inspections).
- c. Report thickness measurement results and note those that were identified as unacceptable and why.
- d. Describe actions already taken or planned for piping that has been found to have a nonconforming wall thickness. If you have performed a failure analysis, include the results of that analysis. Indicate whether the actions involve repair or replacement, including any change of materials.

Response:

- a. Rochester Gas and Electric's inspection program is designed to determine wall loss of carbon steel piping and components. The programmatic effort began in 1983 to specifically take baseline measurements on the preseparator system. This effort has since expanded as described below. Inspection areas have been determined as described in the response to Question #2. Since the program to date has been "concern" oriented, the following describes the inspection program for the individual areas of interest.
 - (1) Routine Refueling Outage Inspection of the Turbine Crossunder Piping Between the High Pressure Turbine Sections and the Moisture Separator Reheaters.

This inspection has been a routine maintenance item for approximately the last ten refueling outages. This inspection consists of plant maintenance crews visually examining the pipe interior by crawling through the large diameter piping. The crossover piping has not had any evidence of pipe wall thickness reduction. However, the crossunder piping has had multiple areas of wall thickness degradation



.

٩

v .

. .

and has been repaired. The procedure for repair consists of marking the areas where wall reduction was clearly evident (gouges, ripples, or depressions) and then making weld repair to bring the reduced areas back to the original wall thickness. No wall thickness measurements were taken during this routine maintenance.

Because of concern provided by a steam leak which developed in one of the expansion joints of a crossunder line, the areas of the pipe that are welded to the expansion diaphragm hinges were UT examined during the '87 refueling outage. The area of the leak was located, cut out, and replaced. То determine the extent of the problem, UT inspections were performed in similar locations on two of the other crossunder lines. These inspections found them to be in good condition. The leak was caused by corrosion resulting from poor geometry under the reinforcement pad and not due to general erosion/ corrosion wear. This area of the joint is not visible during an ID inspection.

The preseparator system was installed in '83 to reduce the moisture content in the crossunders. A 70% removal effectiveness was determined through testing. Subsequent inspections indicate a reduced wear rate.

(2) Turbine Extraction Steam Piping

The extraction steam piping from the high pressure turbine to the feedwater heaters no. 4 and no. 5 was UT examined during the 1983 outage in response to the IE Information Notice 82-22 on the Oconee high pressure turbine exhaust line failure. Excessive wall reduction was found in some elbows, and they were replaced. Based on inspection results, components which had indications of significant wear were re-examined in the subsequent '84, '85, '86 & '87 refueling outages and additional elbows and piping were replaced in the '86 outage. In the '86 refueling outage, the inspection area was expanded to include the extraction steam downcomers from the low pressure turbine in the condenser neck. No unusual wear was observed at that time.

(3) Feedwater Pump Recirculation Piping

The feedwater pump recirculation line to the condenser downstream of the flow control valves has experienced excessive vibration due to suspected flashing. This piping was UT examined during the '86 refueling outage as part of the planned maintenance on the flow control valves and associated piping. Portions

- 5

•

.

· •

× .

• ۲

.

of the piping were found to have excessive wall reduction and were replaced. Portions of the piping were re-examined in the subsequent '87 refueling outage. In the '87 outage a new feedwater pump recirculation/bypass piping arrangement was installed that reduces to acceptable levels the service on the old recirculation control valves to the condenser. This feedwater pump recirculation/ bypass line was given a baseline thickness examination during the outage.

(4) Turbine Moisture Separator - Reheater 2nd Pass Drains to Feedwater Heater No. 5

A forced outage occurred in '86 due to the failure of an elbow downstream of the control valve in the drain line from the 2A MSR to the 5B feedwater heater (Ref. LER 86-004). Informal UT readings were taken in other portions of the same line and in similar portions of the duplicate trains which confirmed that this was an isolated situation; it should be noted that the elbow that failed had a significantly shorter length of pipe between it and the upstream control valve than all of the other lines. The failed elbow was replaced with a higher schedule of a chrome alloy material. In the subsequent '87 refueling outage the piping was re-examined and the control valve was relocated further upstream from the elbow. At the same time, the piping downstream of the control valves in the alternate dump lines to the condenser was examined, found to have excessive wall reduction, and was replaced.

(5) Feedwater Pump Suction Piping

In response to the Surry pipe failure in the feedwater pump suction piping, UT examinations were taken in December '86 in geometrically similar portions of the Ginna feedwater piping and in portions of the feedwater heater drain system while the plant was at full power operating temperatures. All of the measurements indicated that the wall thicknesses were greater than 90% of the nominal wall thickness.

(6) 1987 Outage Program Expansion

For the 1987 refueling outage, the piping inspections were expanded in response to the concerns identified regarding the Surry feedwater line break (IEN 86-106). The 299 components selected for UT examination were a combination of those requiring re-examination based on the results of previous inspections and of those systems, especially single phase liquid systems, that had not been suspected of wall

· ·

*

•

`

11

•

٠

thinning problems prior to the Surry pipe failure. This scope included piping in the Steam Generator Blowdown System, the remainder of the FW Heater Drains and the Moisture Separator-Reheater Drains, including the alternate dump to the condenser. The Main Steam system was added to the scope to include the remaining high energy carbon steel piping system. The Auxiliary Feedwater discharge lines were included because of their critical plant function and moderately severe operating conditions. As a result of the inspections, portions of the , Steam Generator Blowdown piping to the blowdown heat exchanger were replaced, along with portions of the Moisture Separator-Reheater drains alternate dump to the condenser. Many components inspected during 1987 have been selected for reinspection during the 1988 outage to trend the erosion/corrosion rate.

b. The piping which was examined is described in "a" above. The method of performing the examinations is as follows.

The first step in the examination process is the removal of insulation, scale and any other materials that might interfere with the transmission of ultrasound. Next, the entire component (elbow, tee, pipe, or reducer) is laid out in grid fashion. Around the circumference of a given component, numbered rings are generated, and along the longitudinal axis lettered columns are generated. The grid size is determined according to the component's diameter. For components equal to or less than 6" in diameter, grid sizes are 1 inch; greater than 6" and less than 12" in diameter, grids are 2 inch; and greater than 12" in diameter, grids are 3 inch. The first ring begins from the centerline of the upstream weld, and its distance from the weld is the same distance as the grid size. For example, if the component has a grid size of 2 inches, the first ring would begin 2 inches downstream from the centerline of the upstream weld. The first data column follows the same rules for the reference location of a weld, typically the outside radius of an elbow, or, top center of a component. When two components are adjacent to each other, such as an elbow and a pipe (both components to be examined), the columns of the upstream component are extrapolated to the downstream component. In the case of a tee, the grids are laid out the same as for a pipe, with some variation. The rings begin on the run of a tee, leaving out the points where the bull (branch) comes out. As the last ring is marked on the run, the next ring is marked on the bull. When there is a change in flow direction or line size, the downstream component at which the flow change occurs will be examined for a distance of 12 inches. The 12 inch distance may alternately be defined in terms of a

7 -

.

• -

r

`

given number of component diameters. For a representation of the component layout, refer to the drawings that follow the inspection data in Attachment 1.

After the component grid patterns have been laid out, the intersections of the grids are marked with a paint marker in order to provide locations for current and subsequent examinations. However, due to system temperatures and external surface conditions, the paint marks may not be visible for subsequent examinations. Consequently, a consistent method of component layout pattern is maintained and documented for each component. The following items are included in the component layout documentation: grid size, distance of the first ring from the upstream weld and direction the columns are lettered (clockwise or counterclockwise) in reference to flow in the component.

Once a component has been laid out, thickness readings are taken. The instruments used are the SONIC MARK I and the DMX-1. Transducers with frequencies ranging from 2.25 to 10.0 MHz and with diameters from .25" to .5" are used. The selection of the transducer is determined by the nominal wall and the component's geometry. Calibration is performed for a thickness greater than the nominal thickness expected for a given component. Nominal wall is determined from line specifications and/or previous history of the component.

Thickness readings of the component are then taken by a certified NDE technician, who either dictates the measured data to another technician, or he utilizes a data logger. The data logger can be connected to either the SONIC or the DMX-1. This device stores the thickness readings of one or more components, and the data is later downloaded into a computer.

The next step is the data entry into the computer. When the data is recorded manually the data has to be entered manually, but when the data is recorded via the data logger, then it is entered through a serial interface. Each component has a unique number assigned to it and is referred to as a summary number. This number becomes the file name of the data entered into the computer. Grid profile information, type of component, pipe wall schedule and diameter are entered along with the transducer data.

With this information entered the file is compiled and spread sheets and color plots are generated. The color plot is used as a quick reference tool to locate a potential area of concern for a given component. The colors represent different percentages of the nominal wall remaining. The spread sheet is used for exact





.

.

•

.

thickness readings for specific grid locations. (Refer to the sample plot and spread sheet that are attached as Attachment 2)

- c. Thickness measurement results are reported chronologically in Attachment 1.
- d. Actions taken based on thickness measurement results are described in Attachment 1. The "Remarks" column will indicate next to a specific component if it was repaired, replaced or scheduled for further inspection.

5. Question:

Describe any plans either for revising the present or for developing new or additional programs for monitoring pipe wall thickness.

Response:

A significant level of pipe wall thickness inspections have already been made in both single and two phase flow systems as part of the existing Ginna Station program. To date, 501 component UT examinations have been performed, and the results have been recorded and appropriate actions taken. The turbine crossunder piping has been routinely visually examined and repaired as necessary. Beginning with the '87 refueling outage, the procedure for dispositioning nonconforming wall thickness measurements has been more closely controlled by processing a Non-Conformance Report using the plant QA program. The results from previous outages are being entered into the Ginna Station Maintenance In-Service Inspection Program data base system to facilitate identifying, tracking, and scheduling of future inspections.

The existing inspection program will be formalized further for both single and two phase flow systems consistent with the general guidelines of the NUMARC Working Group on Piping Erosion/Corrosion Summary Report dated June 11, 1987. Inspection sample size, inspection methods, acceptance guidelines, and program follow up represent the key areas of the recommended program. The scope of the present program's inspection points will be reviewed and evaluated. Consideration will be given to the need for expanding the number of inspection points and the selection of additional inspection points, if necessary, for single phase flow systems. An analytical computer model recognized by the utility industry will be utilized as a tool for evaluation of the suggested fittings, suggested piping locations, and key parameters identified in the NUMARC summary report (tabulated and included in Attachment 3).

For two phase flow systems, the appropriate portions of the single phase evaluation, previous Ginna Station experience,







·

>

'

,

.

,

and other utility industry recognized evaluation methods will be used. Included in this evaluation will be the determination of the schedule for the completion of the inspections for any additional points and reinspection of the existing points.

.

.

.

Attachment 1

to

NRC IE Bulletin 87-01 Response

(Item 4)

I.

.

,



THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING THE 1983 OUTAGE AT GINNA

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P. HEATER

- A. 4 ELBOWS
- B. 2 PIPE SECTIONS
- C. 1 TEE

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P. HEATER

- A. 3 ELBOWS
- B. 2 PIPE SECTIONS
- C. T TEE

STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

· · ·

- A. 6 ELBOWS
- B. 2 TEES

TOTAL COMPONENTS

NOTE: AS PART OF THE ACCEPTANCE OF COMPONENTS BEING USED FOR A NEW PRESEPARATOR SYSTEM, 40 ADDITIONAL COMPONENTS WERE INSPECTED. ALL INSTALLED COMPONENTS MET ALLOWABLE STANDANDS, HOWEVER, NO ATTEMPT WAS MADE TO TRACK SPECIFIC INSPECTION POINTS IN THE RECEIPT INSPECTION TO SPECIFIC LOCATIONS IN THE FINAL INSTALLED MODIFICATION.



.

4 ٠

•

,

*



RESULTS OF THICKNESS READINGS AT GINNA DURING 1983 OUTAGE

1. . . .

90 - 85% NOMINAL WALL THICKNESS

1 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H. 3 STEAM EXTRACTION TO 5A & 5B H.P.H.

80 - 70% NOMINAL WALL THICKNESS

1	STEAM	EXTRACTION	ΤO	PRESEPARATOR	В	8	4B	L.P.H.
2	STEAM	EXTRACTION	ТО	PRESEPARATOR	Α	&	4A	L.P.H.
° 1	STEAM	EXTRACTION	то	5A & 5B H.P.F	1.			

< 70% NOMINAL WALL THICKNESS

4	STEAM	EXTRACTION	ТО	PRESEPARATOR B & 4B L.P.H
2	STEAM	EXTRACTION	тο	PRESEPARATOR A & 4A L.P.H
2	STEAM	EXTRACTION	то	5A & 5B H.P.H.



• `**.** A a . • • ¥. • . 6

.



1983 OUTAGE THICKNESS READINGS AT GINNA STATION

,

• • • • •

			4			*				
STEAM EX	TRACTION	TO PRESEPAR	ATOR B	AND 4B	L.P.HEATER	DRAWING	6 M-21			
RG&E	ID NO.	COMPONENT	PERCE	NTAGE	. •.	REMARKS	SUMMAR	Y PER		
NUMBER	DRAWING	N F3 L	тніскі	NESS						
301015	1AD ·	F	90-85	46		-				
301025	2AD	P,	>90							
301350	33	τ·	70-65	.580						
301370	35	E ,	80-70							
301390	37	E	<65	.220						
301410	38	E	<65	.220						
301430	40	Ë.	70-65	.260			-	•		
STEAM EX	STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P.HEATER DRAWING M-22									
RG&E	ID NO. OF NOMIN	COMPONENT	PERCE	NTAGE		REMARKS	5 SUMMAR	Y PER		
() KER	DRAWING		THICK	NESS			,			
301705	1B.	P	>90							
301715	2B	P	>90				-			
302070	33	Т	80-70							
302090	35	E	80-70	4						
302130	38	Ē	< 65	- 200	REPLACED	PRIOR TO	END OF	JUTAGE		
302140	39	P '			REPLACED		END OF	DUTAGE		
302150	40	-	< 45	- 210	REPLACED					
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	- 1 <del></del>	Resp.			أستعاليا اعتا اعتازه		1000 i 7 6-7 i 1007 i 1			

- * STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

.

_____

••

DRAWING M-75

REMARKS	SUMMARY	PER
· • .		k

+

v

*

. .

RG&E	ID NO.	COMPONENT	PERCENTAGE
TYPE	OF NOMIN	AL	1
NUMBER	DRAWING		THICKNESS
	•		
303090	9	т	70-85
303110	11	E	>90
303130	13	E .	70-65 .260
303140	14	E	80-70
303230	23	Т	>90
303240	24	Ē	90-85
303260	26	E	90-85
717280	28	E	<65 .240
		t	



. .

.

.

à



## THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING THE 1984 OUTAGE AT GINNA

and the second sec

الم المحصورة المحمد في وحدا معالي المحكم من المحكم من المحمد الم

.......

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P. HEATER

- A. 19 ELBOWS
- B. 2 PIPE SECTIONS
- C. 2 TEES

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P. HEATER

- A. 14 ELBOWS
- B. 2 PIPE SECTIONS
- C. 2 TEES

### STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

. ^

- A. 5 ELBOWS
- B. 1 TEES

47 TOTAL COMPONENTS

. .

x

•

•



## RESULTS OF THICKNESS READINGS AT GINNA DURING 1984 OUTAGE

90 - 85% NOMINAL WALL THICKNESS

3	STEAM	EXTRACTION	тο	PRESEPARATOR B 8	<b>(</b> 4)	B L.P.H.	ت ور			•	4	•
5	STEAM	EXTRACTION	тΟ	PRESEPARATOR A 8	· 41	A L'P.H.	and a state of the second s	*	•	-		4
2	STEAM	EXTRACTION	тο	5A & 5B H.P.H.			•			-		

۲

्रा के िंग क्षम्राज्ञ ⊥ं ६२ ३६ र

### 85 - 80% NOMINAL WALL THICKNESS

STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.
STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H.
STEAM EXTRACTION TO 5A & 5B H.P.H.

### 80 - 70% NOMINAL WALL THICKNESS

4 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.

- 2 STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H.
- 3 STEAM EXTRACTION TO 5A & 5B H.P.H.

0% NOMINAL WALL THICKNESS

2 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.

1 STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H.



•

.

•

,



# 1984 DUTAGE THICKNESS READINGS AT GINNA STATION

* . * . . .

.

л.

یہ ک**ا ہ**ے ہے۔

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P.HEATER DRAWING M-21

.

RG&E SUMMARY	ID NO. PER	COMPONENT TYPE	PERCENTAGE OF NOMINAL	REMARKS
NUMBER	DRAWING		THICKNESS	
301015	1A	P	85-80	
301020	2	E	>90	
301025	2A	P	85-80	
301030	3	Ε	80-70	
301050	5	E	>90	
301070	7 ·	E	>90	
301120	11	E	90-85	
301130	12	E	90-85	
301160	15	E	>90	
3 <u>0</u> 1180	17	Ε	>90	
230	21	E	90-85	
m 260	24	E	>90	
301280	26	Ε	>90	
301300	28	E	>90	
301320	30	Т	85-80 '	
301350	33	Т	80-70	, · · · · · · · · · · · · · · · · · · ·
301370	35	E	80-70	
301390	37	E	<65 .222	
301410	38	E	<65227	
301430	40	E	80-70	
301470	44	E	>90	
301490	46	E	>90	
301510	48	E	85-80	

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P.HEATER DRAWING M-22

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	· REMARKS
301705	1B	Р., .	>90	
301715	2B	P	90-85	
301720	3	E	>9Ó	
301740	5	E	>90	
760	7	E'.	90-85	
780	9	E	70-85	
1800	11	E	>90	
301850	15	Ε	>90	
301900	19	E	>90	


					+				
AM	EXTRACTION	то	PRESEPARATOR	A	AND	<b>4</b> A	L_P_HEATER	DRAWING M-22	CONT.

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
301920	21 26	E	>90 90-85	
302030	30	E	>90	
302050	32	E	>90	на, чт _{ор}
302070	33	Т	70-65 .450	
302090	35	E	80-70	
302110	37	Т	80-70	
302130	38 '	E	90-85	r
302150	40	E	85-80	

# STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
3 <u>0</u> 3090	9	т	80-70
110	11	E	90-85
U 130	13	E	90-85
303140	14	E	80-70
303260	26	E '	80-70
303280	28	E	85-80

# DRAWING -H-75

# REMARKS

...

. .

.

ι

.

.

.

, , ,

.

.

·

. .



THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING THE 1985 OUTAGE AT GINNA

.

÷, ,4

. .

يە بەر بى

and the state of a second

en The Briter

.

the state

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P. HEATER

- A. 4 ELBOWS
- B. 2 PIPE SECTIONS

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P. HEATER

4. 4 ELBOWS

B. 2 PIPE SECTIONS

STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

A. 4 ELBOWS

16 TOTAL COMPONENTS



× . ι. 7

3

۲

-

J



.,

# RESULTS OF THICKNESS READINGS AT GINNA DURING 1985 OUTAGE

. .

. . .

10.00

90	- 85% NOMINAL WALL	THICKNESS
2	STEAM EXTRACTION	TD PRESEPARATOR A & 4A L.P.H.
⁻ 85	- 80% NOMINAL WALL	THICKNESS
1 1	STEAM EXTRACTION STEAM EXTRACTION	TO PRESEPARATOR A & 4A L.P.H. TO 5A & 5B H.P.H.
80	- 70% NOMINAL WALL	THICKNESS
1	STEAM EXTRACTION	TO PRESEPARATOR B & 4B L.P.H.

2 STEAM EXTRACTION TO 5A & 5B H.P.H.

< 70% NOMINAL WALL THICKNESS



.

STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H. STEAM EXTRACTION TO 5A & 5B H.P.H.



`

х



_

# 1985 OUTAGE THICKNESS READINGS AT GINNA STATION

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P.HEATER DRAWING M-21

ы х , **е** 

ъ

-

.

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
301015	1A 7	P	80-70	·
301025	2 2A	P	85-80	
301390	37	E	<65 .225	
301430	40	E	<65 .236	
301440.	41	Ρ	>90	

# STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P.HEATER DRAWING M-22

NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
301705	1B	Р	85-80 [´]	
301715	2B	P	>90	
301720	3	Ε	>90	
301900	19	E	>90	
302130	38	E	90-85	
302150	40	E	90-85	

# STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

# DRAWING M-75

and the second sec

and the second sec

1 20 10 1 1 1 1 1 1 1

-

RG&E	ID ND.	COMPONENT	PERCENTAGE	REMARKS
SUMMARY	PER	TYPE	OF NOMINAL	•
NUMBER	DRAWING		THICKNESS	- · ·
303130	13	Ε	80-70	•
303140	14	E	80-70	
303260	26	Ε.	85-80	
303280	28	Е	<65 .238	



ı.

. x

•

1

,



# THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING THE 1986 DUTAGE AT GINNA

ињ, 15**83** Д

المجم المحال المعلق التمييم المسال الما المثل

FEEDWATER BYPASS TO CONDENSER (CV-18)

- A. 7 ELBOWS
- B. 2 REDUCERS
- C. 8 PIPE SECTIONS

#### FEEDWATER BYPASS TO CONDENSER (CV-19)

- A. 4 ELBOWS
- B. 2 REDUCERS
- C. 4 PIPE SECTIONS

# STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P. HEATER

- A. 6 ELBOWS
- B. 4 PIPE SECTIONS
- C. 1 TEE

A. 2 ELBOWS

STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

A. 3 ELBOWS

- B. 2 PIPE SECTION
- C. 1 TEE

LOW PRESSURE DOWN COMERS

A. 7 PIPE SECTIONS

53 TOTAL COMPONENTS



• •

¢

.

.





# RESULTS OF THICKNESS READINGS AT GINNA DURING 1986 OUTAGE

# 90 - 85% NOMINAL WALL THICKNESS

- 1 FEEDWATER RECIRC CV-18
- 1 FEEDWATER RECIRC CV-19
- 3 LOW PRESSURE DOWNCOMER

#### 85 - 80% NOMINAL WALL THICKNESS

- 2 FEEDWATER RECIRC CV-18
- 1 FEEDWATER RECIRC CV-19
- 1 STEAM EXTRACTION TO 5A & 5B H.P.H.
- 1 LOW PRESSURE DOWNCOMER

# 80 - 70% NOMINAL WALL THICKNESS



FEEDWATER RECIRC CV-18 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H. STEAM EXTRACTION TO 5A & 5B H.P.H. LOW PRESSURE DOWNCOMER

# < 70% NOMINAL WALL THICKNESS

6 FEEDWATER RECIRC CV-18

- 5 FEEDWATER RECIRC CV-19
- 1 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.
- 1 STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H.
- 2 STEAM EXTRACTION TO 5A & 5B H.P.H.
- 2 LOW PRESSURE DOWNCOMER

**K** 4

a



# 1986 OUTAGE THICKNESS READINGS AT GINNA STATION

FEED WAT	ER BYPASS	TO CONDENSI	ER (OL	D CV-1	B) ····································	WING (	CV-18	3,
RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCEN OF NON THICKN	NTAGE 1INAL NESS	, •	REM	ARKS	· , ,
300300 300310	29 30	R P	<65 <65	.212 .214	REPLACED REPLACED	END O END O	F 86 F 86	OUTAGE OUTAGE
300320 300330 300340	31 32 33	E P F	<65 <65 <65	.273 .186	REPLACED REPLACED	END O	F 86 F 86 F 86	
300350 300360	34 35	E P	80-70 85-80	.200	REPLACED REPLACED	END D END D	F 86 F 86	OUTAGE
300370 300380 300380	36 37 39	E P E	85-80 >90			END O	F 86 F 86	
300370 300400 10 410	38 39 40	· P E	90-95 80-70		REFLACED		- 80	OUTHOE
420	41 42	PE	80-70 >90	201				
300440 300450 300460	43 44 45	r R P	>90-65 >90 80-70	• 271			*	

\$P

FEED WATER BYPASS TO CONDENSER (OLD CV-19) DRAWING CV-19

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCEN OF NOM THICKN	TAGE INAL ESS		RE	emaf	RKS	·
300550	9	E	85-80				-		÷
300790	33	R	<65	.062	REPLACED	END	OF	86	OUTAGE
300800	34	E	<65	.088	REPLACED	END	OF	86	OUTAGE
300810	35	Ρ.	<65	.243	REPLACED	END	OF	86	OUTAGE
300820	36	E	90-85		REPLACED	END	OF	86	OUTAGE
300830	37	Р	>90		REPLACED	END	OF	86	OUTAGE
300840	38	E	70-65	.284					
300850	39	P.	70-65	.284					
300860	40	R	>90						
300870	41	P	>90	-					



۰

,

•

.

**y**,

AM EXTRACTION TO PRESEPARATOR B AND 4B L.P.HEATER DRAWING M-21

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
301020	2	F	200	
301160	15	E	>90	ر کو موجود به همه ۲۰۰۰ بوده و مربو موجود ر کو موجود به همه ۲۰۰۰ بوده و مربو موجود
301350	33	Ť,	80-70	
301370	35	E	70-65 .260	· · · · · · · · · · · · · · · · · · ·
301380	36	Р	>90	•
301390	37	E	<b>&gt;90</b> .	*, BASELINE
301400	37A	P	, >90	* , BASELINE
301410	38	E	>90	*, BASELINE
301420	39	P	>90	* , BASELINE
301430	40	E	>90	* , BASELINE
301440	41	P	>90	-

* THESE COMPONENTS WERE REPLACED AT THE BEGINNING OF THE 1986 OUTAGE

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P.HEATER DRAWING M-22

D HE MARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	. REMARK	<s< th=""></s<>
301720 301900	3 19	Ē	>90 >90	•	

# STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
303090	9	T	70-65 .380
303130	13	E	<65 .240
303140	14	F	80-70
303150	15	P	85-80
303280	28	E	<65 .239
303290	29	P	>90

DRAWING M-75

REMARKS

• . • , , .



# PRESSURE DOWN COMER

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
DC1A86	A	P	90-85 /
DC1B86	В	P	85-80
DC1C86	С	P	80-70
DC1D86	D	P	90-85
DC1E86	E	Р	90-85
DC1F86	F	P	<65 .224
DC1686	G	P	<65 .131

REMARKS

н (

. .

,

•

e

• • • •



, s.

, 

•



# THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING DECEMBER 1986 AT GINNA

. .

a 1. - M

ili. The second s

1999 (P. 1997)

_

อเรื่องมีสสรีคุณที่สางหมา เสียงที่ เป็น เรา เกิน

a Same Market of

# HEATERS 4A & 4B TO FEEDWATER SUCTION

- A. 2 ELBOWS
- B. 3 PIPE SECTIONS
- C. 2 TEES

# FEEDWATER SUCTION TO PUMPS A & B

A. 4 ELBOWS

B. 7 PIPE SECTOINS

# 5A H.P.H. DRAIN TO 4A L.P.H.

A. 3 TEES

# 58 H.P.H. DRAIN TO 48 L.P.H.



3 TEES

# 24 TOTAL COMPONENTS



e

.

.

i

# DECEMBER 1986 THICKNESS READINGS AT GINNA STATION



205340

# TERS 4A & 4B TO FEEDWATER SUCTION

P

>90

# FEEDWATER SUCTION TO PUMPS A & B

34

RG&E SUMMARY NUMBER	ID NO. PER DRAWING [;]	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
	_	_	
205020	2	۲	>90
p30	3	E	>90
0640	4	P	>90
206050	5	E	>90
206060	6	P	>90
206110	11	P	>90
206120	12	E	>90
206140	14	P	>90
206250	25	P	>90
206260	26	E	>90
206270	27	P	>90

# 5A H.P.H. DRAIN TO 4A L.P.H.

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
290210 290230 290250	21 23 25	т Т Т ,	>70 >70 >70 >70

# 58 H.P.H. DRAIN TO 48 L.P.H.

NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
291210	60	т	>90
291230	62	т	>90
291250	64	Т	>90

M-5

' REMARKS					
an a					
and an and the second states and a second state and a second second second second second second second second s					
and the second					

• • •

M-6

# REMARKS

.

# M-41A

#### REMARKS

- •
- .

# M-41B

#### REMARKS

ħ

.

١

4



£

# THE FOLLOWING IS A LIST OF COMPONENTS EXAMINED DURING THE 1987 OUTAGE AT GINNA

MSR 1A & 1B 2ND PASS DRAIN TO 5A H.P.H. & CONDENSER

- A.' 4 ELBOWS
- B. 10 PIPE SECTIONS
- C. 3 REDUCERS
- D. 7 TEES

MSR 2A & 2B 2ND PASS DRAIN TO 5B H.P.H. & CONDENSER

- A. 6 ELBOWS
- B. 9 PIPE SECTIONS
- C. 3 REDUCERS
- D. 6 TEES
- 1A, 2A, & 3A L.P.H. DRAINS
- A. 10 PIPE SECTIONS
  - 1 REDUCER
    - 9 TEES
- 1B, 2B, & 3B L.P.H. DRAINS
- A. 2 ELBOWS
- B. 11 PIPE SECTIONS
- C. 1 REDUCER
- D. 7 TEES

MSR 1A, 1B, 2A & 2B TO HEATER DRAIN TANK

- A. 2 ELBOWS
- B. 3 PIPE SECTIONS

#### FEEDWATER PUMP BYPASS

- A. 24 ELBOWS
- B. 18 PIPE SECTIONS
- C. 5 REDUCERS
- D. 5 TEES

DWATER BYPASS TO CONDENSER (CV-18)

- A. 11 ELBOWS
- B. 2 REDUCERS
- C. 11 PIPE SECTIONS





# DWATER BYPASS TO CONDENSER (CV-19)

- A. 12 ELBOWS
- B. 2 REDUCERS
- C. 11 PIPE SECTIONS

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P. "HEATER"

۶ × .

. . . .

- A. 3 ELBOWS
- B. 1 TEE

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P. HEATER

- A. 3 ELBOWS
- B. 1 TEE

#### STEAM EXTRACTION TO 5A & 5B H.P. HEATERS

- A. 5 ELBOWS
- B. 1 PIPE SECTION

C 2 TEES

S/G BLOWDOWN TO BLOWDOWN HEAT EXCHANGER

- A. 4 ELBOWS
- B. 14 PIPE SECTIONS
- C. 4 REDUCERS
- D. 2 TEES
  - * THIS INCLUDES BASELINE ON COMPONENTS THAT WERE REPLACED

S/G BLOWDOWN TO BLOWDOWN TANK HEADER

- A. 12 ELBOWS
- B. 26 PIPE SECTIONS
- C. 2 REDUCERS

PRESEPARATOR A & B DRAIN TO, HEATER DRAIN TANK

- A. 3 ELBOWS
- B. 5 PIPE SECTIONS
- C. 1 TEE -



•

,

.

*

.

,

,

AUX. FEEDWATER PUMP A TO F.W. DISCHARGE LINES



1.ELBOW 3 PIPE SECTIONS

AUX. FEEDWATER PUMP B TO F.W. DISCHARGE LINES

A. 1 ELBOW B. 2 PIPE SECTIONS

TURBINE DRIVEN AUX. FEEDWATER PUMP TO F.W. DISCHARGE LINES

a . . . . . . .

A. 3 PIPE SECTIONS

MAIN STEAM FROM S/G B

A. 1 ELBOW

MAIN STEAM TO TURBINE .

A. 1 ELBOW

4

1 PIPE SECTION

277 TOTAL COMPONENTS

.

•

•



# RESULTS OF THICKNESS READINGS AT GINNA DURING "1987 OUTAGE

V. + 1

#### 90 - 85% NOMINAL WALL THICKNESS

SER
•

#### 85 - 80% NOMINAL WALL THICKNESS



#### 80 - 70% NOMINAL WALL THICKNESS

4 MSR 1A & 1B 2ND PASS DRAIN TO 5A H.P.H. & CONDENSER MSR 2A & 2B 2ND PASS DRAIN TO 5B H.P.H. & CONDENSER 2 FEEDWATER RECIRC CV-18 3 3 FEEDWATER RECIRC CV-19 1 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H. STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H. 1 STEAM EXTRACTION TO 5A & 5B H.P.H. 2 2 S/G BLOWDOWN TO BLOWDOWN HEAT EXCHANGER 1 S/G BLOWDOWN TO BLOWDOWN TANK HEADER

## < 70% NOMINAL WALL THICKNESS

MSR 1A & 1B 2ND PASS DRAIN TO 5A H.P.H. & CONDENSER
MSR 2A & 2B 2ND PASS DRAIN TO 5B H.P.H. & CONDENSER
FEEDWATER RECIRC CV-18
FEEDWATER RECIRC CV-19
STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.
STEAM EXTRACTION TO PRESEPARATOR A & 4A L.P.H.
STEAM EXTRACTION TO 5A & 5B H.P.H.
S/G BLOWDOWN TO BLOWDOWN HEAT EXCHANGER
S/G BLOWDOWN TO BLOWDOWN TANK HEADER



.

.

.

'n

.

,



. "

Р

.

# 1987 OUTAGE THICKNESS READINGS AT GINNA STATION

.

6 5 5 5

.

MSR 1A &	18 2ND P	ASS DRAIN T	D 5A H.P.H. &	CONDESER DRAWING M-12A
RG&E SUMMARY	ID ND. PER	COMPONENT TYPE	PERCENTAGE OF NOMINAL	, REMARKS
NUMBER	DRAWING		IHICKNESS	
222230	21A	R	>90	,
222240	22	E	>90	REPLACED END OF 87 OUTAGE
222250	23	P	>90	REPLACED END OF 87 OUTAGE
222330	31	R	>90	
222340	32	Т	>90	•
222350	33	Т	>90	
222352	33A	P	>90	
222357	33B	т	>90	l de la constante de
222360	34	P	>90	
222370	35	Т	>90	
222380	36	P	>90	×
222390	37	Т	>90	
400	38	P	>90	
410	39	Т	>90	
222415	39A	P	>90	
222420	40	Т	>90	
222920	90	Т	>90	
223020	99	т		NO READINGS WERE TAKEN DUE TO
				WELD OVERLAY, REPLACED 87 OUTAGE
223030	100	P	80-70	REPLACED END OF 87 OUTAGE
223040	101	E	70-65 (.298)	REPLACED END OF 87 OUTAGE
223050	102	P	90-85	REPLACED END OF 87 OUTAGE
223060	103	E	<65 (.274)	REPLACED END OF 87 OUTAGE
223070	104	P	80-70	REPLACED END OF 87 OUTAGE
223080	105	E	80-70	REEXAMINE DURING 88 OUTAGE
223090	106	P	80-70	REEXAMINE DURING 88 OUTAGE
223095	106A	R	>90	
MSR 2A &	28 2ND P	ASS DRAIN T	D 58 H.P.H. &	CONDENSER DRAWING M-12B
			PEPCENTAGE	DEMADYC
	ID NU.	TVDE		NEHAKKO
		1166	TUTOVNECC	
NULIBER	DRAWING	,	1 HIGKNESS	• • • •
222400		Þ	NP0 ¹	
222470	48	F	80-70	FIRDW WAS REPLACED SUMMER 1986
222300	40 _.	E	80-70	WITH SCHEDULE 120 LINE SCHEDULE
				IS BO REFYAMINE DURING BR DUTAGE
510	49	Б.	200	10 00. NECKHITIKE DONTIG DO DOTHOL
2520	50	i- E	270	
222530	51	P	90-85	REEXAMINE DURING 88 OUTAGE
222680	66	Т	>90	
	~~	•	F F W	

22

a ²²

,

•

11

•

.

.

234180

234190

234200

234210

234220

234230

234240

234250

234260 234270

234340

234345

234350

234355

234370

234380

234510

0530

520

34540

18

19

20

21

22

23

24

25

26

27

34

34A

35

37

38

51

52

53

54

35A .

Т

Ρ

Т

Ρ

Т

Ρ

Т

Ρ

Т

P

R

Ρ

Т

Р

Т

P

т

Ρ

Т

Ρ

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

>90

.

.

2A & 2B 2ND PASS DRAIN TO 5B H.P.H. & CONDENSER DRAWING M-12B CONT.

٠

.

----

. . .

1314

•				· · · · · · · · · · · · · · · · · · ·
RG&E	ID NO.	COMPONENT	PERCENTAGE	REMARKS
SUMMARY	PER	TYPE	OF NOMINAL	
NUMBER	DRAWING	•	THICKNESS	
	/ <del>- 7</del>	••••	200	
222690	6/		290	in the second second to the second
222700	68	۲ ۲	>90	•
222710	69		290	
222720	70	P _	\$90	•
222730	71 [·]	Т	>90	
222800	78	R	>90	•
222610	79	E	>90	REPLACED END OF 87 OUTAGE
222820	80	P	90-85	REPLACED END OF+87 OUTAGE
222830	81	Ţ		NO READINGS WERE TAKEN DUE TO
				WELD OVERLAY, REPLACED 87 OUTAGE
222840	82	P	85-80	REPLACED END OF 87 OUTAGE
222850	83	E	<65 (.254)	REPLACED END OF 87 OUTAGE
222860	84	· P '	>.90	REPLACED END OF 87 OUTAGE
222870	85	Ē	90-85	REPLACED END OF 87 OUTAGE
222880	86	P	80-70	REPLACED END OF 87 OUTAGE
222890	87	F	85-80	REPLACED END OF 87 OUTAGE
222900	88	p `	90-85	REEXAMINE DURING 88 OUTAGE
222805	880	R	20	
<b>E P</b> 10	90 90	T	200	
	07	•	210	
1A, 2A,	& 3A, L.P	.H. DRAINS		DRAWING M-19
RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS

•

1

,

•

,

•

×

2B &	38 L.P.H	. DRAINS	
RG&E	ID NO.	COMPONENT	PERCENTAGE
SUMMARY	PER	TYPE	OF NOMINAL
NUMBER	DRAWING		THICKNESS
235140	14	, P	200
233180	10	г е	270 1280
233170	17		270
235180	18	۲ ۲	
233170	17	<b>E</b>	270 280
235200	20 -	г Т	270
235210	21	1	290
235220	22	r' 	>90
.235230	23	1	>90
235240	24	P	>90
235250	25	Т	>90
235260	26	P	>90
235325	32A	R	<b>&gt;</b> 90 -
235330	33	P	>90
235340	34	т	>90
235350	35	P	>90
235370	37	т	>90
235380	38	P	>90
2 <u>35</u> 510	51	Т	>90 -
<b>520</b>	52	P	>90
530	53	Т	>90
235540	54	p '	200

# MSR 1A, 1B, 2A & 2B TO HEATER DRAIN TANK

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
262030	3	Ē	>90
262040	4	Р	>90
262055	5A	P	>90
262060	6	E	>90
262070	7	P	85-80

# FEEDWATER PUMP BYPASS

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS
281020	2	E	BASELINE
281030	3	Р	BAŚELINE
281040	4	E	BASELINE
050	5	Р.	BASELINE
6060	6	E	BASELINE
201070	7	Р	BASELINE
281,090	<b>'</b> 7	P	BASELINE
281110	11	Р	BASELINE

DRAWING M-20

.

•

# REMARKS

**1**11 11 12

.

and and the constants

# 

•

.

# DRAWING M-33

REMARKS

# REEXAMINE DURING 88 OUTAGE

# DRAWING M-92

REMARKS



•

.

ø

,

ì

.


## DWATER PUMP BYPASS

### DRAWING M-92 CONTINUED

• •

.

RG&E	ID NO.	COMPONENT	PERCENTAGE
SUMMARY	PER	TYPE	OF NOMINAL
NUMBER	DRAWING		THICKNESS
	1		
281130	13	R	BASELINE
281140	14	P	BASELINE
281150	15	E	BASELINE
281160	16	P	BASELINE
281180	18	Е	BASELINE
281190	19	P	BASELINE
281200	20	F	BASEL INE
281210	21	P	BASEL INE
291230	27	P	BASEL THE
201200		Þ	
201230	23	r D	DAGELINE
201270	27	n D	
281280	28	۲ ۲	BASELINE
281290	27	R	BASELINE
281300	30	<u>T</u>	BASELINE
281310	31	E	BASELINE
281320	32	Т	BASELINE
281330	33	P	BASELINE
<u>28</u> 1340	34	E	BASELINE
350	35	, E	BASELINE
<b>1</b> 360	36	P	BASELINE
281370	37	E	BASELINE
281380	38	E	BASELINE
281390	39	P	BASELINE
281400	40	Ē	BASELINE
281410	41	P	BASEL INE
281420	42	F	BASEL INE
281440	44	Ē	BASELINE
281440	44	F	BASEL INE
281480	40	5	BACELINE
201400	40	с Е	
201470	<del>4</del> 7		DAGELINE
281300	30	г т	BHOELINE DAOGLINE
281520	52	1	BASELINE
281530	53	<u>к</u>	BASELINE
281540	54	Ť	BASELINE
281560	56	E	BASELINE
281600	60	E	BASELINE
281620	62	É	BASELINE
281640	64	E	BASELINE `
281680	68	т.	BASELINE
281700	70	E	BASELINE
281730	73	R	BASELINE
281750	75	E	BASELINE
281760	76	P	BASELINE
770	77	E.	BASELINE
			· · _ · _ <b> · · · -</b>

REMARKS

•••

· ·

# 

•

.

· · · · ·

770

NDTE: FEEDWATER BYPASS LINE IS A NEW INSTALLATION DONE DURING THE 87 OUTAGE



•

WAT	ER BYPASS	TO CONDENS	ER (OLD CV-18	۲ ( ۱	DRAWING C	¥−18	
RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS		REMA	ARKS	
300220	22	E	>90 ,		•	¥	ų
300230	23	P	<b>&gt;</b> 90 `	* *	-s *x	1. S. 1999 (g. 1999)	
300240	24	E	>90				
300250	25	P	>90				
300260	26	E	70-85	×			
300270	27	P	90-85	×			
300280	28	E	>90			t	
300300	29	R	>90				
300310	30	P	>90				
300320	31	E	`>90				
300330	32	P	>90				
300340	33	E	>90				
300350	34	E	>90				
300360	35	P	>90				
300370	36	E	>90			,	
300380	37	Р	>90				
300390	38	E	>90		A		
3 <u>00</u> 400	39	P	80-70	×			
\$10	40	E	80-70	*			
A20	41	P	80-70	*			
300430	42	E	>90				
300440	43	۴	70-65 (.299)	<b>*</b> '			
300450	44	R	90-85	*			
300460	45	P	90-85	*			

4 x

• ----

* NOTE: IT HAS NOT BEEN DECIDED IF THESE COMPONENTS WILL BE REEXAMINED IN 1988. THE FEEDWATER BYPASS SYSTEM THAT WAS INSTALLED IN 1987 SHOULD TAKE OF THIS EROSION PROBLEM. ALSO THE NEW FEEDWATER BYPASS HAS REPLACED COMPONENTS 1' THROUGH 20

FEED WATER BYPASS TO CONDENSER (OLD CV-19)

### DRAWING CV-19

. .

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS		REMARKS
300480	2	E	>90	4 <b>4</b> 5	en 1997
300490	3	P.	>90		-
300640	18	E	>90		2
300650	19	P	>90		
300660	20	ΕĹ	>90		
300670	21	P	>90		
229680	22	Ε.	>90		
<u>_</u> 50	23	F	90-85	×	
500700	24	E	>90		
300710	25	P	>90		
300720	26	E	80-70	*	



•

.

χ.

ш

D WAT	ER BYPASS	TO CONDENS	ER (OLD CV-)	17) DRAWING CV-19 CONTINUED
RG&E SUMMARY NUMBER	ID NO. PER DRAWING	CÓMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
300730	27	Р	>90	•
300740	28	. <b>E</b>	· <b>90-85</b>	💥 👘 🧞 🔹 👘 👘 👘 👘 👘
300750	29	P,	90-85	<b>* .</b>
300760	30	E	>90	an ang ang ang ang ang ang ang ang ang a
300770	31	E	>90	
300790	33	R	<u>&gt;</u> 90	
300800	34	E	>90	
.300810	35	Р	>90	
300820	36	E	80-70	*.
300830	37	P	>90	1
300840	38	E	80-70	*
300850	39	P	<65 (.270)	*
300890	40	R	>90	
300870	41	P	>90	•

* NOTE: IT HAS NOT BEEN DECIDED IF THESE COMPONENTS WILL BE REEXAMINED IN 1988. THE FEEDWATER BYPASS SYSTEM THAT WAS INSTALLED IN 1987 SHOULD TAKE OF THIS EROSION PROBLEM. ALSO THE NEW FEEDWATER BYPASS HAS REPLACED COMPONENTS 3 THROUGH 16.

STEAM EXTRACTION TO PRESEPARATOR B AND 4B L.P.HEATER DRAWING M-21

RG&E II SUMMARY I NUMBER DR/	D ND. COMPO PER TYP AWING	NENT PERCEN E OF NON THICKN	NTAGE 1INAL NESS	REMA	RKS	
301020 2	E	>90				
301160 15	5 E	>90				
301350 33	з Т	80-70	REEX	AMINE DURIN	3 88	OUTAGE
301370 3	5 E	70-65	(.260) REEX	AMINE DURIN	G 88	OUTAGE

STEAM EXTRACTION TO PRESEPARATOR A AND 4A L.P.HEATER DRAWING M-22

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS	۰ بر ۱
301720 301900	3 19	E.	>90 >90		
302070 302090	33 35	TE	80-70 <65 (.223)	REEXAMINE DURING 88 REEXAMINE DURING 88	OUTAGE OUTAGE

•

.

y.

,

AM EX	TRACTION	TD 5A & 5B	H.P. HEATERS	DRAWING M-75
RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
303090	9	Т	<65 (.244)	REEXAMINE DURING 88 OUTAGE
303100	10	P	80-70 📫 🖤	""REEXAMINE DÜRING"88 DUTAGE
303110	11	E	80-70	REEXAMINE DURING 88 OUTAGE
303130	13	E	<65 (.237)	REEXAMINE DURING 88 OUTAGE
303140	14	E	70-65 (.247)	REEXAMINE DURING 88 OUTAGE
303230	23	Т	90-85	REEXAMINE DURING 88 OUTAGE
303240	24	E	85-80	REEXAMINE DURING 88 OUTAGE
303280	28	E	<65 (.232)	REEXAMINE DURING 88 OUTAGE
S/G BLOW	IDOWN TO E	BLOWDOWN HEA	T EXCHANGER	DRAWING M-87
RG&E	ID NO.	COMPONENT	PERCENTAGE	REMARKS
SUMMARY	PER	TYPE	OF NOMINAL	
NUMBER	DRAWING		THICKNESS	-
304080	8	P	290	
304100	10	P	(45 (.120))	* *
004100	10	, , q	BASELINE	-
20	17	· P	(171)	
	12	P	BASEL INF	
304130	13	R	90-85	*
004100	13	R	BASEL INE	
304210	21	P	>90	
304230	23	P	(45 (115)	¥
004200	23	P	RASELINE	•
304740	24	י ק	80-70	COMPONENT HAS BEEN ELIMINATED
304250	27	י ד	70-45 (.708)	
004200	25	Ť	RASELINE	
304260	20	- -	80-70	*
004200	26	, p	BASELINE	••
304270	20	, E	200 200	
304270	20	5	270	•
304280	20	' E	270	· ·
304270	30	, L P	290	
304300	30	, F	90-85	REEXAMINE DURING 88 DUTAGE
304320			200 200	REEXHITTE DONTIO DO BOTHDE
304340	34	. 8	590 	
304350	77 75	F	90-85	
304330	34	R	,	A Y 10 REDUCER CAN NOT RE
007080	00	iv .	•	PROPERLY LAID OUT, HOWERVER SCAN SHOWS NO SIGN OF WEAR

٠

بالكر فالع

-

.

8

* THESE COMPONENTS WERE REPLACED DURING 87 DUTAGE AND BASELINE DATA WAS TAKEN



4**۴.** 

•



·

۲

.

s.

### BLOWDOWN LINES - INTERMIDIATE BLDG.

### RG&E ID NO. COMPONENT PERCENTAGE OF NOMINAL PER TYPE SUMMARY NUMBER DRAWING THICKNESS -304420 2 Ε . Ε 304440 4

### DRAWING M-88A

### REMARKS

COMPONENT IS A FORGED ELBOW AND CAN*NOT BE LAID OUT, HOWEVER SCAN SHOWS MINIMUM WALL OF .180 WILL REEXAMINE DURING 88 OUTAGE COMPONENT IS A FORGED ELBOW AND CAN NOT BE LAID OUT, HOWEVER SCAN SHOWS MINIMUM WALL OF .133 WILL REEXAMINE DURING 88 OUTAGE

### S/G BLOWDOWN TO BLOWDOWN TANK HEADER

### DRAWING M-888

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
690	29	P	>90	
710	31	P	>70	
304730	33	P	>90	
304750	35 '	P	>90	
304770	37	P	>90	•
304790	39	P	80-70	REEXAMINE DURING 88 OUTAGE
304820	42	P	>90	
304840	44	P	>90	
304860	46	R	>90	
304865	46A	E	<65 (.208)	OUTSIDE RADIUS OF ELBOW CAN NOT BE EXAMINED DUE TO RESTRICTIONS,
•				REEXAMINE DURING 88 DUTAGE
304870	47	P	85-80	REEXAMINE DURING 88 OUTAGE
304880	48	E	90-85	REEXAMINE DURING 88 OUTAGE
304890	49	P	>90 -	
304900	50	E	85-80	REEXAMINE DURING 88 OUTAGE
304920	52	E	90-85	REEXAMINE DURING 88 OUTAGE
304930	53	P	>90	•
305220	82	P	>90	٠
305240	84	P	>90	e si ^e k ^a n _s an
305260	86	Ρ.	>90	
305280	88	P	>90	•
305300	90	·P	>90	
305320	92	P	>90	
305340	94	P	>90	
5360	96	• Р .	70-65 (.142)	REEXAMINE DURING 88 OUTAGE
U390	99	P	>90	
5-5410	101	P	90-85	REEXAMINE DURING 88 OUTAGE
305430	103	Ð	200	,



• .

4

•

•

*,* '

.

BLOW	DOWN TO B	LOWDOWN TAN	K HEADER	DRAWING M-888 CONTINUED
RG&E SUMMARY	ID NO. PER	COMPONENT TYPE	PERCENTAGE OF NOMINAL	REMARKS
NUMBER	DRAWING		THICKNESS	
305440	104	E 🔒	70-65 (.229	) OUTSIDE RADIUS OF ELBOW CAN NOT See EXAMINED DUE TO RESTRICTIONS, REEXAMINE DURING 88 OUTAGE
305450	105	Р	>90	and the second
305460	106	E	90-85	REEXAMINE DURING BB OUTAGE
305470	107	P	90-85	REEXAMINE DURING 88 OUTAGE
305480	108	E	>90	
305490	109	P	90-85	REEXAMINE DURING 88 OUTAGE
305500	110	E	>90	,
305510	111	P	>90	
305520	112	E	90-85	REEXAMINE DURING 88 OUTAGE
305540	114	E	>90	
305550	115	P	90-85	REEXAMINE DURING 88 OUTAGE
 GEPAR	ATOR A &	NOTE: M D B DRAIN TO	IANY ELBOW CO DUE TO GEOMET IOT LEND THEM <b>HEATER DRAIN</b>	MPONENTS CAN NOT BE EXAMINED RY. ELBOWS ARE FORGED AND DO SELVES TO LAYOUT OR U.T. SCANNING TANK DRAWING M-46B
		COMODUCNIT		DEMARKE
RUMADY	ID NU.		PERLENIAGE	RENHRKS
	DRANTNE	ITE	TUICKNERR	
NOMBEN	DUHATIO		INTERACOO	
328160	16	т	>90	
328240	24	P	>90	UPSTREAM PORTION OF PIPE
328245	24	P ·	>90	DOWNSTREAM PORTION OF PIPE
328250	25	E	>90	
328260	26	P	>90	
328270	27	E	90-85	REEXAMINE DURING 88 DUTAGE
328280	28	P	>90	
328290	29	E	90-85	REEXAMINE DURNIG 88 OUTAGE
328300	30	P.	>90 、	
AUX. F.W	. PUMP A	TO F.W. DIS	CHARGE LINES	DRAWING M-48
RG&E	ID ND.	COMPONENT	PERCENTAGE	REMARKS
SUMMARY NUMBER	PER DRAWING	TYPE	OF NUMINAL THICKNESS	
320240	25	F	90-85	REEXAMINE DURING BB OUTAGE
320244	268	P	>90	
320430	43	°P	>90	UPSTREAM PORTION OF PIPE
280435	43	P	>90	DOWNSTREAM PORTION OF PIPE
D		*		

. .

.



$\sim$	- 22.

### F.W. PUMP B TO F.W. DISCHARGE LINES

DRAWING M-49

w er

ی ا

. . .

i. . .

.

d .

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
323200	20	E	>90	REEXAMINE DURING 88 OUTAGE
323210	21	P	>90	
323420	42	P	90-85	

# TURBINE DRIVEN AUX F.W. PUMP TO F.W. DISCHARGE LINES DRAWING-47

RG&E SUMMARY NUMBER	ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
327560 327565 327880	56 56 88	P P	>70 >70 85-80	UPSTREAM PORTION OF PIPE DOWNSTREAM PORTION OF PIPE REEXAMINE DURING 88 OUTAGE

### MAIN STEAM FROM S/G A & B

RG&E SUMMARY	、ID NO. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	
370020	2	Ē	>90	

### MAIN STEAM TO TURBINE

DRAWING M-72

DRAWING M-70

REMARKS

RG&E SUMMARY NUMBER	ID ND. PER DRAWING	COMPONENT TYPE	PERCENTAGE OF NOMINAL THICKNESS	REMARKS
372140	14	E	>90	
372150	15	P (	200	









*

•

.

•

. .

.

.

С М





# LOW PRESSURE DOWNCOMERS



TOP VIEW





NO.	DESCRIPTIC	FILE
		NAME
1	4'PIPE	300010
2	90 ELBOW	300020
3	6'PIPE	300030
4	90 ELBOW	300040
5	6'PIPE	300050
6	90 ELBOW	300060
7	3' PIPE	300070
8	90 ELBOW	300080
9	2' PIPE	300090
10	VALVE 4061	300100
11	90 ELBOW	300110
12	3'PIPE	300120
13	90 ELBOW	300130
14	4'PIPE	300140
15	90 ELBOW	300150
16	9' PIPE	300160
17	90 FLBOW	300170
18	4'PIPE	300180
19		300190
· 20	27' DIDE	300200
21	517 DTDF	300210
22		300220
27		300230
24		300240
25		300250
20		300250
27	41 DIDE -	300280
		300270
20	45 ELBUW	300280
28	AUTO CUREDUCER	300290
29	4"IU B"REDUCER	300300
30	S, DIDE	300310
31	, 45 ELBUW	300320
32	1, PIPE	300330
33	45 ELBUW	300340
34	45 ELBOW	300350
, 35	1'PIPE	300360
36	45 ELBOW	300370
37	4'PIPE	300380
38	90 ELBOW	300390
39	2'PIPE	300400
40	45 ELBOW	300410
41	1'PIPE	300420
42	45 ELBOW	300430
43	4'PIPE	300440
44	6"TO 4"REDUCER	300450
45	2'PIPE	300460

+

!.

ì



•

\$

.

.





,

1

.

,

.

.



٩. ÷

•

• •

.

.

•

κ.



. . .

() ()

£

* - *

* .

,

· · · ,

ν.

.



M-12A MSR 1A & 1B 2ND PASS DRAIN TO 5A H.P.H. & CONDENSER

して

.

, e , e ,

۰.

.

,



•

:



٩

,

,

•





# ч,

,

.

.

*





÷

.

٠

.

.

٣

с.

•



2

M-21 STEAM EXTRACTION TO PRESEPARATOR B & 4B L.P.H.

1.

2 x × . .

. ·

•





,

μ

٠

4

.

,




ę

,

,

L

.



. `

4

ja

•



# . . .

.

.

· •

۰ .

,





6.

.



トナ

, A.

•

. .

.

,

.



л. С

. • ٩

é

.



:

M-49 AUX F.W. PUMP B TO DISCHARGE LINES

л. 0.





.

×

8

• • ,

•





d) O

9

Ν



,





ι,

·

.

•

.

. , ,



M-75 STEAM EXTRACTION TO 5A & 5B H.P.H.

y.

3

۴

•

¢

`

e.



Ю. ())

Ą

,





. ...



. B

۰.

.



σı (JI

2 •

•



.

.

;

7

.

, .

.

.

.

Attachment 2

to

# NRC IE Bulletin 87-01 Response

(Ref. Item 4b)

,

•

*.* 

t

.



# LAYOUT FOR U.T. THICKNESS READINGS











.

-

,

4



(N

, , .

,

r.

¢۵

DATA FILE : SAMPLE. PLT

**`** ¥

• ;

**?**)

 $\mathbf{O}$ 

7

0

<u>_</u>`i

्र

j

1

_)

)

.)

ر

2

## ELBOW

2 - 2

COMPONENT DESCRIPTION : 90 DEGREE ELBOW

SCHEDULE NUMBER : 80

ELBOW ANGLE : 90

NOMINAL PIPE SIZE : 6 OUTER DIAMETER : 6.625 PIPE THICKNESS : 432

CIRCURFERENTIAL RANGE : A - U LENGTH RANGE : 1 - 18 NUMBERS OF TRANSITION RINGS : 1 AND 18

### FLOW DIRECTION : DOWNSTREAM

INCREMENT DIRECTION : CW REFERENCE FROM WHICH RINGS WILL BE MEASURED : UPSTREAM WELD LOCATION OF FIRST DATA RING (FROM REFERENCE) : .5 DISTANCE BETWEEN DATA RINGS : 1

		1	2	3	4	5	6	7	8	9	10
	A	0.4850	0.3820	0.3820	0.3820	0.3610	0.3400	. 0.2970	0.1540	0.0920	0.2970
	B	0.4480	0.4370	0.4340	0.4340	0.3820	0.3820	0.3400	0.2970	0.2970	0.3400
	C	0,4190	0.4140	0.4160	0.4190	0.4110	0.3820	0.3820	0.3400	0.3400	0.3820
•	D	0.4460	0.4230	0.4170	0.4380	0.4130	0.4000	0.3820	0.3820	0.3820	0.3820
	ε	0.4380	0.4490	0.4550	0.4340	0.4310	0.4240	0.4370	0.4450	0.4620	0.4190
	F	0.4760	0.4590	0.4600	0.4690	0.4480	0.4740	0.4580	0.4510	0.4800	0.4710
	6	0.4900	0.4780	0.4690	0.4730	0.4620	0.4960	0.4540	0.4790	0.4580	0.4620
	H	0.5090	0.4890	0.4900	0.4850	0.4980	0.4520	0.4560	0.4520	0.4570	0.4680
	I	0.4930	0.4880	0.4450	0.4640	0.4600	0.4380	0.4440	0.4470	0.4420	0.4460
	J	0.4840	0.4840	0.4950	0.4500	0.4450	0.4410	0.4620	0.4430	0.4510	0.4520
	К	0, 4970	0.4740	0.4750	0.4780	0.4750	0.4730	0.4800	0.4990	0.4920	0.4770
	L	0.5240	-1.0000	-1.0000	-1.0000	0.5270	0.5250	0.5000	0.5160	0.5210	0.5090
ار +	H	0.5270	-1.0000	-1.0000	-1.0000	0.4880	0.5010	0.4980	0.5000	0.5120	0.5070
	N	0.4700	-1.0000	-1.0000	-1.0000	0.4660	0.4540	0.4600	0.4550	0.4720	0.4470
	0	0.4820	0.4790 *	0.4590 Æ	0.4620 w	0.4530	0.4830	0.4580	0.4580	0.4580	0.4570
	P	0.4540	0.4440-	0.4380	• 0.4440-*	0.4650	0.4620	0.4590	0.4570	0.4620	0.4540
	۵.	0.4540	0.4540	0.4520	0.4380	0.4420	0.4400	0.4580	0.4480	0.4330	0.4350
	R	0.4430	0.4250	0.4250	0.4290	0.4370	0.4320	0.3820	0.3820	0.3820	0.3820
	S	0.4430	0.4550	0.4180 p	0.4140*	o. 4040	0.3820	0.3820	0.3400	0.3400	0.3820
	T	0.4400	0.4400	0.4060	0.4180	0.3820	0.3820	0.3400	0.2970	0.2970	0.3400
	U	0.4400	0.4230	0.3820	0.3820	0.3510	0,3400	0.2970	0.1540	0,1000	0.2970

З

_

. х

,
\$		11	12	13	14	15	16	17	18	
'n	A	0.3400	0.3610	0.3820	0.4360	0.4270	0.4370	0.4300	0.4420	
	В	0.3820	0.3820	0.4270	0.4390	0.4330	0.4250	0.4250	0.4260	
<del>ت</del>	C	0.3820	0,4080	0.4200	0.4130	0.3970	0.4190	0.3990	0.4150	
	D	0.4790	0.4160	0.4040	0.4050	0.4150	0.4320	0.4190	0.4340	
÷	Ε	0.4590	0.4190	0.4560	0.4390	0.4520	0.4300	0,4320	0.4360	
	F	0.4640	0.4540	0.4530	0.5120	0.4980	0.4520	0.4670	0.4390	
	6	0.4510	0 <b>. 4</b> 470 [*]	0.4470	0.4450	0,4530	0.4510	0.4540	0.4420	
	H	0.4520	0.4470	0.4450	0.4390	0.4400	0.4390	0.4370	0.4360	
	I	0.4530	0.4760	0.4370	0,4730	0.4430	0.4480	0.4430	0.4240	
	J	0.4520	0.4420	0.4500	0.4410	0.4480	0.4480	0.4380	0.4430	
•	K	0.4840	0.4820	0.4750	0.5220	0.4780	0.4850	0.4900	0.4940	
	L	0.5170	0.5100	0.4930	0.5020	0.5110	0.5020	0.5960	0.5070	
")	M	0.4880	0.4920	0.4950	0.4800	0.4840	0.4920	0.5280	0.4850	
	н	0.4570	0.4650	0.4920	0.4410	0.4550	0.4550	0.5050	0.5260	
,)	0	0.4620	0.4620	0.4560	0.4510	0.5140	0.4550	0.5030	0.4540	
	р	0.4540	0.4540	0.4530	0.4730	0.4780	0.4620	0.5000	0.4660	
`>	Q	0.4330	0.4470	0.4540	0.4540	0.4540	0.4560	0.4570	0.4560	
	R	0.4540	0.4540	0.4650	0.4550	0.4580	0.4570	0.4570	0.4540	
5	S	0.3820	0.4220	0.4620	0.4210	0.4030	0.4270	0.4230	0.4460	
	T	0.3820	0.3820	0.4110	0.4060	0.4030	0.3990	0.4080	0.4450	
۲	ป	0.3400	0.3610	0.3820	0.3820	0.4340	0.4540	0.4350	0.4700	
,										

•

<u>,</u>

.)

}

ン

S

J

C

C

 $\mathbf{c}$ )

٤

4

•

. . . 9 . . 

.



## Attachment 3

# TABLE 1

## SUGGESTED FITTINGS

- ° Closely Coupled Fittings or Configurations
- ° Entrant Tee, Combining Tee, Splitting Tee
- ° 90° Elbow
- Reducer/Expander
- Straight Section of Pipe Downstream of:
  - Reducer
  - Flow Control/Throttling Valve
  - Restricting Orifices
  - Multiple Thermowells, etc.

# TABLE 2

#### SUGGESTED PIPING LOCATIONS

- Feedwater Suction
- Feedwater Discharge
- Heater Drain Pump Discharge
- Condensate from FW Heater
- HPCI (BWR)

, . -

2 .

, . ,

•

, 1 -

2



## Attachment 3

# TABLE 3

### KEY PARAMETERS

C.S. piping & components - major parameter; chromium content
pH.

° 0₂ content

° Fluid temperature "

• Local/Bulk flow rate :

Out configurations (backing rings, etc.)

NOTE: Information extracted from EPRI Workshop Information (April 14-15) and EPRI Report NP-3944



- ÷

ł

\$

,

.

. . -,

4

•

a

. .

理いに認知