





SUPPLEMENT TO LER #78-098/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

AS THE PREOPERATIONAL TEST WILL NEVER AGAIN BE PERFORMED, THE AFFECTED TEST WAS NOT BACKFITTED TO ADD IN A DETAILED PROCEDURE FOR THE ADJUSTMENT AND RESTORATION OF THE SUBJECT ALARMS.

THE RESPONSIBLE ENGINEERING SECTION HEAD HAS REVIEWED THIS EVENT WITH ALL SECTION PERSONNEL. ADDITIONALLY, A LETTER HAS BEEN RECENTLY SENT TO THE SECTION HEAD REQUESTING TRAINING ON SPECIFIC POINTS OF THIS EVENT, INCLUDING THE NEED FOR PROMPT OPERATOR NOTIFICATION, WHO, IF PROMPTLY NOTIFIED, COULD POSSIBLY HAVE PERFORMED T.S. 4.2.1.1.a.2 WITHIN THE SPECIFIED TIME LIMIT.

2 2 2 2 2