May 22, 1979

Docket llos. 60-315 and 30-316

Mr. John Tillinghast, Vice President Indiana and Hichigan Electric Company Indiana and Michigan Power Company Post Office Box 18 Bowling Green Station New York, New York 10004

Dear Mr. Tillinghast:

SUBJECT: NRC STAFF REVIEW OF RESPONSES TO IRE BULLETINS 79-06 AND (see 50-305 for eacl)

We have completed a preliminary review of the licensee responses to I&E Bulletins 79-06, 79-06A, and amendment 1 to 79-06A. The purpose of this letter is to advise you of the preliminary results of that review, with particular emphasis on potential problem areas, and to identify related concerns which we believe require your further examination.

Will be held on May 30, 1979, in rooms P-110/114 at our Phillips Building office in Bethesda, Maryland. You are expected to attend the meeting and be prepared to discuss those matters identified below along with a schedule and procedure for providing the information needed by NRC to complete the review of these issues.

- (1) Our preliminary review of the Bulletin responses indicates that a number of the Bulletin items are not yet satisfactorily resolved. Enclosure 1 provides a summary of our current assessment of the responses to the Bulletins issued on Westinghouse plants.
- (2) In certain instances, licensee responses differ, without apparent justification, from the Westinghouse recommendations for individual Bulletin items. We expect to resolve each such difference, as well as licensee exceptions to specific Bulletin responses, prior to our approval of the Bullétin responses. A copy of the Westinghouse recommendations is provided as Enclosure 2.

(3) The Westinghouse advice is prescriptive on resetting of the high pressure injection system and incomplete as to the need for keeping

						1
DATE≯	L				••••••••	
	l .	`	I .			
CURNAME>		}			••••••	,
OFFICE→					*******************	
	the read	feor coolane p	mps running.	,		ĺ

P N The T

11.50

Mr. John Tillinghast
Indiana and Michigan Electric Co.
Indiana and Michigan Power Co.

(4) We are finalizing a generic report on THI-2 matters related to Hestinghouse operating plants. Although this report is not yet complete, among other things, we expect that it will recommend further analyses of transients and small reactor coolant system breaks, the development of appropriate written procedure guidance to operators in the use of these new procedures.

- (5) In certain instances, licensees are using fuel and relying on safety analyses, which were not provided by Westinghouse. As a result, it is not clear to us what the respective roles of the licensees, Westinghouse, the fuel suppliers, and/or other parties should be in implementing those requirements described in item (4) above. We need a clear and concise definition of their respective roles in these cases.
- (6) The Advisory Committee on Reactor Safeguards (ACRS) has issued five letters to the Commission as a result of their examination of the TMI-2 accident. We need a clear and concise position from all licensees with respect to each of the recommendations contained in these letters. A summary of the ACRS recommendations is provided as Enclosure 3.
- (7) Individual licensees have indicated an interest in meeting directly with the staff regarding the Bulletin items for their facilities. Experience to date has demonstrated that the staff does not have time to meet individually with each licensee to resolve these items.

It is clear that there are a significant number of technical issues yet to be resolved for a large number of Nestinghouse operating plants. There are limited resources available within the NRC staff to perform the necessary work. This situation is exacerbated by the need to conduct similar and concurrent activities with those owners of B&W, C-E, and GE designed operating plants. At the same time, there is a need to resolve these matters promptly.

To resolve the issues described above in a prompt and expeditious manner, we believe there is a compelling need to establish an owner's group for Westinghouse operating plants. We expect that such a group would be needed for the remainder of calendar year 1979. Owner's groups have worked effectively in the past in minimizing staff and industry resource requirements to resolve other generic problems. We strongly urge you to meet with other owners of Westinghouse operating plants to consider the formation of such a group prior to our meeting on May 30. This will be one of the principal agenda items at that meeting.

offic k >	 ••••••		••••••••••	*************************	
CURNAME >>	 	4.1	************************	r	
*		•			



Mr. John Tillinghast
Indiana and Michigan Electric Co.
Indiana and Michigan Power Co. - 3

Please note that investigation of a number of areas related to the TNI-2 accident, including the long-term ACRS recommendations and long-term action items from NUREG-0560, will be specifically included as part of the future "Lessons Learned" staff activity. You can expect additional correspondence in the future on these items.

If you require any clarification of the matters discussed in this letter please contact Patrick D. O'Reilly, the staff's assigned project manager for these activities on Nestinghouse plants. Nr. O'Reilly may be reached on (301) 492-7745.


Sincerely,

A. Schwencer, Chief Operating Reactors Branch #1 Division of Operating Reactors

. Enclosures: As Stated

> cc: w/enclosures See next page

offic# >				,*	DOR: ORB#1
	4		l l		
•	•	•		٠, ١	5//79
				<u></u>	





UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

May 22, 1979

Docket Nos. 50-315 and 50-316

Mr. John Tillinghast, Vice President Indiana and Michigan Electric Company Indiana and Michigan Power Company Post Office Box 18
Bowling Green Station
New York, New York 10004

Dear Mr. Tillinghast:

SUBJECT: NRC STAFF REVIEW OF RESPONSES TO I&E BULLETINS 79-06 AND

79-06A

We have completed a preliminary review of the licensee responses to I&E Bulletins 79-06, 79-06A, and amendment 1 to 79-06A. The purpose of this letter is to advise you of the preliminary results of that review, with particular emphasis on potential problem areas, and to identify related concerns which we believe require your further examination.

We have scheduled a meeting with the owners of all operating plants having Westinghouse designed nuclear supply systems. This meeting will be held on May 30, 1979, in rooms P-110/114 at our Phillips Building office in Bethesda, Maryland. You are expected to attend the meeting and be prepared to discuss those matters identified below along with a schedule and procedure for providing the information needed by NRC to complete the review of these issues.

- (1) Our preliminary review of the Bulletin responses indicates that a number of the Bulletin items are not yet satisfactorily resolved. Enclosure 1 provides a summary of our current assessment of the responses to the Bulletins issued on Westinghouse plants.
- (2) In certain instances, licensee responses differ, without apparent justification, from the Westinghouse recommendations for individual Bulletin items. We expect to resolve each such difference, as well as licensee exceptions to specific Bulletin responses, prior to our approval of the Bulletin responses. A copy of the Westinghouse recommendations is provided as Enclosure 2.
- (3) The Westinghouse advice is prescriptive on resetting of the high pressure injection system and incomplete as to the need for keeping the reactor coolant pumps running.

• Α..... • • · ; . •

Mr. John Tillinghast
Indiana and Michigan Electric Co.
Indiana and Michigan Power Co. - 2 -

- (4) We are finalizing a generic report on TMI-2 matters related to Westinghouse operating plants. Although this report is not yet complete, among other things, we expect that it will recommend further analyses of transients and small reactor coolant system breaks, the development of appropriate written procedure guidance to operators in the use of these new procedures.
- (5) In certain instances, licensees are using fuel and relying on safety analyses, which were not provided by Westinghouse. As a result, it is not clear to us what the respective roles of the licensees, Westinghouse, the fuel suppliers, and/or other parties should be in implementing those requirements described in item (4) above. We need a clear and concise definition of their respective roles in these cases.
- (6) The Advisory Committee on Reactor Safeguards (ACRS) has issued five letters to the Commission as a result of their examination of the TMI-2 accident. We need a clear and concise position from all licensees with respect to each of the recommendations contained in these letters. A summary of the ACRS recommendations is provided as Enclosure 3.
- (7) Individual licensees have indicated an interest in meeting directly with the staff regarding the Bulletin items for their facilities. Experience to date has demonstrated that the staff does not have time to meet individually with each licensee to resolve these items.

It is clear that there are a significant number of technical issues yet to be resolved for a large number of Westinghouse operating plants. There are limited resources available within the NRC staff to perform the necessary work. This situation is exacerbated by the need to conduct similar and concurrent activities with those owners of B&W, C-E, and GE designed operating plants. At the same time, there is a need to resolve these matters promptly.

To resolve the issues described above in a prompt and expeditious manner, we believe there is a compelling need to establish an owner's group for Westinghouse operating plants. We expect that such a group would be needed for the remainder of calendar year 1979. Owner's groups have worked effectively in the past in minimizing staff and industry resource requirements to resolve other generic problems. We strongly urge you to meet with other owners of Westinghouse operating plants to consider the formation of such a group prior to our meeting on May 30. This will be one of the principal agenda items at that meeting.

N H . . · . •

Mr. John Tillinghast
Indiana and Michigan Electric Co.
Indiana and Michigan Power Co. - 3 -

Please note that investigation of a number of areas related to the TMI-2 accident, including the long-term ACRS recommendations and long-term action items from NUREG-0560, will be specifically included as part of the future "Lessons Learned" staff activity. You can expect additional correspondence in the future on these items.

If you require any clarification of the matters discussed in this letter please contact Patrick D. O'Reilly, the staff's assigned project manager for these activities on Westinghouse plants. Mr. O'Reilly may be reached on (301) 492-7745.

Sincerely,

A. Schwencer, Chief

Operating Reactors Branch #1
Division of Operating Reactors

Enclosures: As Stated

cc: w/enclosures

See next page

o • . * ٠ * 4, ø Mr. John Tillinghast
Indiana and Michigan Electric Company
Indiana and Michigan Power Company

cc: Mr. Robert W. Jurgensen Chief Nuclear Engineer American Electric Power Service Corporation 2 Broadway New York, New York 10004

> Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 1800 M Street, N.W. Washington, D. C. 20036

David Dinsmore Comey Executive Director Citizens for a Better Environment 59 East Van Buren Street Chicago, Illinois 60605

Maude Reston Palenske Memorial Library 500 Market Street St. Joseph, Michigan 49085

Mr. D. Shaller, Plant Manager Donald C. Cook Nuclear Plant P. O. Box 458 Bridgman, Michigan 49106

Kenneth R. Baker 2874 Robin Hood Drive Stevensville, Michigan 49127 8.4. 3.6.m. Late, WA. Lea. What's delice a parel (second second s

į

DMB/LER



DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

June 18, 1981

Mr. J.G. Keppler, Regional Director Office of Inspection and Enforcement United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Operating License DPR-74 Docket No. 50-316

Dear Mr. Keppler:

Enclosed please find a Licensee Event Report that exceeds the 10 day time limit reporting requirement. On June 18, 1981, we advised your Senior Resident Inspector, Mr. E.R. Swanson, of this delay.

Sincerely,

D.V. Shaller Plant Manager.

/bab

cc: J.E. Dolań

R.S. Hunter

R.W. Jurgensen

R.F. Kroeger

K.J. Vehstedt

E. Swanson/N. DuBry RO:III

R.C. Callen MPSC

G. Charnoff, Esq.

J.M. Hennigan

W. Lavallee EPRI

PNSRC

J.F. Stietzel

E.L. Townley

Dir., IE (30 copies)

Dir., MIPC (3 copies)

ρδ/9 4

W

1 v

الراء ال

•,

, • 1 **5.** n • • $\mathbf{x} = q_0 = q_0$ ľ J . 9

SUPPLEMENT TO RO 50-316/81-020/04T-0

During normal operation the steam generator startup blowdown flash tank was in service to reduce secondary system chemical contamination. Flow through radiation monitor R-19 had been previously verified. Routine technician surveillance at 1415 hrs noted the absence of flow. By rapidly cycling the valves full open and shut, the lines were blown out and flow reestablished immediately. Leaving the area to notify control room of the situation would have resulted in a longer time period of unmonitored release. Blowdown had been on the startup flash tank since 1340 hrs. The maximum time the unmonitored release could have existed was 35 minutes.

Daily analysis to monitor the primary to secondary leak on Unit 2 had been completed and all parameters were within limits for release via the startup flash tank. A grab sample at the blowdown flash tank was taken at 1415 hrs and analyzed and showed secondary system activities had not significantly changed since the previous analysis.

<u>Time</u>	<u>Sample</u>	Tritium(μCi/cc)	Gross β-γ(μCi/cc)	<u>Iodine-131(μCi/cc</u>)
0015 0015 0015 0015 1415	#21 S/G #22 S/G #23 S/G #24 S/G 2-DSX-350 (flash tank composite)	2.52 x 10 ⁻⁶ 2.74 x 10 ⁻⁶ 3.58 x 10 ⁻⁶ 2.42 x 10 ⁻⁶ 5.21 x 10 ⁻⁶	4.38 x 10 ⁻⁵ 1.67 x 10 ⁻⁵ 1.54 x 10 ⁻⁵ 1.06 x 10 ⁻⁵ 4.46 x 10 ⁻⁶	6.43 × 10 ⁻⁷ 2.89 × 10 ⁻⁷ N.D. 2.75 × 10 ⁻⁷ 5.81 × 10 ⁻⁷

Using the 1415 steam generator blowdown flash tank composite analysis of the following releases were calculated:

	•	Release Rate	<u>Total Release</u>
Tritium	2.48 x $10^{-9}\mu\text{Ci/cc/sec}$	2.29 x 10 ⁻¹¹ Ci/sec	4.81×10^{-8} Ci
Gross β-γ	2.12 x $10^{-9}\mu\text{Ci/cc/sec}$	1.96 x 10 ⁻¹¹ Ci/sec	4.11×10^{-8} Ci
Iodine-131	2.77 x $10^{-10}\mu\text{Ci/cc/sec}$	2.55 x 10 ⁻¹² Ci/sec	5.36×10^{-9} Ci

A design change, RFC-12-1825, is currently being engineered which will provide an immediate loss of flow warning to the Operations control room, whenever flow to R-19 is interrupted.

15

Carat .

y.

DMB /LER



DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

June 19, 1981

Mr. J.G. Keppler, Regional Director Office of Inspection and Enforcement United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Operating License DPR-74 Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 81-021/03L-0.

Sincerely,

D.V. Shaller Plant Manager

/bab

cc: J.E. Dolan

R.S. Hunter

R.W. Jurgensen

R.F. Kroeger

K.J. Vehstedt

E. Swanson/N. DuBry RO:III

R.C. Callen MPSC

G. Charnoff, Esq.

J.M. Hennigan

W. Lavallee EPRI

PNSRC

J.F. Stietzel

E.L. Townley

Dir., IE (30 copies)

Dir., MIPC (3 copies)

pols 4

1JUN 2 2 1981

No. of the second secon

(7-77) LICENSEE EVENT REPORT	
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
0 1 M I D C C 2 2 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5)
CON'T 0 1 SOURCE L 6 0 5 0 0 0 3 1 6 7 0 5 2 3 8 1 8 0 6 1 9 8 1 9 7 8 75 REPORT DATE 80 9 1 1 1 1 1 1 1 1 1)
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) FOLLOWING A TRIP OF THE UNIT 2 REACTOR, FEEDWATER ISOLATION VALVES FOR #1 AND #4	
STEAM GENERATOR (FMO-201 AND FMO-204), FAILED TO CLOSE UPON RECEIPT OF A FEEDWATER	
ISOLATION SIGNAL. THIS CONDITION WAS NON-CONSERVATIVE WITH REGARDS TO TECHNICAL	
O 5 SPECIFICATION 3.3.2.1.	
06	
07	
7 8 9	80
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO	
SEQUENTIAL OCCURRENCE REPORT REVISION	
NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONEN TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURE	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) TIO THE CAUSE FOR THE FAILURE OF THE FEEDWATER ISOLATION VALVES, FMO 201 and 204 WAS DU	JE I
TO THE MISALIGNMENT OF THE SWITCH ACTUATING ARM ON REACTOR RYPASS BREAKER A. CAUSIN	
	<u></u>
THE SWITCH TO STAY IN THE OPEN POSITION. THIS SWITCH, IN SERIES WITH SWITCHES ON	<u></u>
REACTOR TRIP BREAKER A, SUPPLY THE "REACTOR IS TRIPPED" SIGNAL TO TRAIN A SSPS FOR	
FEEDWATER ISOLATION. (SEE ATTACHED SUPPLEMENT)	80
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32 NA LA 3 OPERATOR OBSERVATION	
7 8 9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA NA	80
7 8 9 10 11 44 45 PERSONNEL EXPOSURES	80
1 7 0 0 0 37 Z 38 NA	80
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA	
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE _ DESCRIPTION	80
1 9 Z 42 NA NA	80
PUBLICITY ISSUED DESCRIPTION 45 NA NRC USE ONLY NA NA	90 17. 17. 82 84.7.18
7 8 9 10 68 69 616-465-5901 PHONE: 616-465-5901	- 0 0 0 80 %

. 1

ATTACHMENT TO LER #81-021/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE SWITCH LINKAGE WAS REALIGNED, AND FUNCTIONALLY TESTED AND THE SYSTEM RETURNED TO OPERATION. NO FURTHER ACTION IS PLANNED.

A Commence of the Commence of

15 . .

•

.

.