REGULATOR NFORMATION DISTRIBUTION STATEM (RIDS)

ACCESSION NBR:8405080149 DOC.DATE: 84/05/04 NOTARIZED: NO DOCKET # FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316 AUTH.NAME AUTHOR AFFILIATION ALEXICH.M.P. Indiana & Michigan Electric Co. RECIP.NAME RECIPIENT AFFILIATION

DENTON, H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Forwards Exxon Nuclear Co 840416 explanation of statements re rod bow.Cycle 4 SER indicated that evaluation of rod bow & rod power should be made to if peaking factor limits need be adjusted.

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR \_\_ ENCL \_\_ SIZE:\_\_\_\_\_ TITLE: OR Submittal: General Distribution

NOTES:

|           | RECIPIENT<br>ID CODE/NAM<br>NRR ORB1 BC |          | COPIE<br>LTTR<br>7 |             | RECIPIENT<br>ID CODE/NAM                          | 1E       | COP:<br>LTTR | IEŞ<br>Encl |
|-----------|-----------------------------------------|----------|--------------------|-------------|---------------------------------------------------|----------|--------------|-------------|
| INTERNAL: | ELD/HDS3<br>NRR/DL DIR<br>NRR/DSI/METB  | 04       | 1<br>1<br>1        | 0 1 1 1     | NRR/DE/MTEB<br>NRR/DL/ORAB<br>NRR/DSI/RAB<br>RGN3 | 4        | 1 1 1 1      | 1<br>0<br>1 |
| EXTERNAL  | ACRS<br>NRC PDR<br>NTIS                 | 09<br>02 | 6<br>1<br>1        | 6<br>1<br>1 | LPDR<br>NSIC                                      | 03<br>05 | 1            | 1<br>1      |

аларана алараана алар Алараана алар Алараана алар Алараана ал

|        |   |     | Б    |   |                  |   |   | 1 |     |   | a be |   |   |
|--------|---|-----|------|---|------------------|---|---|---|-----|---|------|---|---|
| 3 · A' | y |     |      |   |                  |   |   |   | .,  |   | 15 P |   |   |
|        |   | 2.1 | 8 14 | k | 1 <sup>2</sup> # | ¥ | 0 |   | a i | r |      | n | + |
| · ·    |   |     |      |   |                  |   |   |   |     |   |      |   |   |
|        |   |     |      |   |                  |   |   |   |     |   |      |   |   |

|            |     |  |   | 1 |
|------------|-----|--|---|---|
| <b>3</b> 1 | ,   |  |   |   |
|            | я́. |  |   |   |
|            |     |  | А |   |

| и  |   | 11 <b>H</b>                         | F | 1 No. 1 |  |
|----|---|-------------------------------------|---|---------|--|
|    | н | <b>1</b> , <sup>11</sup> <b>1</b> , |   | 1       |  |
| N. | à | N N                                 |   | h. 14   |  |
|    | 1 |                                     |   |         |  |
|    | * |                                     |   |         |  |
|    |   |                                     |   |         |  |

**1** P 1. **X** 

· A +

-

## INDIANA & MICHIGAN ELECTRIC COMPANY

P.O. BOX 16631 COLUMBUS, OHIO 43216

> May 4, 1984 AEP:NRC:0860E

Donald C. Cook Nuclear Plant Unit No. 2 Docket No. 50-316 License No. DPR-74 CYCLE 5 SAFETY ANALYSIS REPORT

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Denton:

The Cycle 4 Safety Evaluation Report (SER) indicated that an evaluation of rod bow and rod power should be made to determine if DNBR or peaking factor limits need to be adjusted to account for fuel rod bowing. During the course of our review of the Cycle 5 Safety Analysis Report (SAR), Exxon Nuclear Company (ENC) was asked to further explain the statements with respect to rod bow. We mentioned to Mr. D. Wigginton on April 6, 1984 that we would be clarifying the SAR statements on rod bow after receiving confirmation from ENC. We are attaching a copy of a letter on the subject from ENC for this purpose.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to insure its accuracy and completeness prior to signature by the undersigned.

Very truly yours,

M.P. Alexich (0) 80 Vice President 5130

Attachment bjs

cc: John E. Dolan W.G. Smith, Jr. - Bridgman R.C. Callen G. Charnoff E.R. Swanson, NRC Resident Inspector - Bridgman

05000316

8405080149 84050

PDR ADOCK

## EXON NUCLEAR COMPANY, Inc.

600 - 108th Avenue N.E., C-00777, Bellevue, Washington 98009, Telephone (206) 453-4300

April 16, 1984 ENC-AEP/0343

Mr. George John, Sr. Engineer 'APR 2 3 1984. Nuclear Materials & Fuel Management Indiana & Michigan Electric Company c/o American Electric Power Service Corp. One Riverside Plaza Columbus, OH 43215

Dear George:

- Subject: Supplemental Information to D. C. Cook 2, Cycle 5 Safety Analysis. Report Regarding Effect of Rod Bow on DNB Margins
- Ref: 1) XN-NF-83-85, Supp. 1, Rev. 1, "D. C. Cook Unit 2, Cycle 5 Safety Analysis Report," March 15, 1984
  - 2) XN-NF-75-32(P)(A), Supps. 1, 2, 3 & 4, "Computational Procedure for Evaluating Fuel Rod Bowing," October 1983
  - 3) XN-NF-82-32(P), Rev. 2, "Plant Transient Analysis for the Donald C. Cook Unit 2 Reactor at 3425 MWt: Operation with 5% Steam Generator Tube Plugging," February 1984

Exxon Nuclear has reanalyzed the effect of rod bow on DNB margin during the D. C. Cook Unit 2, Cycle 5. The effects were analyzed in accordance with the NRC Staff SER and Exxon Nuclear methodology (Reference 2). The results of the analysis show that no fuel assembly is expected to experience DNBR less than that reported (Reference 3) during Cycle 5. The analysis showed that the reduction in fuel assembly power due to burnup more than compensates for the effects of rod bow to EOC5.

Very truly yours, Н. Shaw

Contract Administrator

tlm

- c: M. P. Alexich
  - J. M. Cleveland W. L. Zimmermann

AFFILIATE OF EXXON CORPORATION