

SUPPLEMENT TO LER # 79-067/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

BEEN USED FOR THESE DETECTORS HAD SIGMAS OF 0.6 PERCENT AND 1.1 PERCENT RESPECTIVELY. DURING THIS TIME THE THIMBLES SELECTED FOR DETECTORS 3 AND 4 WERE CORRECT. THEREFORE, ONE APPROPRIATE DETECTOR WAS ALWAYS BEING USED TO MONITOR CORE PERFORMANCE.

THE PROBLEM WAS DISCOVERED IN 2½ HOURS AND F_z RECALCULATED USING THE CORRECT THIMBLES. THE F_z MARGINS WERE REDUCED FROM +15.9 PERCENT TO +14.5 PERCENT AND +17.4 PERCENT TO 15.5 PERCENT FOR DETECTORS 1 AND 2 RESPECTIVELY.

THIS ERROR WAS DISCUSSED WITH THE INDIVIDUAL INVOLVED AND A TRAINING SESSION WAS CONDUCTED WITH ALL SECTION PERSONNEL IN ORDER TO PREVENT A REOCCURRENCE.

