

CENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 58 80  
 0 1 | M I D C C | 2 | 0 0 0 0 | 0 0 0 0 0 0 0 | 4 1 1 1 1 | 4 | 5  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
 7 8 60 61 68 69 74 75 80  
 0 1 | L | 0 5 0 0 0 3 1 6 | 0 3 2 1 8 0 | 0 4 1 8 8 0 | 9  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

0 2 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 DURING NORMAL OPERATION, THE TDAFP TRIP AND THROTTLE VALVE TRIPPED AND COULD  
 0 3 | NOT BE RESET. THIS RENDERED THE TDAFP INOPERABLE FOR A PERIOD OF 14 HOURS.  
 0 4 | THIS EVENT DID NOT MEET THE AFW PUMP OPERABILITY REQUIREMENTS OF T.S. 3.7.1.2.  
 0 5 |  
 0 6 |  
 0 7 |  
 0 8 |

7 8 9 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47 80  
 0 9 | C H | E | B | T U R B I N | Z | Z |  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 17 LER/RO REPORT NUMBER 8 0 |  
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
 0 1 7 | 0 3 | L | 0 |  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
 E F | Z | Z | 0 0 0 0 | Y | Y | A | T I I 4 7 |  
 18 19 20 21 22 23 24 25 26

1 0 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 INVESTIGATION REVEALED THAT THE RESET SOLENOID WAS DEFECTIVE. THE COILS WERE  
 1 1 | REPLACED, BUT THIS SET OF COILS DID NOT FUNCTION PROPERLY ETIHER. THE TRIP LINKAGE  
 1 2 | WAS MANUALLY RESET AND THE TDAFP WAS TESTED AND DETERMINED OPERABLE. FINAL REPAIRS  
 1 3 | INCLUDED THE COIL REPLACEMENT AND A LINKAGE ADJUSTMENT TO ALLOW THE SOLENOID  
 1 4 | TO SEAT PROPERLY. SEE ATTACHMENT SUPPLEMENT

7 8 9 10 12 13 44 45 46 80  
 1 5 | E | 1 0 0 | NA | A | OPERATIONAL EVENT  
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
 28 29 30 31 32

7 8 9 10 11 12 13 44 45 80  
 1 6 | Z | Z | NA | NA | NA  
 ACTIVITY CONTENT RELEASER OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
 33 34 35 36

7 8 9 11 12 13 80  
 1 7 | 0 0 0 | Z | NA  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
 37 38 39

7 8 9 11 12 80  
 1 8 | 0 0 0 | NA  
 PERSONNEL INJURIES NUMBER DESCRIPTION  
 40 41

7 8 9 11 12 80  
 1 9 | Z | NA | 8004230357  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
 42 43

7 8 9 10 80  
 2 0 | N | NA  
 PUBLICITY ISSUED DESCRIPTION  
 44 45

NAME OF PREPARER: J. L. Rischling PHONE: 616-465-5901



100

ATTACHMENT TO LER # 80-017/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

AN ENGINEERING REVIEW IS PRESENTLY IN PROGRESS ON THE TRIP -  
MECHANISM DESIGN.



100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000