

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D I C C | 2 | 0 0 0 0 0 0 0 0 0 0 0 0 | 3 | 4 1 1 1 1 | 4 | | | 5

0 1 | REPORT SOURCE | L | 0 5 0 0 0 3 1 6 | 7 | 0 4 1 1 8 0 | 8 | 0 5 0 6 8 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | DURING A RAPID POWER REDUCTION TO REMOVE THE WEST MAIN FEED PUMP FROM SERVICE BECAUSE
0 3 | OF A FAULTY COUPLING, THE AXIAL FLUX DIFFERENCE WAS FORCED OUT OF THE +/- 5% TARGET
0 4 | BAND DEFINED IN T. S. 3.2.1 FOR A PERIOD OF SIXTEEN MINUTES.
0 5 | PREVIOUS OCCURRENCES INCLUDE: 50-315/79-002, 79-006; 50-316/79-013.

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | THE RAPID POWER REDUCTION IN ANTICIPATION OF LOSS OF THE WEST MAIN FEED PUMP DUE TO
1 1 | COUPLING FAILURE WAS ACCOMPLISHED CHIEFLY BY CONTROL ROD INSERTION. THIS FORCED THE
1 2 | AXIAL FLUX DIFFERENCE OUTSIDE THE DESIGNATED TARGET BAND. THE AFD REACHED A MAXIMUM
1 3 | OF - 9% WHICH IS WITHIN THE LIMITS SHOWED ON T. S. FIGURE 3.2-1. THE AFD WAS RETURNED
1 4 | TO THE TARGET BAND BY BORATION OF THE RCS TO PERMIT CONTROL ROD ADJUSTMENT.

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
1 6 | ACTIVITY TAKEN | CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
1 7 | PERSONNEL EXPOSURES NUMBER | TYPE | DESCRIPTION
1 8 | PERSONNEL INJURIES NUMBER | DESCRIPTION
1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | DESCRIPTION
2 0 | ISSUED | DESCRIPTION

NAME OF PREPARER: H. M. CHADWELL PHONE: 616-465-5901 X1316



Handwritten scribbles or marks in the top right corner.

78