

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104170533 DOC DATE: 81/04/10 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH NAME: RISCHELM, J. L. AUTH AFFILIATION: Indiana & Michigan Electric Co.
 RECIP NAME: REGION 3, Chicago, Office of the Director

SUBJECT: LER 81-001/04L-0: on 810313 & 0224, unplanned & unsampled radioactive gases found released. Caused by excessive leakage from reciprocating charging pump stuffing box & leaking isolated gas decay tank valves.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 143
 TITLE: Incident Reports

NOTES: I&E: 3 copies all material. 05000315

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	VARGA, S.	04	3 3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J, HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR ENGINEER120	1	1
	DIR HUM FAC S21	1	1	DIR SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OP EX EVAL BR34	3	3	OR ASSESS BR 35	1	1
	POWER SYS BR 36	1	1	RAD ASSESS BR39	1	1
	REACT SYS BR 40	1	1	<u>REG FILE</u> 01	1	1
	REL & RISK A 41	1	1	SFTY PROG EVA42	1	1
	STRUCT ENG BR44	1	1	SYS INTERAC B45	1	1
EXTERNAL:	ACRS	46	16 16	LPDR	03	1 1
	NSIC	05	1 1			

APR 20 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 68 ENCL 68

HA



[The text in this section is extremely faint and illegible due to the quality of the scan. It appears to be a list or a series of entries.]



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

DLB

April 10, 1981

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix B Technical Specifications
the following report/s are submitted:

RO 81-001/04L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
W. Lavalley EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (20 copies)
Dir., MIPC (2 copies)
Directorate of Licensing

APR 16 1981



12

62

ATTACHMENT TO LER #81-001/04L-0SUPPLEMENT TO CAUSE DESCRIPTION

INVESTIGATION REVEALED THAT AT 2330 ON 02-23-81 R-26 (VENT RADIOGAS MONITOR) BEGAN INCREASING AND AT 0310 ON 02-24-81 A HIGH ALARM WAS RECEIVED ON R-26. IT WAS DETERMINED THAT THE CAUSE OF THE ALARM WAS THE LEAKAGE FROM THE RECIPROCATING CHARGING PUMP. THE PUMP WAS TAKEN OUT OF SERVICE AT 0308 DUE TO EXCESSIVE LEAKAGE AT THE STUFFING BOX. THE RECORDER INDICATES THAT R-26 STARTED DECREASING AFTER THE RECIPROCATING CHARGING PUMP WAS REMOVED FROM SERVICE. THE STUFFING BOX OF THE CHARGING PUMP DRAINS TO THE CLEAN SUMP TANK WHICH IS VENTED TO THE AUXILIARY BUILDING VENTILATION SYSTEM.

RELEASE CALCULATIONS

RELEASE KNOWN TO BE FRESH GAS, 1.041 Ci OF Xe-133 WAS RELEASED AT A RATE OF 7.23 E-5 Ci PER SECOND. THIS IS .1215% OF THE NOBLE GAS TECHNICAL SPECIFICATION LIMITS. THE MAXIMUM RELEASE RATE WAS DETERMINED TO BE 7.348 E-4 Ci PER SECOND OR 1.235% OF THE NOBLE GAS TECHNICAL SPECIFICATION LIMIT.

THIS EVENT WAS DETERMINED TO BE REPORTABLE ON 03-23-81, FOLLOWING A REVIEW OF THE INVESTIGATION REPORT AND DISCUSSION WITH THE NRC RESIDENT INSPECTOR.

THE SECOND UNPLANNED RELEASE OCCURRED WHEN NO. 3 GAS DECAY TANK (GDT) WAS ISOLATED FOR GAS DECAY PURPOSES ON 02-03-81 AT 97 PSIG. ON 03-13-81 TANK PRESSURE WAS FOUND TO BE 53 PSIG. THE REMAINDER OF THIS GDT WAS RELEASED ON 03-13-81 TO ALLOW FOR THE REPAIR OF THE ISOLATION VALVES, MANUFACTURED BY GRINNEL-DRAWING NO. WREF-3-CS. THE VALVE DIAPHRAMS WERE REPLACED AND THE GDT WAS RETURNED TO SERVICE. EXAMINATION OF THE DIAPHRAMS WHICH

12-2-57

WERE REMOVED, REVEALED INDENTATIONS, WHICH MAY HAVE PROVIDED A LEAKAGE PATH FOR THE GAS. THIS GAS DECAY TANK WAS ONE OF TWO RECENTLY INSTALLED FOR RFC 12-2196.

RELEASE CALCULATIONS

Xe-133	2.73 E-4	μCi/cc
Xe-131M	7.84 E-5	μCi/cc
Kr-85	9.17 E-4	μCi/cc
I-133	2.82 E-9	μCi/cc

FOR A TOTAL OF $6.74 \times E-2$ TOTAL CURIES AT $5.12 \times E-5\%$ OF TECHNICAL SPECIFICATION LIMITS FOR NOBLE GASSES AND $1.51 \times E-4$ CURIES OF IODINE 133 AT $6.86 \times E-7\%$ OF TECHNICAL SPECIFICATIONS.

THESE RESULTS ARE BASED ON ANALYSIS PERFORMED 3-13-81 ON THE REMAINDER OF THE TANK. SINCE IT HAD BEEN "ISOLATED" IT IS ASSUMED ONLY OUTLEAKAGE OCCURRED AND NO INLEAKAGE INTO THE TANK. AN ADDITIONAL LEAK TEST WAS ALSO PERFORMED ON THE OTHER GDT RECENTLY INSTALLED, TO INSURE SIMILAR PROBLEMS DID NOT EXIST WITH THE ISOLATION VALVES. IN THE FUTURE, SIMILAR UNPLANNED RELEASES SHOULD BE DETECTED QUICKLY AS OPERATIONS DEPARTMENT HAS MODIFIED PLANT PROCEDURES REQUIRING A CLEARANCE TAG ON THE GDT'S WHEN EACH IS ISOLATED FOR DECAY PURPOSES, AND THE PRESSURE INDICATION FOR THE ISOLATED TANK IS MARKED SUCH THAT ANY DECREASE IN GDT PRESSURE IS EASILY IDENTIFIABLE.

15