

ACCELERATED. DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8905240545 DOC. DATE: 89/05/16 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 SMITH, W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION
 DAVIS, A.B. Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890409, several fire barrier penetration seals inoperable longer than 7 days. R
I

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 D
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. S

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	
	PD3-1 LA	1		1	PD3-1 PD	1		1	A
	STANG, J	1		1					D
INTERNAL:	ACRS MICHELSON	1		1	ACRS MOELLER	2		2	D
	ACRS WYLIE	1		1	AEOD/DOA	1		1	
	AEOD/DSP/TPAB	1		1	AEOD/ROAB/DSP	2		2	S
	DEDRO	1		1	IRM/DCTS/DAB	1		1	
	NRR/DEST/ADE 8H	1		1	NRR/DEST/ADS 7E	1		0	
	NRR/DEST/CEB 8H	1		1	NRR/DEST/ESB 8D	1		1	
	NRR/DEST/ICSB 7	1		1	NRR/DEST/MEB 9H	1		1	
	NRR/DEST/MTB 9H	1		1	NRR/DEST/PSB 8D	1		1	
	NRR/DEST/RSB 8E	1		1	NRR/DEST/SGB 8D	1		1	
	NRR/DLPQ/HFB 10	1		1	NRR/DLPQ/QAB 10	1		1	
	NRR/DOEA/EAB 11	1		1	NRR/DREP/RPB 10	2		2	
	NUDOCS-ABSTRACT	1		1	REG FILE 02	1		1	
	RES/DSIR/EIB	1		1	RES/DSR/PRAB	1		1	
	RGN3 FILE 01	1		1					
EXTERNAL:	EG&G WILLIAMS, S	4		4	FORD BLDG HOY, A	1		1	R
	L ST LOBBY WARD	1		1	LPDR	1		1	
	NRC PDR	1		1	NSIC MAYS, G	1		1	I
	NSIC MURPHY, G.A	1		1					D

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 42

JA

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



May 16, 1989

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315, 50-316
License Nos. DPR-58, DPR-74

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

ATTN: A.B. Davis

Dear Mr. Davis:

This special report is being submitted in accordance with Technical Specification 3.7.10 Action a, to inform you that several fire barrier penetration seals have been inoperable longer than the seven days allowed by Technical Specification 3.7.10 Action a.

Fire Barrier Penetration Seals F-6714 and F-6706 separate the Unit 2 Control Room and Unit 2 Control Room Cable Vault. Fire Seal F-6714 was declared inoperable on April 9, 1989, and returned to service on May 2, 1989. Fire Seal F-6706 was declared inoperable on April 11, 1989, and returned to service on April 23, 1989. Fire watches, as required by Technical Specification 3.7.10 Action a, were maintained while the seals were inoperable.

The fire seal under Motor Control Center 1 AMD (fire seal not numbered) in the Unit 1 Auxiliary Building was declared inoperable on April 19, 1989, and returned to service on April 28, 1989. A fire watch, as required by Technical Specification 3.7.10 Action a, was maintained while the seal was inoperable.

The TSI fire retardant material was removed from conduit 98676-1 and electrical pull box B-41 in the Unit 1 ESW Pump Room on April 17, 1989. The TSI was reapplied on April 26, 1987. TSI is a fire retardant material applied to specified cable trays and conduits for Appendix R purposes. A fire watch, as required by Technical Specification 3.7.10 Action a, was maintained while the TSI material was removed.

Fire Door 346 was declared inoperable on April 14, 1989, when it failed to close completely during routine testing. Following repair the door was returned to operable status on April 26, 1989. A fire watch, as required by Technical Specification 3.7.10 Action a, was maintained while the door was inoperable.

8905240545 890516
PDR ADOCK 05000315
S PDC

JE22
1/1

Mr. A.B. Davis
May 16, 1987
Page 2

Fire Doors 349, 371 and 347 in the Unit 1 4KV complex and 350 and 472 in the Unit 2 4KV complex were declared inoperable on April 14, 1989, as the result of an adverse trend of fire doors failing to close from the open position during CO2 system testing. A fire watch, as required by Technical Specification 3.7.10 Action a, was established at that time and will remain in effect until the problems can be resolved. Engineering evaluations are under way to determine a permanent resolution. We will notify you when a schedule for completion can be determined.

In a letter dated October 29, 1988, we informed you that Fire Door 371, separating the New Containment Access Building and the Aux Building Crane Bay, was inoperable. Following extensive reworking of the door frame and the door hardware, the door was returned to service on April 26, 1989.

Respectfully,



W.G. Smith, Jr.
Plant Manger

c: D.H. Williams, Jr.
A.B. Davis, Region III
M.P. Alexich
P.A. Barrett
J.E. Borggren
R.F. Kroeger
NRC Resident Inspector
J.F. Stang
R.C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
PNSRC
A.A. Blind
S.J. Brewer/B.P. Lauzau