



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

October 2, 1991

Docket Nos. 50-315  
and 50-316

Mr. Gene E. Fitzpatrick, Vice President  
Indiana and Michigan Power Company  
c/o American Electric Power Service Corporation  
1 Riverside Plaza  
Columbus, Ohio 43216

Dear Mr. Fitzpatrick:

SUBJECT: THIMBLE TUBE WALL THINNING ROOT CAUSE D.C. COOK UNITS 1 AND 2  
(TAC NOS. 80117 AND 80118)

Members of your staff and your contractors met with the NRC on April 11, 1991 to discuss the root cause of the thimble tube wear and resultant leakage which occurred at D.C. Cook Nuclear Plant Unit 2 on June 18, 1990. Previous leakages occurred at Unit 1 in 1983 and 1988. The results of the meeting are contained in meeting minutes dated April 23, 1991 and May 7, 1991. The staff had previously met with members of your staff and your contractors on August 29, 1990. Results of that meeting are contained in meeting summaries dated September 13 and October 10, 1990. At the most recent meeting you committed to provide the staff with the results of metallurgical examinations of two (2) of Unit 2s defective thimble tubes which included surface examination, metallographic examination, detailed wear morphology evaluations, and hardness measurements. You provided this information by letter dated July 15, 1991, AEP:NRC:1059C, with attachment MT-MNA-035 (91), "Metallurgical Investigation of Wall Thinning and Leakage of the BMI Thimble Tubing at D.C. Cook Unit 2", dated January 1991, which contained the results of the Westinghouse hot cell laboratory analysis.

The primary cause attributed to the thimble tube wear as described in your report appears to be flow-induced vibration. There appeared to be relatively low impact loads involved with two different types of wear conditions depending on location and depth of the wear suggesting varying degrees of displacement, contact loads and fluid jetting conditions along the length of the thimble tubes at the nozzle penetration.

We have reviewed your consultant's report and your corrective actions as described during the April 11, 1991 meeting. This includes the repositioning and replacement of thimble tubes, as necessary, during the upcoming 1992 refueling outages for D.C. Cook Units 1 and 2. Additionally, you described your intention to chrome plate replacement thimble tubes to enhance the wear resistance. You further described your inspection plans including base line

9110210157 911002  
PDR "ADOCK" 05000315  
P PDR

NRC FILE CENTER COPY

*APOL*  
*110*  
*M/A*

7-11-68



100-100000-100000

RECEIVED  
FEDERAL BUREAU OF INVESTIGATION  
U. S. DEPARTMENT OF JUSTICE  
WASHINGTON, D. C. 20535

100-100000-100000

Mr. Gene Fitzpatrick

-2-

October 2, 1991

eddy current examinations and additional eddy current examinations after one cycle of operation to quantify the benefit of the wear resistant design features and to determine if addition hardware fixes may be warranted. We understand that you do not intend any lower core plate and fuel assembly lower nozzle modifications at this time and that pending your eddy current results after one cycle of operation with new thimble tubes, these may be reevaluated. We also understand that as described by your staff, you have the capability to isolate leaking thimble tubes should they occur during the remainder of the operating cycle or during future operating cycles and that procedures are in place and training has been completed for performing this evolution, if necessary.

Based on the above discussion, we consider your actions responsive to the staff concerns in this area and consider this item closed for your facilities. Please keep us apprised of new developments or inspection findings, particularly if they shed any more light on the perceived "accelerated" wear aspects of the thimble tube thinning.

Sincerely,

Original signed by

Timothy G. Colburn, Sr. Project Manager  
Project Directorate III-1  
Division of Reactor Projects III, IV, V  
Office of Nuclear Reactor Regulation

cc w/enclosures:  
See next page

DISTRIBUTION

|                        |                  |
|------------------------|------------------|
| <del>Docket File</del> | NRC & Local PDRs |
| PD #3-1 Reading file   | BBoger           |
| JZwolinski             | PShuttleworth    |
| TColburn               | OGC              |
| EJordan MNBB-3701      | ACRS (10)        |
| DC Cook plant file     | BClayton RIII    |
| JNorberg 7D2           | SHou 7E23        |
| TChan 7E23             |                  |

|      |                |             |           |            |   |
|------|----------------|-------------|-----------|------------|---|
| OFC  | :LA/PDIII-1    | :PM/PDIII-1 | :EMEB     | :D/PDIII-1 | : |
| NAME | :PShuttleworth | :TColburn   | :JNorberg | :LBMarsh   | : |
| DATE | :10/2/91       | :10/2/91    | :10/2/91  | :10/2/91   | : |

OFFICIAL RECORD COPY  
Document Name: LTR MR. FITZPATRICK

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by proper documentation and that the books should be kept up to date at all times.

In the second section, the author provides a detailed explanation of the double-entry system. This method ensures that every debit entry is balanced by a corresponding credit entry, which helps in detecting errors and maintaining the integrity of the accounting system.

The third section covers the process of closing the books at the end of each accounting period. This involves transferring the balances of temporary accounts to permanent accounts and ensuring that the ledger is ready for the start of the next period.

Finally, the document concludes by highlighting the role of the accountant in providing reliable financial information to management and other stakeholders. It stresses the need for honesty, objectivity, and adherence to professional standards in all accounting activities.

Mr. Gene Fitzpatrick  
Indiana Michigan Power Company

Donald C. Cook Nuclear Plant

cc:

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Mr. S. Brewer  
American Electric Power  
Service Corporation  
1 Riverside Plaza  
Columbus, Ohio 43216

Attorney General  
Department of Attorney General  
525 West Ottawa Street  
Lansing, Michigan 48913

Township Supervisor  
Lake Township Hall  
Post Office Box 818  
Bridgman, Michigan 49106

Al Blind, Plant Manager  
Donald C. Cook Nuclear Plant  
Post Office Box 458  
Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission  
Resident Inspectors Office  
7700 Red Arrow Highway  
Stevensville, Michigan 49127

Gerald Charnoff, Esquire  
Shaw, Pittman, Potts and Trowbridge  
2300 N Street, N.W.  
Washington, DC 20037

Mayor, City of Bridgman  
Post Office Box 366  
Bridgman, Michigan 49106

Special Assistant to the Governor  
Room 1 - State Capitol  
Lansing, Michigan 48909

Nuclear Facilities and Environmental  
Monitoring Section Office  
Division of Radiological Health  
Department of Public Health  
3500 N. Logan Street  
Post Office Box 30035  
Lansing, Michigan 48909