

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9412210135 DOC. DATE: 94/12/12 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH. NAME AUTHOR AFFILIATION
 MOREY, D.O. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 BLIND, A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 94-011-00: on 941028, missed liquid effluent batch release sample compositing analysis surveillance due to lack of adequate counting room program oversight. Current liquid release procedures have been revised. W/941212 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME	LTR	ENCL	
	PD3-1 PD		1	1	HICKMAN, J	1	1	
INTERNAL:	AEOD/SPD/RAB		2	2	AEOD/SPD/RRAB	1	1	
	EELB CENTER 02		1	1	NRR/DE/ECGB	1	1	
	NRR/DE/EELB		1	1	NRR/DE/EMEB	1	1	
	NRR/DISP/PIPB		1	1	NRR/DOPS/OECB	1	1	
	NRR/DRCH/HHFB		1	1	NRR/DRCH/HICB	1	1	
	NRR/DRCH/HOLB		1	1	NRR/DRSS/PRPB	2	2	
	NRR/DSSA/SPLB		1	1	NRR/DSSA/SRXB	1	1	
	RES/DSIR/EIB		1	1	RGN3 FILE 01	1	1	
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE, J H	2	2	
	NOAC MURPHY, G.A		1	1	NOAC POORE, W.	1	1	
	NRC PDR		1	1	NUDOCS FULL TXT	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 27

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



December 12, 1994

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by
10 CFR 50.73 entitled Licensee Event Report System, the
following report is being submitted:

94-011-00

Sincerely,

A. A. Blind
Plant Manager

/sb

Attachment

c: J. B. Martin, Region III
E. E. Fitzpatrick
P. A. Barrett
R. F. Kroeger
M. A. Bailey - Ft. Wayne
NRC Resident Inspector
J. B. Hickman - NRC
J. R. Padgett
G. Charnoff, Esq.
D. Hahn
INPO
S. J. Brewer

9412210135 941212
PDR ADOCK 05000316
S PDR

JE 22

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Donald C. Cook Nuclear Plant		DOCKET NUMBER (2) 05000 315	PAGE (3) 1 OF 3
--	--	---------------------------------------	---------------------------

TITLE (4) **Missed Liquid Effluent Batch Release Sample Compositing Analysis Surveillance Due to Lack of Adequate Counting Room Program Oversight**

EVENT DATE (5)			LER NUMBER (6)			REPORT NUMBER (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	28	94	94	011	00	12	12	94	Cook - Unit 2	05000 316
									FACILITY NAME	DOCKET NUMBER
										05000

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)			
POWER LEVEL (10) 100	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	(Specify in Abstract below and in Text, NRC Form 366A)
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
	<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME D. O. Morey - Chemistry Superintendent	TELEPHONE NUMBER (include Area Code) (616) 465-5901 X2502
---	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On October 28, 1994, it was discovered that three of six liquid effluent batch release samples from the month of October could not be located. Technical Specification 4.11.1.1.1 requires that liquid effluent batch release samples be composited on a monthly and quarterly basis. When the samples could not be located, it was assumed that they had been disposed of, and the three available samples were composited and analyzed.

On November 18, 1994, it was determined that the event was reportable under 10CFR50.73(a)(2)(i)(B).

This event resulted from a lack of oversight of the counting room program which resulted in the need to use multiple procedures to complete a single task.

The procedures will be revised to ensure proper retention of the samples for monthly and quarterly compositing.

During the month of October no abnormal operation occurred that would have caused a shift in the normal radionuclide composition of effluents. At no time was the health and safety of the public affected by this event as each liquid effluent batch was sampled and analyzed prior to release and showed no abnormal results.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Donald C. Cook Nuclear Plant	DOCKET NUMBER (2) 0 5 0 0 0 3 1 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 4	- 0 1 1	- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit 1 in Mode 1 at 100% power, Unit 2 shutdown in Mode 5.

Description of Event

On October 28, 1994, Chemistry personnel attempted the compositing and analyses of the liquid effluent batch releases for the month of October, as required by Technical Specification 4.11.1.1.1. It was discovered at this time that three of the six liquid effluent batch release samples from that period could not be located.

The samples are normally stored in the counting room after the batch tank is released, until they are needed for the monthly and quarterly composites. When the samples could not be located, it was concluded that they had been disposed of. The three available samples were then composited and analyzed.

More time was required than was originally anticipated in performing the investigation. In general, a lack of identifiable leads or knowledge of the event inhibited the identification of the root cause. In addition, the radiochemistry performance engineer determined it prudent to investigate for perturbations in the operational history of the units and the radwaste system performance. Nuclide analyses bracketed before and after this event were carefully reviewed to ensure the expected activity was consistent throughout the event period. These investigations culminated in confidence in the Analysis of Event Section. By November 18, 1994, a thorough review of the event had been conducted and the event was determined to be reportable.

Cause of Event

The cause of this event is attributed to deficiencies in the liquid release procedure in that the requirements and direction for compositing the sample are not clearly and coherently defined. In conjunction, a general lack of awareness exists relative to the procedure that does contain compositing requirements. This combination has led to confusion and uncertainty in the Production section about the requirements. Subsequently, some samples were not placed in the designated area which resulted in the inadvertent disposal of three samples prior to satisfying the compositing requirement. Programmatically, the root cause is a lack of adequate oversight in the counting room.

Analysis of Event

This event is being reported in accordance with 10CFR50.73(a)(2)(i)(B) as operation prohibited by the plant's Technical Specifications. Technical Specification 4.11.1.1.1 required that the liquid effluent batch releases be composited and analyzed on a monthly and quarterly basis. The failure to retain all samples for the month of October for compositing is a violation of the Technical Specification surveillance requirements.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Donald C. Cook Nuclear Plant	DOCKET NUMBER (2) 0 5 0 0 0 3 1 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 4	— 0 1 1	— 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Analysis of Event (cont'd)

The pre-release sample results from the batch releases that were not available for compositing were reviewed, as was plant operation and work activities for the month of October. The samples showed no abnormal activity. The review of plant operation and work activities showed nothing unusual during the month of October which would have caused a shift in the normal radionuclide composition. It was concluded that the missing samples were similar in composition to those remaining samples which were available for compositing, and at no time was the health and safety of the public affected by this event.

Corrective Action

The current liquid release procedures have been revised by change sheet to correct the immediate concern. The procedures used for this evolution will be revised to provide effective and coherent guidance for the entire liquid release program, including the compositing requirements. As part of the Chemistry procedure upgrade project, these simplified procedures will be implemented by early March, 1995.

To improve the programmatic oversight in the counting room, the roles of the radiochemistry performance engineer and the counting room supervisor will be clearly defined and documented. This item will be formalized by January 31, 1995. In addition, the management expectation of program ownership was immediately verbally communicated to the department. This item will be formalized by January 31, 1995.

To further improve the radiochemistry program, a self-assessment will be conducted focusing on the human factors aspect of the tasks being performed. This assessment will be completed by June 30, 1995.

Previous Similar Events

- 316/93-010
- 316/93-002
- 315/92-004
- 315/92-013
- 316/91-003

Failed Component Identification

None



100-11111