

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

F I L T P S 3 0 0 1 - 0 0 1 0 1 0 1 0 - 0 0 0 4 1 1 1 1

L I C E N S E E C O D E L 0 5 0 1 5 0 1 0 2 1 5 1 0 0 1 5 0 1 8 1 0 5 2 9 8 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
During cold shutdown, the 3A component cooling water (CCW) pump did not start during routine equipment rotation. The 3B and 3C component cooling water pumps remained in service. This failure resulted in 2 CCW pumps operable. T.S. 3.4.4.1 requires 3 pumps to be operable. Similar occurrences were reported on LERs 250-72-4, 250-73-2, 250-74-2, and 250-78-10.

SYSTEM CODE W B CAUSE CODE E CAUSE SUBCODE A COMPONENT CODE C K T B R K COMP SUBCODE A VALVE SUBCODE Z
LER/RO REPORT NUMBER 8 1 SEQUENTIAL REPORT NO. 0 1 1 0 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
ACTION TAKEN B EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0 0 0 0 ATTACHMENT SUBMITTED N VPRO-FORM SUB. N PRIME COMP SUPPLIER A COMPONENT MANUFACTURER G O 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Operations personnel found the 3A CCW pump circuit breaker in the trip mode. The closing latch spring in the GE Magne-Blast type breaker had detached on one end which prevented the charging of the closing springs. The breaker was repaired and the pump was then started.

FACILITY STATUS G % POWER 0 1 0 0 OTHER STATUS NA METHOD OF DISCOVERY A DISCOVERY DESCRIPTION Equipment rotation

ACTIVITY CONTENT Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 0 TYPE Z DESCRIPTION NA

PERSONNEL INJURIES NUMBER 0 DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

PUBLICITY RELEASED NA NRC USE ONLY

NAME OF PREPARER P. L. Pace PHONE: (305) 552-3801

810608 387

