

1717 Wakonade Drive
Welch, MN 55089

800.895.4999
xcelenergy.com



December 11, 2017

L-PI-17-049
10 CFR 50.73

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Prairie Island Nuclear Generating Plant, Unit 2
Docket No. 50-306
Renewed Facility Operating License No. DPR-60

LER 50-306/2017-002-00, Reactor Coolant System Shutdown Communication Line Vent Through Wall Defect

Northern States Power Company, a Minnesota Corporation (NSPM), doing business as Xcel Energy, hereby submits Licensee Event Report (LER) 50-306/2017-002-00, Reactor Coolant System Shutdown Communication Line Vent Through Wall Defect.

If there is any question or if any additional information is needed, please contact Leonard Sueper, at 612-330-6917.

Summary of Commitments

This letter makes no new commitments and no revisions to existing commitments.

A handwritten signature in black ink, appearing to read 'Scott Northard', written in a cursive style.

Scott Northard
Site Vice President, Prairie Island Nuclear Generating Plant
Northern States Power Company – Minnesota

Enclosure

cc: Administrator, Region III, USNRC
Project Manager, Prairie Island, USNRC
Resident Inspector, Prairie Island, USNRC

ENCLOSURE

Licensee Event Report 50-306/2017-002-00

3 pages follow



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

| | | |
|--|-------------------------------------|--------------------------|
| 1. FACILITY NAME Prairie Island Nuclear Generating Plant | 2. DOCKET NUMBER 05000306 | 3. PAGE 1 OF 3 |
|--|-------------------------------------|--------------------------|

4. TITLE
Reactor Coolant System Shutdown Communication Live Vent Through Wall Defect

| 5. EVENT DATE | | | 6. LER NUMBER | | | 7. REPORT DATE | | | 8. OTHER FACILITIES INVOLVED | |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REV NO. | MONTH | DAY | YEAR | FACILITY NAME | DOCKET NUMBER |
| 10 | 16 | 2017 | 2017 | - 002 | - 00 | 12 | 11 | 2017 | | 05000 |
| | | | | | | | | | FACILITY NAME | DOCKET NUMBER |
| | | | | | | | | | | 05000 |

| | | | | | | | | | | | | |
|-----------------------------------|--|--|--|---|--|--------------------------------|--|--|---|---|--|--|
| 9. OPERATING MODE 5 | 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) | | | | | | | | | | | |
| | <input type="checkbox"/> 20.2201(b) | | | <input type="checkbox"/> 20.2203(a)(3)(i) | | | <input checked="" type="checkbox"/> 50.73(a)(2)(ii)(A) | | | <input type="checkbox"/> 50.73(a)(2)(viii)(A) | | |
| | <input type="checkbox"/> 20.2201(d) | | | <input type="checkbox"/> 20.2203(a)(3)(ii) | | | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | | | <input type="checkbox"/> 50.73(a)(2)(viii)(B) | | |
| | <input type="checkbox"/> 20.2203(a)(1) | | | <input type="checkbox"/> 20.2203(a)(4) | | | <input type="checkbox"/> 50.73(a)(2)(iii) | | | <input type="checkbox"/> 50.73(a)(2)(ix)(A) | | |
| 10. POWER LEVEL 0 | <input type="checkbox"/> 20.2203(a)(2)(i) | | | <input type="checkbox"/> 50.36(c)(1)(i)(A) | | | <input type="checkbox"/> 50.73(a)(2)(iv)(A) | | | <input type="checkbox"/> 50.73(a)(2)(x) | | |
| | <input type="checkbox"/> 20.2203(a)(2)(ii) | | | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | | | <input type="checkbox"/> 50.73(a)(2)(v)(A) | | | <input type="checkbox"/> 73.71(a)(4) | | |
| | <input type="checkbox"/> 20.2203(a)(2)(iii) | | | <input type="checkbox"/> 50.36(c)(2) | | | <input type="checkbox"/> 50.73(a)(2)(v)(B) | | | <input type="checkbox"/> 73.71(a)(5) | | |
| | <input type="checkbox"/> 20.2203(a)(2)(iv) | | | <input type="checkbox"/> 50.46(a)(3)(ii) | | | <input type="checkbox"/> 50.73(a)(2)(v)(C) | | | <input type="checkbox"/> 73.77(a)(1) | | |
| | <input type="checkbox"/> 20.2203(a)(2)(v) | | | <input type="checkbox"/> 50.73(a)(2)(i)(A) | | | <input type="checkbox"/> 50.73(a)(2)(v)(D) | | | <input type="checkbox"/> 73.77(a)(2)(i) | | |
| | <input type="checkbox"/> 20.2203(a)(2)(vi) | | | <input checked="" type="checkbox"/> 50.73(a)(2)(i)(B) | | | <input type="checkbox"/> 50.73(a)(2)(vii) | | | <input type="checkbox"/> 73.77(a)(2)(ii) | | |
| | | | <input type="checkbox"/> 50.73(a)(2)(i)(C) | | | <input type="checkbox"/> OTHER | | | Specify in Abstract below or in NRC Form 366A | | | |

12. LICENSEE CONTACT FOR THIS LER

| | |
|--|--|
| LICENSEE CONTACT Leonard Sueper, Senior Regulatory Engineer | TELEPHONE NUMBER (Include Area Code) (612) 330-6917 |
|--|--|

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX |
|-------|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| B | AB | VTV | V085 | Y | N/A | N/A | N/A | N/A | N/A |

| | | | | |
|--|-------------------------------------|-------|-----|------|
| 14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO | 15. EXPECTED SUBMISSION DATE | MONTH | DAY | YEAR |
| | | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On October 16, 2017, with Unit 2 shutdown for a refueling outage, investigation into a boric acid indication identified a through wall leak at the socket weld that joins a 3/4 inch line to Loop A Reactor Coolant System (RCS)[AB] shutdown communication line valve 2RC-8-37][VTV]. The leak was isolated by closed valves that would have limited primary coolant leakage to within the capacity of the charging system when the reactor coolant system was pressurized. The quantity of dry boric acid at the location was small (estimated at 1/2 teaspoon in volume). This failure constituted a welding or material defect in the primary coolant system that was not found acceptable under ASME Section XI and an event or condition prohibited by Technical Specifications.

The cause of the leakage was determined to be stress corrosion cracking. Valve 2RC-8-37 was replaced. In addition, Prairie Island Nuclear Generating Plant intends to perform phased array ultrasonic inspections of socket welds on similar Class 1 piping containing stagnant water during future refueling outages.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

| 1. FACILITY NAME | 2. DOCKET NUMBER | 3. LER NUMBER | | |
|---|------------------|---------------|-------------------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| Prairie Island Nuclear Generating Plant | 05000-306 | 2017 | - 002 | - 00 |

NARRATIVE

DESCRIPTION OF EVENT

On October 16, 2017, with Prairie Island Nuclear Generating Plant (PINGP) Unit 2 shutdown for refueling outage 2R30, an indication of leakage was found on the pipe socket weld upstream of valve 2RC-8-37 [VTV] during boric acid corrosion examinations. Valve 2RC-8-37 functions as a vent path on the normally isolated 3/4 inch Loop A shutdown communication line [AB]. Subsequent non-destructive examination confirmed a pressure boundary leak existed, which was not found acceptable under ASME Section XI.

EVENT ANALYSIS

This event is being reported in accordance with 10 CFR 50.73(a)(2)(ii)(A), "Any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded" because the weld defect in the primary coolant system was not found acceptable under ASME Section XI. In addition, the pressure boundary leakage exceeded the zero reactor coolant system operational leakage limit specified in Tech Spec 3.4.14 and therefore was reportable per 50.73(a)(2)(i)(B) as a condition prohibited by plant technical specifications.

CAUSE

Laboratory analysis determined the cause of the leak to be stress corrosion cracking. Contributing causes included weld material sensitization and the presence of sulfur and oxygen on internal surfaces. Oxygen is introduced from containment air when the system is in use during outages and is not removed by the normal primary system oxygen scavenging mechanisms because the line is normally isolated / stagnant.

SAFETY SIGNIFICANCE

There was no actual safety consequence associated with this event. The quantity of dry boric acid at the location was small (estimated at 1/2 teaspoon in volume). Even if the weld had experienced a complete circumferential failure, the leak was isolated by closed valves that would have limited primary coolant leakage to within the capacity of the charging system when the reactor coolant system was pressurized (see figure next page).

CORRECTIVE ACTIONS

Valve 2RC-8-37 and the associated weld were replaced and the reactor coolant pressure boundary was restored.

PINGP intends to perform phased array ultrasonic inspections of socket welds on similar Class 1 piping containing stagnant water during future PINGP Unit 1 and 2 refueling outages.

PREVIOUS SIMILAR OCCURRENCES

A similar boric acid deposit was previously identified during refueling outage 2R29 in 2015 on valve 2RC-8-37 at the same location. However, visual and dye penetrant testing performed in accordance with plant procedures showed no indication of flaws or an active leak. The origin of the boric acid residue on the valve at the time was incorrectly attributed to a prior leak (e.g. reactor coolant pump seal leak) or maintenance activity.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

| 1. FACILITY NAME | 2. DOCKET NUMBER | 3. LER NUMBER | | |
|---|------------------|---------------|-------------------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| Prairie Island Nuclear Generating Plant | 05000-306 | 2017 | - 002 | - 00 |

Figure

