

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

MAR 1 6 1984

Mr. E. P. Rahe, Manager Nuclear Safety Department Nuclear Technology Division Westinghouse Electric Corporation Box 355 Pittsburgh, PA 15230

Dear Mr. Rahe:

Subject: Case Study Report - Low Temperature Overpressure Events

at Turkey Point Unit 4

Following resolution of peer review comments, we have completed the enclosed study of low temperature overpressure events. This study concentrates on two overpressure events that occurred at Turkey Point, Unit 4, but also considers related events at other pressurized water reactors occurring after 1979 when the staff resolved the generic issue entitled, "Reactor Vessel Pressure Protection (Overpressure Protection)."

The report provides: (1) an analysis and evaluation of the Turkey Point events; (2) a review of operating events that have challenged the low temperature overpressure protection (LTOP) systems; (3) evaluation of the LTOP technical specifications; (4) an evaluation of water solid operation during the low temperature regime; and (5) recommendations that, if implemented, could reduce challenges to the overpressure protection system and strengthen its mitigatory capability to minimize the potential severity of overpressure events.

You will note that there is an activity identified for the nuclear industry to further evaluate the necessity for water solid operation and consider developing a recommended operating practice for filling and venting which excludes water solid operation. As a vendor for a PWR design that operates water solid, I encourage you to pursue this activity in the interest of improving reactor safety.

The recommendations contained in this report are under review within the Nuclear Regulatory Commission. The report is being forwarded for your information and use as you deem appropriate.

If you have any questions regarding this report, please contact Wayne D. Lanning of my staff. Mr. Lanning can be reached at (301) 492-4433.

Sincerely,

8404130052 840316 PDR ADDCK 05000251 S_____PDR C. 0. Heltemes, Jr., Director
Office for Analysis and Evaluation
of Operational Data

Enclosure: As stated

cc: See page 2

cc: w/o enclosure

Mr. Joseph Sheppard, Chairman Carolina Power & Light Company

Mr. Eugene P. Wilkinson, President Institute of Nuclear Power Operations

Dr. David Rossin, Director Nuclear Safety Analysis Center MAR 1 6 1984

DISTRIBUTION:
DESTOR
AEOD CF
ROAB CF
ROAB RF
WLanning
TAIppolito
KVSeyfrit

CJHe1temes

Dr. Paul L. McGill, Vice President Commercial Department Combustion Engineering Inc. 1000 Prospect Hill Road Windsor, Connecticut 06095

Dear Dr. McGill:

Subject: Case Study Report - Low Temperature Overpressure Events

at Turkey Point Unit 4

Following resolution of peer review comments, we have completed the enclosed study of low temperature overpressure events. This study concentrates on two overpressure events that occurred at Turkey Point, Unit 4, but also considers related events at other pressurized water reactors occurring after 1979 when the staff resolved the generic issue entitled, "Reactor Vessel Pressure Protection (Overpressure Protection)."

The report provides: (1) an analysis and evaluation of the Turkey Point events; (2) a review of operating events that have challenged the low temperature overpressure protection (LTOP) systems; (3) evaluation of the LTOP technical specifications; (4) an evaluation of water solid operation during the low temperature regime; and (5) recommendations that, if implemented, could reduce challenges to the overpressure protection system and strengthen its mitigatory capability to minimize the potential severity of overpressure events.

You will note that there is an activity identified for the nuclear industry to further evaluate the necessity for water solid operation and consider developing a recommended operating practice for filling and venting which excludes water solid operation. As a vendor for a PWR design that operates water solid, I encourage you to pursue this activity in the interest of improving reactor safety.

The recommendations contained in this report are under review within the Nuclear Regulatory Commission. The report is being forwarded for your information and use as you deem appropriate.

If you have any questions regarding this report, please contact Wayne D. Lanning of my staff. Mr. Lanning can be reached at (301) 492-4433.

Sincerely,

Original signed by: C. J. Heltemes, Jr.

C. J. Heltemes, Jr., Director
Office for Analysis and Evaluation
of Operational Data

SURNAMED As. stated WLanning/cj KVSeyfrit TAIppolito CJHallemes CC: See page 2 1/3/84 1/3/84 2-/3/84 3/16/84	OFFICE		8}_ ' • ()	ROAB; 7℃	ROAB C	AEOD:DD	AEOD:D	
DATED CC: See page 2 1/3/84 1/3/84 2-/3/84 3/16/84	SURNAME			WLanning/cj	KVSeyfrit	TAIppolito	CJHe(Ttemes	
	DATE	cc: See	.page.2	1 /2//84	1 /31/84	2-13/84	3/16/84	

LIBETTED THE TENNEL COME TO THE CONTROL OF THE CONT

cc: w/o enclosure

Mr. Richard Wells, Chairman Northeast Utilities Service Company

Mr. Eugene P. Wilkinson, President Institute of Nuclear Power Operations

Dr. David Rossin, Director Nuclear Safety Analysis Center

. ,