



86 NOV 18 AIO: 05

NOVEMBER 14 1986

L-86-463

Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., N.W., Suite 2900
Atlanta, GA 30323

Dear Dr. Grace:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report 86-37

Florida Power & Light has reviewed the subject inspection report and a response is attached.

Should you or your staff have any questions on this information, please contact us.

Very truly yours,

C. O. Woody
Group Vice President
Nuclear Energy

COW/PLP/gp

Attachment

cc: Harold F. Reis, Esquire

8612030311 861114
PDR ADOCK 05000250
Q PDR

TEOI

10-10-68



10-10-68

10-10-68

10-10-68

10-10-68

10-10-68

10-10-68

10-10-68

10-10-68

10-10-68



10-10-68

10-10-68

ATTACHMENT

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report 86-37

FINDING:

Technical Specification 6.8.1 requires that written procedures be implemented that meet or exceed the requirements and recommendations of USNRC Regulatory Guide 1.33.

USNRC Regulatory Guide 1.33, Appendix A, Item 6.p. indicates that the forced evacuation of the control room should be covered by written procedures.

Off Normal Operating Procedure 0-ONOP-103, Control Room Inaccessibility, Section 4.5 and 5.1, require the plant supervisor-nuclear to obtain and take eight (8) radios from the control room to the turbine operator shelter, distribute the radios to the specified personnel, establish communication with the operators at their local control stations, and ensure that hot standby conditions are maintained.

Contrary to the above, on August 27, 1986, the licensee did not maintain eight (8) radios in the control room to support communications necessary to implement Off Normal Operating Procedure 0-ONOP-103 in the event of control room inaccessibility. The licensee was unable to locate the full complement of eight (8) radios for approximately two days.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The reason for the finding was a misinterpretation of the radio system requirements by FPL operations and contractor personnel. It was known that the radios were in place to deal with off normal situations and testing situations that require special communications. It was felt that if a radio failed, it was acceptable to send the radio out for repairs and a replacement was not required.
- 3) A) The required eight (8) radios were obtained and placed in the chargers. The chargers were posted to identify the minimum number of radios necessary to comply with 0-ONOP-103.
B) A program to test and replace defective radios was discussed with and implemented with a contractor to insure a sufficient number of radios are maintained in the charger for both off normal and testing situations.
- 4) Plant modifications include a new communications system that has a separate independent protected power supply that when fully implemented will alleviate the requirement of hand held radios for safe and alternate shutdown communications.
- 5) A) Full compliance for Item 3 above was achieved by August 29, 1986.
B) Full compliance for Item 4 above will be achieved by the end of the next Unit 3 refueling outage.

BN

Page 24

The first part of the document discusses the importance of maintaining accurate records and the role of the various departments involved in the process.

It is noted that the current procedures are outdated and need to be revised to reflect the changes in the industry and the needs of the organization.

The second part of the document outlines the proposed changes to the record-keeping system, including the implementation of a new software program and the reorganization of the data center.

It is expected that these changes will result in a more efficient and cost-effective system, and will also improve the accuracy and reliability of the records.

Very truly yours,

John Doe, Director

The following table shows the estimated costs and benefits of the proposed changes. It is clear that the benefits far outweigh the costs, and the investment is well justified.


It is recommended that the proposed changes be approved and implemented as soon as possible to ensure that the organization remains competitive in the market.

The attached documents provide further details on the proposed changes and the supporting data. Please review them carefully and let me know if you have any questions.

I am confident that these changes will be a significant step forward for the organization, and I look forward to working with you to ensure a smooth transition.

Thank you for your attention and support.

Best regards,
John Doe



86 NOV 18 A10:05

NOVEMBER 14 1986

L-86-463

Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., N.W., Suite 2900
Atlanta, GA 30323

Dear Dr. Grace:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report 86-37

Florida Power & Light has reviewed the subject inspection report and a response is attached.

Should you or your staff have any questions on this information, please contact us.

Very truly yours,

A handwritten signature in dark ink, appearing to read "C. O. Woody".

C. O. Woody
Group Vice President
Nuclear Energy

COW/PLP/gp

Attachment

cc: Harold F. Reis, Esquire

*1 Original sent to DMS
Extra Copy*

10-10-68



Dear Mr. [Name obscured]

I am writing to you regarding the [subject obscured]

As you are aware, the [subject obscured] is currently [status obscured]

I am sure you will find this information [status obscured]

Very truly yours,

[Signature obscured]

[Title obscured]

[Company Name obscured]

[Address obscured]

[City obscured]

[State obscured]



ATTACHMENT

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report 86-37

FINDING:

Technical Specification 6.8.1 requires that written procedures be implemented that meet or exceed the requirements and recommendations of USNRC Regulatory Guide 1.33.

USNRC Regulatory Guide 1.33, Appendix A, Item 6.p. indicates that the forced evacuation of the control room should be covered by written procedures.

Off Normal Operating Procedure 0-ONOP-103, Control Room Inaccessibility, Section 4.5 and 5.1, require the plant supervisor-nuclear to obtain and take eight (8) radios from the control room to the turbine operator shelter, distribute the radios to the specified personnel, establish communication with the operators at their local control stations, and ensure that hot standby conditions are maintained.

Contrary to the above, on August 27, 1986, the licensee did not maintain eight (8) radios in the control room to support communications necessary to implement Off Normal Operating Procedure 0-ONOP-103 in the event of control room inaccessibility. The licensee was unable to locate the full complement of eight (8) radios for approximately two days.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The reason for the finding was a misinterpretation of the radio system requirements by FPL operations and contractor personnel. It was known that the radios were in place to deal with off normal situations and testing situations that require special communications. It was felt that if a radio failed, it was acceptable to send the radio out for repairs and a replacement was not required.
- 3) A) The required eight (8) radios were obtained and placed in the chargers. The chargers were posted to identify the minimum number of radios necessary to comply with 0-ONOP-103.
B) A program to test and replace defective radios was discussed with and implemented with a contractor to insure a sufficient number of radios are maintained in the charger for both off normal and testing situations.
- 4) Plant modifications include a new communications system that has a separate independent protected power supply that when fully implemented will alleviate the requirement of hand held radios for safe and alternate shutdown communications.
- 5) A) Full compliance for Item 3 above was achieved by August 29, 1986.
B) Full compliance for Item 4 above will be achieved by the end of the next Unit 3 refueling outage.

10-1-1954

8-11

