

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company
Turkey Point, Units 3 and 4

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

During the Nuclear Regulatory Commission (NRC) inspection conducted on December 28, 1991, through January 24, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1991), the violation is listed below:

Technical Specification 6.8.1 requires that written procedures and administrative policies be established, implemented, and maintained in accordance with the requirements and recommendations of Appendix A of Regulatory Guide 1.33, Revision 2, dated February 1978.

Appendix A of Regulatory Guide 1.33, Revision 2, dated February 1978, recommends that written procedures be established for typical safety-related activities carried out during the operation of nuclear power plants. Section 1.b of this Appendix recommends administrative procedures which include authorities and responsibilities for safe operation and shutdown.

Paragraph 5.6.16.1 of procedure O-ADM-200, Conduct of Operations, requires that evolution briefings be conducted for individuals involved in an evolution that is to be performed and that the detail of the briefing is dependent on the degree and complexity of the evolution and the number of individuals involved.

Contrary to the above, on January 14, 1992, an adequate evolution briefing was not conducted prior to the investigation of a possible malfunction of the pressurizer control group heaters with Unit 3 at 100% power. As a result, power operated relief valve PCV-3-455C was inadvertently cycled due to excessive demand on controller PC-3-444J.

This is a Severity Level IV violation (Supplement 1).

Pursuant to the provisions of 10 CFR 2.201, Florida Power and Light Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further



Florida Power and Light Company 2
Turkey Point, Units 3 and 4

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia
this *27th* day of February 1992

