ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS) '

ACCESSION NBR:	9204280056 DOC.D	DATE: 92/04/20	NOTARIZED: NO	DOCKET #
FACIL:50-250	Furkey Point Plant,	, Unit 3, Flori	da Power and Light	C 05000250
AUTH.NAME	AUTHOR AFFILIA	ATION		
TOMONTO, R.J.	Florida Power &	& Light Co.		
PLUNKETT, T.F.	Florida Power &	a Light Co.	-	
RECIP.NAME	RECIPIENT AFFI	LIATION		

SUBJECT: LER 92-002-00:on 920319,steam/feedwater flow mismatch bistables not tripped within 1 h action statement when steam flow testing in progress.Caused by personnel error.Procedure revised to add bistables.W/920420 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR / ENCL / SIZE: C TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:NRR RAGHAVAN, L

05000250

R

I

D

S

Α

D

D

S

Α

D

D

S

	RECIPIENT ID CODE/NAME PD2-2 LA	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME PD2-2 PD	COP LTTR 1	IES ENCL 1	D
	AULUCK, R	1	T				5
INTERNAL:	ACNW	2	2	AEOD/DOA	1	1	
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2	
	NRR/DET/EMEB 7E	1	1	NRR/DLPO/LHFB10	1	1	
	NRR/DLPO/LPEB10	1	ī	NRR/DOEA/OEAB	1	1	
	NER/DEEP/PEPB11	2	2	NRR/DST/SELB 8D	ī	ī	
	NPR/DST/STCB8H3	า	า	NRR/DST/SPLB8D1	1	ī	
	NDD/DST/SDYB 8F	า้	1 (PEG FILE 02	า	า	
	RES/DSIR/EIB	i	ī	RGN2 FILE 01	ī	ĩ	
		-			1		
EXTERNAL:	EG&G BRYCE J.H	3	3	L ST LOBBY WARD	1	1	
2.1.2.2.4.1.2.4	NRC PDR	ĩ	1	NSTC MURPHY .G.A	1	ī	
	NSIC POORE, W.	ī	ī	NUDOCS FULL TXT	ī	ī	R
	•						T
NOTES:		1	1				L

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

• • •



P.O. Box 029100, Miami, FL, 33102-9100

APR 2 0 1992

L-92-111 10 CFR 50.73

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

Gentlemen:

 \mathbf{O}

Re: Turkey Point Unit 3 Docket No. 50-250 Reportable Event: 92-002 Date of Event: March 19, 1992 Failure to Trip Steam Flow/Feedwater Flow Mismatch Bistables

The attached Licensee Event Report 250-92-002 is provided pursuant to the requirements of 10 CFR 50.73 (2)(i)(B) to provide information on the subject event.

Very truly yours,

T. F. Plunkett Vice President Turkey Point Nuclear

TFP\RJT\rt

Attachment

cc: Stewart D. Ebneter, Regional Administrator, Region II, USNRC Senior Resident Inspector, USNRC, Turkey Point Plant

9204280056 920420 P PDR ADDCK 05000250 S PDR 1

an FPL Group company

IE22

				*																	
		•	L:	IC:	ENSE	E	E۱	7E]	NT	R	EF	20	RT		LI	ER)		•	_ 	
FACILIT	у нане	(1)												DOCK	T NUMBE	R (2)	Z	AGE	(3)	···	
TURKEY POINT UNIT 3 05000250											1	OF	3								
TITLE (4) E	AIL	URE	то	TRIP STE	AM/I	FEED	WATI	ER F	LOW	MIS	MAT	CH E	BIST	ABLE	ES					
EVENT DATE (5) LER NUMBER (6) RPT DATE (7) OTHER FACILITIES INV. (8)																					
MON	DAY	YR		YR	SEQ #	Rŧ	MON	DAY	YR			NAN	1E		• DOCKET # (S)						
03	19	92		92	002	00	04	20	92												
OPERATI	NG MODE	(9)	1			10 C	FR !	50.7	3 ()	2) (i) (B)							·		
PONER LEVE	iL (10)					Specify	in Abs	tract be	slow and	i in tex	t)	-									
81	7	1			-																
	-				L	ICENS	SEE C	ONTA	CT F(OR TH	IS L	ER (:	12)								
R. (Ј. Т	omoi	nto,	Lic	censing]	Engi	nee	r							TELEP	HONE NUR	MBER				
			·													30	5-246-	732	7		
					COMPLETE ON	E LINE	FOR EAC	н сонго	ENT FAI	ILURE DE	SCRIBED	IN THI	S REPOR	T (13)							
CAUSE	Syste	EM .	COHPOI	ENT	HANUFACTURER	NPROS				CAUSE	-	SYSTE	н	COMPONENT MANUFACTURES		ACTURER		NPRDS			
SUPPLEMENTAL REPORT EXPECTED (14)							EXPEC SUBHI	TED SSION	MON	ITH	DAY		YEA	R							
Y Z S		(11)	(es, con	plete E	XPECTED SUBMISSIC	N DATE)					NO NO			(15)							
ABSTRAC	r (16)			<u> </u>						-		^							•••		
	At ope Pri Pri wh: Ste Ste Ste Ste	apr erat rcer gh H essi ogre ich 141 anne eam/ rvic eam/ rvic chnis	rox ing it p low ire als 'Fee 23 h See Fee cal	imat at OVCha Prot Voc Voc Voc Voc Voc Voc Voc Voc Voc Voc	ely 1311 87 perce ; testin innels. ection 1 est comp uired re uplies i er Flow n Marc stopped, Reacton er Flow e same t ecificat:	l ho ent Ig w Pla Inst amov inpu Mis ch 1 c Co Mis cime	urs power as l nt n tor al t tor al t mato g, t h ntro as 3/4	on er a perin set from ch c l992 ch c the .1 m/F	Marc nd g pe edu tion poin sei eam hani tean pera hani tean pera	ch 1 Iurfo re 3 ntsice ntsice nesti nesti neam eacte	9, 2 ey 1 rmed -PM: for 3 dwat ng 0 lat had flor or F	1992 Poir d or I-07 V Ch f th ter re r ter ter ter ter ter ter ter ter	y with 2.5 ann wie s inel inel biann Sy	ith nit e Ur el F line tean w Mi remc Stea ermi een els. sten	Tur 4 o hit rbi -3- e hi sma oved m L ere rem rem i In	key pera 3 St 447, gh f ow t fro that inest ovec stru	Point ating ceam I First was flow. ransr chanr om sen High cored at the d from	Utintin Titlin I Sin Titlin Fto tipe	on,	3 0	
	be	en t stir	rip	ped as j	within t	:he ess.	1 h	our	ACT:	ION	STA	was violated, since the Steam/Feedwater Flow Mismatch bistables had not been tripped within the 1 hour ACTION STATEMENT while steam flow testing was in progress									

C

\sim		LICENSEE	e int	REPORT	(LER)	TEXT	UNTINUATION	
-	FACILITY NAME TURKEY POINT	CUNIT 3	docket 050002	NUMBER	LER NU 92-0	лее 102-00	PAGE NO. 02 of 03	'

I. DESCRIPTION OF THE EVENT

At approximately 1311 on March 19, 1992, with Turkey Point Unit 3 operating at 87 percent power and Turkey Point Unit 4 operating at 100 percent power, testing was being performed on the Unit 3 Steam Line High Flow Channels. Plant procedure 3-PMI-072.5, Turbine First Stage Pressure Protection Instrumentation Set IV Channel P-3-447, was in progress to test comparator setpoints for steam line high flow. The procedure required removal from service of the steam flow transmitter which also supplies input to the Steam/Feedwater Flow Mismatch channels. Steam/Feedwater Flow Mismatch channels were not removed from service. At 1413 hours on March 19, 1992, testing on the Steam Line High Flow channels was stopped, and the steam flow channels were restored to service. When testing resumed at approximately 1800 hours on March 19, 1992, the Reactor Control Operator determined that the Steam/Feedwater Flow Mismatch channels had not been removed from service at the same time as the Steam flow channels. As a result, the Nuclear Plant Supervisor directed the Instrument and Control (I&C) supervisor to discontinue testing and return the equipment to normal. The I&C Field Supervisor informed the Nuclear Plant Supervisor that the procedure was complete. The Steam Flow channels were immediately returned to service.

At 2030 hours on March 19, 1992, an investigation concluded that during testing between 1311 hours and 1413 hours, Unit 3 did not meet the requirements of Technical Specification 3/4.3.1.

Technical Specification Table 3.3-1, Reactor Trip System Instrumentation, ACTION STATEMENT 6, states the following:

With the number of OPERABLE channels one less than the Total Number of Channels, STARTUP and/or POWER OPERATION may proceed until performance of the next required ANALOG CHANNEL OPERATIONAL TEST provided the inoperable channel is placed in the tripped condition within 1 hour.

Technical Specification 3/4.3.1 was violated, since the Steam/Feedwater Flow Mismatch bistables had not been tripped within the 1 hour time restriction, while steam flow testing was in progress. The actual elapsed time was 1 hour, two minutes.

II. CAUSE OF THE EVENT

The cause of this event is personnel error during the review of the procedure. Technical Specification 3.3.1 and Table 3.3-1 item 12 requires that when the Steam Line Flow protection channels are removed from service when the unit is in Modes 1 or 2, bistables from Steam/Feedwater Flow Mismatch protection channels must be placed in the tripped condition within one hour. Contrary to this requirement, plant procedure 3-PMI-072.5, Turbine First Stage Pressure Protection

0	LICENSEE	ELENT RE	EPORT (LE	R) TEXT	ONTINUATION	
FACILITY NAME TURKEY POINT	UNIT 3	DOCKET NUN 0500025	MBER LE 0 92	R NUMBER 2-002-00	PAGE NO. 03 of 03	•

Instrumentation Set IV Channel P-3-447, only required the First Stage Pressure Channel P-447 and Steam Line High Flow Channels F-475, F-485, and F-495 be removed from service by placing the respective bistables in the tripped condition.

III. ANALYSIS OF THE EVENT

The reason for this discrepancy is that the original plant procedure for testing the Steam Line High Flow channels was specifically intended to be performed during refueling (Mode 6) and thus only specified that the bistables for the Steam Line High Flow protection be tripped. When this procedure was upgraded to a new format on October 8, 1987, only those bistables previously designated to be tripped were included in the new procedure, even though the new procedure is applicable in all operating modes. Since 1977, the procedure (or portions of the procedure) that govern this activity have only been performed during refueling.

IV. CORRECTIVE ACTIONS

- 1. Procedures 3-PMI-072.5 and 3-PMI-072.4 were revised to add bistables for the Steam/Feedwater Flow Mismatch protection function and annunciators to the removal of the Steam Flow channel from service.
- 2. All infrequently scheduled load threatening Instrument and Control (I&C) surveillance and calibration procedures were reviewed and found consistent with Technical Specification Surveillance Requirements.
- 3. All load threatening I&C surveillance and calibration procedures will be modified to include review and written acknowledgement by the Reactor Control Operator of channels to be removed from service, and annunciators and status lights expected. These procedural modifications will be completed by 7/31/92. In the interim, I&C will include an Operations Briefing Checksheet with each Plant Work Order issued for infrequently scheduled load threatening maintenance activities.

V. ADDITIONAL INFORMATION

No similar LERs have been identified.

. •

• • • • • • v 1 ,

· · •

×

•