

AUG - 6 1993

Docket Nos. 50-250, 50-251, 50-335, 50-389  
License Nos. DPR-31, DPR-41, DPR-67, NPF-16

Florida Power and Light Company  
ATTN: Mr. J. H. Goldberg  
President - Nuclear Division  
P. O. Box 14000  
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: MEETING TO DISCUSS ENGINEERING INITIATIVES AT FLORIDA POWER AND  
LIGHT

This letter refers to the meeting conducted at your request at the NRC  
Region II offices in Atlanta on July 16, 1993. The purpose of the meeting was  
to allow Florida Power and Light (FPL) to make a presentation on engineering  
initiatives at FPL.

It is our opinion that this meeting was beneficial and provided a better  
understanding of the issues and status of current programs.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 1,  
Title 10, Code of Federal Regulations, a copy of this letter and its  
enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please let us know.

Sincerely,

Ellis W. Merschoff, Director  
Division of Reactor Projects

Enclosures:

1. List of Attendees
2. Presentation Summary

cc w/encls:

D. A. Sager  
Site Vice President  
St. Lucie Nuclear Plant  
P. O. Box 128  
Ft. Pierce, FL 34954-0128

9309100135 930806  
PDR ADOCK 05000250  
P PDR

IE01

cc w/encls cont'd:

T. F. Plunkett  
Site Vice President  
P. O. Box 029100  
Miami, FL 33102

L. W. Pearce  
Plant General Manager  
Turkey Point Nuclear Plant  
P. O. Box 029100  
Miami, FL 33102

T. V. Abatiello  
Site Quality Manager  
Turkey Point Nuclear Plant  
P. O. Box 029100  
Miami, FL 33102

E. J. Weinkam  
Licensing Manager  
Turkey Point Nuclear Plant  
P. O. Box 029100  
Miami, FL 33102

R. E. Grazio, Director  
Nuclear Licensing  
P. O. Box 14000  
Juno Beach, FL 33408-0420

G. J. Boissy  
Plant General Manager  
P. O. Box 128  
Ft. Pierce, FL 34954-0128

Harold F. Reis, Esq.  
Newman & Holtzinger  
1615 L Street, NW  
Washington, D. C. 20036

John T. Butler, Esq.  
Steel, Hector and Davis  
400 Southeast Financial Center  
Miami, FL 33131-2398

Bill Passeti  
Department of Health and  
Rehabilitative Services  
1317 Winewood Boulevard  
Tallahassee, FL 32399-0700

cc w/encls cont'd: (See page 3)

AUG - 6 1993

Florida Power & Light Company

3

cc w/encls cont'd:  
Attorney General  
Department of Legal Affairs  
The Capitol  
Tallahassee, FL 32304

Administrator  
Department of Environmental  
Regulation  
Power Plant Siting Section  
State of Florida  
2600 Blair Stone Road  
Tallahassee, FL 32301

Joaquin Avino  
County Manager of Metro Dade  
County  
111 NW 1st Street, 29th Floor  
Miami, FL 33128

Jack Shreve  
Public Counsel  
Office of the Public Counsel  
c/o The Florida Legislature  
111 West Madison Avenue, Room 812  
Tallahassee, FL 32399-1400

Joe Myers, Director  
Division of Emergency Preparedness  
2740 Centerview Drive  
Tallahassee, FL 32399-2100

Thomas R. L. Kindred  
County Administrator  
2300 Virginia Avenue  
Ft. Pierce, FL 34982

Charles B. Brinkman  
Washington Nuclear Operations  
12300 Twinbrook Parkway, Suite 3300  
Rockville, MD 20852

bcc w/encls:  
K. Landis, RII  
J. Norris, NRR  
L. Raghavan, NRR  
St. Lucie Resident Inspector  
Turkey Point Resident Inspector  
Document Control Room

RII:DRP  
*RS*  
RSchin  
8/4/93

RII:DRP  
*KL*  
KLandis  
8/4/93

RII:DRP  
*MUS*  
MSinkule  
8/4/93

*rb* *Y*

ENCLOSURE 1

LIST OF ATTENDEES

NRC

L. A. Reyes, Deputy Regional Administrator, Region II (RII)  
J. R. Johnson, Deputy Director, Division of Reactor Projects (DRP), RII  
J. P. Jaudon, Deputy Director, Division of Reactor Safety (DRS), RII  
N. N. Berkow, Director, Project Directorate II-2, DRP-I/II, Office of Nuclear  
Reactor Regulation (NRR)  
M. V. Sinkule, Chief, Reactor Projects Branch II, DRP, RII  
C. A. Julian, Chief, Engineering Branch, DRS, RII  
K. D. Landis, Chief, Reactor Projects Section 2B, DRP, RII  
R. P. Schin, Project Engineer, DRP, RII  
G. A. Hallstrom, Reactor Inspector, Materials and Processes Section, DRS, RII

FPL

J. H. Goldberg, President, Nuclear Division  
W. H. Bohlke, Vice President, Nuclear Engineering and Licensing  
J. B. Hosmer, Director, Nuclear Engineering  
G. J. Boissy, Plant General Manager, St. Lucie  
J. Scarola, Site Engineering Manager, St. Lucie  
D. H. West, Technical Manager, St. Lucie  
L. A. Rogers, Supervisor, Instrumentation and Control Maintenance, St. Lucie  
D. M. Wolf, Supervisor, Site Engineering, St. Lucie  
J. J. Hutchinson, Manager, Equipment Support and Inspections

**NRC/FPL  
SEMIANNUAL COMMUNICATION MEETING  
NRC REGION II OFFICE, ATLANTA  
JULY 16, 10:00 A.M. - 12 NOON**

# **PURPOSE**

**Discuss Engineering And Technical  
Support To Both Plants With Focus On:**

- 1) St. Lucie Challenges**
  
- 2) Process Improvements**

## **INTRODUCTIONS**

<b>J. Goldberg</b>	<b>President, Nuclear Division</b>
<b>W.H. Bohlke</b>	<b>Vice President, Nuclear Engineering And Licensing</b>
<b>G.J. Boissy</b>	<b>Plant General Manager, PSL</b>
<b>J.B. Hosmer</b>	<b>Director, Nuclear Engineering</b>
<b>D.H. West</b>	<b>Manager, PSL Technical Support</b>
<b>L.A. Rogers</b>	<b>Supervisor, PSL I&amp;C Maintenance</b>
<b>J. Scarola</b>	<b>Project Manager, PSL Engineering</b>
<b>D.M. Wolf</b>	<b>Supervisor, PSL Site Engineering</b>
<b>J.J. Hutchinson</b>	<b>Manager, Equipment Support &amp; Inspections</b>

**NRC/FPL SEMIANNUAL COMMUNICATION MEETING  
NRC REGION II OFFICE, ATLANTA**

**JULY 16, 1993 10:00 A.M. - 12 NOON**

***MEETING AGENDA***

- INTRODUCTION/PURPOSE W. BOHLKE 5 MIN

**PSL CHALLENGES**

- ST. LUCIE RCP SHAFT  
ROOT CAUSE EVALUATION D. WEST 15 MIN
- ST. LUCIE PRESSURIZER  
INCONEL 600 NOZZLE J. SCAROLA 10 MIN
- UNLATCHED CEA J. HUTCHINSON 10 MIN
- DROPPED CEA L. ROGERS 10 MIN
- ST. LUCIE CODE SAFETIES D. WOLF 10 MIN
- ST. LUCIE LESSONS LEARNED G. BOISSY 10 MIN

**PROCESS IMPROVEMENTS**

- ENGINEERING PROCESS  
IMPROVEMENTS TO SUPPORT  
OPERATIONS & MAINTENANCE J. HOSMER 5 MIN
- OPEN DISCUSSION 25 MIN



## **ENGINEERING JOURNEY**

- **Successfully Transitioned To A\E Independence**
- **Conduct Quarterly Self Assessments**
- **Transition Continues As Engineering Focuses On Involvement With Operations And Maintenance**
  - **People Philosophy**
    - **More People On Site**
  - **Product Philosophy**
    - **Products More Focused On Operations And Maintenance**
- **Avoid Repeating Mistakes (Internal/Industry)**
  - **Problem Reports**
  - **Tech Alerts**

# ST. LUCIE REACTOR COOLANT PUMP I. BACKGROUND

VENDOR: BRYON JACKSON

HEAD/FLOW: 245 FT/81,250 GPM


- SEAL:
- 4 Stages Including Vapor Seal
  - 1-1.5 GPM Controlled Bleed Off
  - Seal Injection Capability Installed As Modification
  - Seal Injection Used For Fill And Vent, Heat-Up And Cooldown
  - Design Pressure 2485 psig
  - Design Temperature 250° F

- SHAFT:
- 304 Stainless Steel
  - Stainless Steel Pump Hydrostatic Bearing

- COOLING:
- CCW Cools Motor And Seal

EDGE PARTS LISTED  
AT DWG IE-3436-3

4-4 11-24 11-25



7-1 11-35 11-43 11-34

## II. PROBLEM


- **PSL NO. 1**

- 6/30/90 Pump 1A1 Experienced High Seal Leakoff Flow Requiring Plant Shutdown - Resultant Inspection Revealed Bent Shaft


- **PSL NO. 2**

- 1/13/93 Pump 2A1 Experienced High Vibration Requiring Plant Shutdown - Resultant Inspection Revealed A Cracked Shaft

- **For Both Events The Unit Was Safely Shutdown Based On Existing Indications**



## 2A1 CRACK LOCATIONS:



### **III. ANALYSIS**

- **Formed Plant/Engineering Team**
- **Byron Jackson/Combustion Engineering Participation**
- **Performed Dimensional & NDE of 2A1 Shaft**
- **Review Operating/Maintenance/Modification History**
- **2A1 & 1A1 RCP's Idle for H/U & C/D**
- **Reviewed 1A1 (Unit No. 1) Analysis**
  - **Confirmed Thermal Transient Can Bend A Shaft**
- **Industry Survey**
  - **Use of Seal Injection**
  - **Other RCP Shaft Failures**
- **Preliminary Root Cause Is Thermal Stress From Seal Injection**
- **Analysis Continuing**

## **SHORT TERM IV. CORRECTIVE ACTIONS**

### **Plant and Engineering Team Assigned To Address Short Term Actions**

- **Installed New Rotating Assembly  
- Improved Alignment Procedures**
- **Engineering/Operations/Maintenance Evaluation  
Of Operating w/o Seal Injection**
- **Changed Procedures On Both Units To Eliminate  
Use Of Seal Injection, Except During Fill And  
Vent Operations And Emergency Procedures**
- **Moved Vibration Monitoring Instrumentation  
From Lower Motor To Pump Coupling**
- **Prepared Startup Procedure For Monitoring  
& Data Collection**

## **V. LONG TERM CORRECTIVE ACTIONS**

### **A. Long Term Root Cause Team Formed**

- St. Lucie Plant Staff Mechanical Maintenance**
- St. Lucie Plant Reliability Maintenance**
- St. Lucie Plant Technical Staff**
- Nuclear Engineering Pump Specialists**
- Nuclear Engineering Supervisor Component Specialists**
- Nuclear Engineering Thermal/Hydraulic Analysis Specialist**
- Nuclear Engineering Systems & Operations Specialist**
- Nuclear Engineering Design**
- Nuclear Engineering Metallurgist**
- Pump Vendor (Byron Jackson)**



## **V. LONG TERM CORRECTIVE ACTIONS**

**(Continued)**

### **B. Long Term Root Cause Team Overall Action Plan**

- Using Event Tree/FMEA Methodology To Identify Potential Causes**
  - Perform Pump Shaft Metallurgical Analysis**
  - Perform Stress Analysis - Pump Rotor**
  - Operating & Maintenance Procedures Review**
  - Analyze Manufacturing And Pre-Service Test Data**
  - Evaluate RCP Modification Packages**
  - Evaluate RCP Vibration Data (Prior To & Following Failure)**
  - Provide Additional Monitoring Instrumentation To RCPs**
  - Draw Conclusion Re Root Cause**
  - Recommend Further Corrective Actions And Issue Report**

## **V. LONG TERM CORRECTIVE ACTIONS**

(Continued)

### **C. Action Plan Status**

- **Manufacturing & Pre-Service Data Analysis Completed**
  - **Concluded That Initially Defective Assembly Is Not A Probable Root Cause**
- **Thermal Stress Analysis**
  - **Preliminary Conclusion That Seal Injection Thermal Stresses Can Propagate Small Surface/Subsurface Flaws (<.010 In)**
  - **Crack Initiation & Propagation Investigation Is Continuing**
  - **Definition Of Mechanical Loads That Could Cause Crack Propagation Is Continuing**
    - **RCP Runout**
    - **RCP Shaft Misalignment**
    - **S/U Torque Against Reverse Flow**
- **Disassembly Of Pump Rotating Assembly For Dimensional & Metallurgical Analysis Has Begun**

## **VI. SUMMARY**

- **Replaced Damaged RCP Rotating Assembly**
- **Changed Procedures To Eliminate Use Of Seal Injection (Suspected Root Cause)**
- **Relocated Vibration Monitoring Probes To Pump Side Of Coupling**
- **Proceeding With Further Analysis To Confirm Root Cause And Final Corrective Actions**
- **Expect Final Recommendations By 12/93**

## **PRESSURIZER INSTRUMENT NOZZLE CRACKING**

**March 3, 1993, Visually Identified Four Steam Space Nozzles With Leakage On Unit 2 In Mode 5**

- **Background:**

- **SONGS 3 Instrument Nozzle Leaks '86**
- **Pressurizer Steam Space Nozzles Replaced '87**
- **Hot Leg & Pressurizer Liquid Space Replaced '89**

- **Analysis:**

- **No Significant Safety Hazard**
- **Susceptible Material Inconel Alloy 600**
- **High Temperature Environment**
- **Heat Number**

- **Root Cause:**

- **Primary Water Stress Corrosion Cracking**

- **Immediate Corrective Action:**


- **Steam Space Nozzles Replaced With Alloy 690**
- **Inspected Liquid Space Nozzles Of Same Heat**

- **Long Term Corrective Actions:**

- **Inspect During Refueling Inconel 600 Nozzles**
- **Replace Pressurizer Liquid Space Nozzles In '96**
- **Continue To Monitor Industry Data**

Figure 1

# I-600 SUSCEPTIBILITY TO PWSCC FUNCTION OF STRESS, ENVIRONMENT AND MICROSTRUCTURE




## **PRESSURIZER INSTRUMENT NOZZLE REPAIR**

- **Examination Phase:**
  - NSSS To Perform The Work
  - Independent Oversight (FPL & Vendor)
  - PT Examination
  - Destructive Examination
- **Surface Preparation:**
  - Removal Of Cracks
  - Clad Build-Up
- **Nozzle Replacement:**
  - Nozzles Machined
  - Nozzles Welded In Place
- **Errors Made:**
  - ASME Code Compliance
    - Size Of Weld Rods
    - Thermocouple Placement
  - Work Control
- **Lessons Learned:**
  - Improve Technical Oversight On Special Process Jobs
- **Safety Significance:**
  - Qualified Weld




# ST. LUCIE UNIT 2 PRESSURIZER UPPER & LOWER INSTRUMENT NOZZLE ANALYSIS



## PRESSURIZER NOZZLE EXAM FINDINGS UPPER NOZZLE LOCATIONS (PCM 8096-287)



## PRESSURIZER NOZZLE LOCATIONS (UPPER NOZZLES)



## PRESSURIZER LOWER NOZZLE LOCATIONS



**ST LUCIE UNIT 1  
ALLOY 600 RCS PENETRATION SUMMARY (3-93)**

PENETRATION TYPE (HEAT #)	STATUS	PREDICTED LIFE	REPLACEMENT RECOMMENDATION	INSPECTION RECOMMENDATIONS
<b>I. PZR NOZZLES</b>				
7-STREAM & WATER SPACE (NX8297 *)	NOT LEAKING	NO PREDICTION (NOTE 1)	MONITOR	< 1100 DAY
<b>II. PZR HTR SLEEVES</b>				
5-SLEEVES (C2202/NX8878) *	NOT LEAKING	BYOND PREDICTION	MONITOR	< 1100 DAYS
6-SLEEVES (C2831-1/NX8878)	NOT LEAKING	MODERATE SUSCEPTIBILITY	MONITOR	< 1100 DAYS
109-SLEEVES (NX5038)	NOT LEAKING	HIGH SUSCEPTIBILITY	MONITOR	< 1100 DAYS
<b>III. RCS NOZZLES</b>				
2-RV O RING LEAK MONITOR TUBES (NX5358/NX5282)	NO KNOWN LEAKS	NA	NONE NON PRESSURE APPLICATION	NA
30-HOT & COLD LEG RTD'S (NX9752/NX0003)	NOT LEAKING	> 40 YRS (NO FAILURES)	MONITOR	NORMAL B.A. WALKDOWN

\* Indicates heats with industry failure history.

NOTE: 1) Based on one failure point, but many more survival points exist with more hours of operation at pressurizer temperature.

ALLOY 600



**ST LUCIE UNIT 2  
ALLOY 600 RCS PENETRATION SUMMARY (3-93)**

PENETRATION TYPE (HEAT #)	STATUS	PREDICTED LIFE	REPLACEMENT RECOMMENDATION	INSPECTION RECOMMENDATIONS
<b>I. PZR NOZZLES</b>				
4-STEAM SPACE (41501 *)	CRACKED (3-93)	NA	ALLOY 690 (1993)	< 1100 DAYS
1-WATER SPACE (41501 *)	NOT LEAKING	28,000 HRS REMAINING FROM 3-93	ALLOY 690 ● EOC 8 (1995)	< 1100 DAYS
2-WATER SPACE (NX7630/7387-2)*	NOT LEAKING	BEYOND PREDICTION (NOTE 1)	ALLOY 690 ● EOC 8 (1995)	< 1100 DAYS
<b>II. PZR HTR SLEEVES</b>				
30-SLEEVES (VARIOUS HEATS)	NOT LEAKING	LOW SUSCEPTIBILITY	MONITOR	< 1100 DAYS
<b>III. RCS NOZZLES</b>				
2-RV O RING LEAK MONITOR TUBES (54318 *)	NO KNOWN LEAKS	NA	NONE NON PRESSURE APPLICATION	NA
5-HOT LEG RTD'S (41501 *)	NOT LEAKING	97,000 HRS REMAINING FROM 3-93	MONITOR/REPLACE	NORMAL B.A. WALKDOWN
9-HOT LEG RTD'S (NX7630 *)	NOT LEAKING	> 40 YRS	NONE	NORMAL B.A. WALKDOWN
4-HOT LEG RTD'S (NX3918V)	NOT LEAKING	> 40 YRS (NO FAILURES)	NONE	NORMAL B.A. WALKDOWN
1-HOT LEG RTD (7760-6)	NOT LEAKING	> 40 YRS (NO FAILURES)	NONE	NORMAL B.A. WALKDOWN
12-COLD LEG RTD'S (VARIOUS HEATS)	NOT LEAKING	> 40 YRS	NONE	NORMAL B.A. WALKDOWN

\* Indicates heats with industry failure history.

NOTE: 1) Based on 1992 failure data at other CE designed plants.

ALLOY 600


JPN-PSL-SEMP-93-013  
REVISION 1  
PAGE 14 OF 14

# ST. LUCIE UNIT #1 UNLATCHED CONTROL ELEMENT ASSEMBLY

## Background:

- May 29th, 1993 Low Power Physics Testing Indicated Anomaly With Rod Worth Associated With Dual CEDM #7
- Additional Low Power Physics Tested Indicated That Only One Of The Two CEAs Was Coupled
- Decision Was Made To Shutdown And Dissassemble The Reactor To Pursue Root Cause
- Cross Functional Team Consisting Of Tech Staff/Operations/ Maintenance/Fuels/ And Engineering Formed To Determine Root Cause

ST. LUCIE UNIT 1  
OPERATING PROCEDURE NO. 1-0110022, REVISION 12  
COUPLING AND UNCOUPLING OF CEA EXTENSION SHAFTS



Y	X	W	V	T	S	R	P	N	M	L	K	J	H	G	F	E	D	C	B	A		
							FR08 a b d c		M21	M18		FR04 a b d c									21	
				M13	R01	P05	R05 124	P25	R03 125	P07	R07	M12									20	
		M60	R17 126	P16	R49 127	M05	R29 302	M03	R51 123	P10	R19 128	M56									19	
	M53	R25 201	P33	R78 122	P56	R57 121	P75	R59 120	P57	R76 119	P32	R27 204	M57								18	
	M10	R21 129	P29	R33	P42	R65 118	M30	R37	M33	R67 117	P39	R35	P36	R24 130	M16						17	
	R09	P12	R73 116	P38	M92 81	P66	R41	M25	R43	P63	M90 82	P43	R83 115	P13	R12						16	
	P01	R53 131	P59	R72 80	P62	P72 114	P21	P46 132	P20	P70 113	P67	R69 83	P54	R56 112	P04						15	
FR01 a b d c	R13 133	M01	R64 111	M36	R45	P17	R84 110	P50	R81 109	P24	R48	M32	R61 108	M08	R16 134						FR06 a b d c	14
M19	P27	R32 301	P74	R40	M28	P48 107	P52	M87 135	P51	P47 106	M27	R39	P73	R31 303	P28						M23	13
M24	R15 136	M07	R62 105	M31	R47	P23	R80 104	P49	R82 103	P18	R46	M35	R63 102	M02	R14 137						M20	12
FR05 a b d c	P03	R55 101	P53	R70 79	P68	P69 100	P19	P45 99	P22	P71 98	P61	R71 84	P60	R54 97	P02						FR02 a b d c	11
	R11	P14	R75 96	P44	M89 95	P64	R44	M26	R42	P65	M91 85	P37	R74 94	P11	R10							10
	M15	R23 138	P35	R36	P40	R60 93	M34	R38	M29	R58 92	P41	R34	P30	R22 139	M09							9
		M58	R28 203	P31	R77 91	P58	R68 90	P76	R66 89	P55	R79 88	P34	R26 69	M54								8
			M55	R20 140	P09	R52 87	M04	R30 304	M06	R50 F02	P15	R18 141	M59									7
				M11	R06	P08	R04 142	P26	R08 143	P06	R02	M14										6
							FR03 a b d c	M17	M22	FR07 a b d c												5

Assembly Insert





# **ST. LUCIE UNIT #1 UNLATCHED CONTROL ELEMENT ASSEMBLY**

## **Short Term Actions**

- 1. Core Physics Predictions Analyzed To Verify Initial Conclusions**
- 2. All CEA Drive Shafts Reweighed & Pin Postion Verified**
- 3. CEDM Coupling & Uncoupling Procedure # 1-0110022 Rev 12 Reviewed For Potential Root Cause**
- 4. Performed Engineering Study By Use Of Fault Tree To Examine Potential Root Causes**
- 5. Performed Visual/Dimensional Inspections To Verify As-Found Condition**

**ST. LUCIE UNIT #1**  
**UNLATCHED CONTROL ELEMENT ASSEMBLY**

**Root Cause Physical Inspection Results:**


- 1. Inboard CEA #103 Found Unlatched From Dual Extension Shaft #7**
- 2. Dual CEDM Shaft #7 Removed From Upper Guide Structure. Functionally, Dimensionally And Visually Checked - No Anomalies Noted**
- 3. Inspection Of CEA Hubs #103 & #98 Showed No Damage**
- 4. Inspection Of Dual Shroud And Associated Area Above Fuel Found No Anomalies**













PROBABLE ROOT CAUSE




INCORRECT PIN POSITION



CORRECT PIN POSITION





CORRECTLY COUPLED CEA

# **ST. LUCIE UNIT #1 UNLATCHED CONTROL ELEMENT ASSEMBLY**

## **Long Term Actions**

- 1. Enhance Coupling/Uncoupling Procedure By:**
  - (a) Add Requirements To Measure Coupled Extension Shaft Height**
  - (b) Include Step To Verify Adequate Slack Exists In Coupling Tool Suspension System**
  
- 2. Human Factor Improvements To Improve Indicator Pin Verification**
  - (a) Supply Additional Lighting To Assist Position Indicator Pin Verification**
  - (b) Independant Verification Of Position Indicator Pin Location**
  
- 3. Improve Training Of Personnel On The Implementation Of The Coupling And Verification Procedure**



# **ST. LUCIE UNIT 2 DROPPED CEA EVENT**

## **BACKGROUND**

- **May 21, 1993**
  
- **Reactor At 72% Power - Steady State;  
Water Box Cleaning In Progress**
  
- **Seven CEAs Dropped Fully Into Core**
  
- **Reactor Manually Tripped**
  
- **Fuel Group Analysis Concluded:**
  - **DNBR & PLHR Limits Not Exceeded**
  - **SAFDLs Not Violated**
  - **Event Bounded By Design Basis Analysis**

## **ST. LUCIE UNIT 2 DROPPED CEA EVENT**

### **ANALYSIS**

- **Root Cause Team Formed**
  - Tech Staff Engineers
  - I&C Engineers
  - Site Design Engineers
  - ABB-CE Design Engineers
  - Containment Penetration Vendor Design Engineers
  
- **Numerous Inspections & Tests Performed**
  - CEDMCS System Component/Functional Test
  - Meggered & Tested All CEDM Penetrations For Grounds
  - Time Domain Reflectometer (TDR)
  - Local Leak Rate Testing (LLRT)
  - Visual Inspection Of Penetration With Vendor
  
- **Root Cause For Event**
  - Grounds In Containment Electrical Penetration

## **ST. LUCIE UNIT 2 DROPPED CEA EVENT**

### **IMMEDIATE CORRECTIVE ACTIONS**


- **Meggered All CEDMs From CEDMCS To Identify Grounds**
- **Re-Routed Grounded Connections To Tested Spare Penetration Conductors**
- **Monitored Output Of MGs Via Power Line Monitor**


### **LONG TERM CORRECTIVE ACTIONS**

- **Perform Inspection Of Defective Penetration To Identify Failure Mechanism**
- **Addition Of Ground Detection System To CEDMCS Bus**

# PENET. D-1

(NB)





1	INSTRUMENTATION	2	PLUMBING
3	MECHANICAL	4	ELECTRICAL
5	STRUCTURAL	6	GENERAL
7	HAZARDOUS WASTE	8	OTHER
9	UNASSIGNED	10	UNASSIGNED

- 1. INSTRUCTIONS TO BE FOLLOWED BY THE CONTRACTOR.
- 2. CHECKED DESIGN & CONSTRUCTION BY THE OWNER'S PERSONNEL.
- 3. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 4. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 5. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 6. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 7. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 8. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 9. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.
- 10. ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.

- 11. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 12. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 13. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 14. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 15. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 16. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 17. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 18. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 19. CHECK CONSTRUCTION BY THE CONTRACTOR.
- 20. CHECK CONSTRUCTION BY THE CONTRACTOR.

**NUCLEAR SAFETY RELATED NOTICE**  
 SEE SHEETS 0-A, 0-B, 0-C, 0-D FOR FURTHER INFORMATION

NO.	DESCRIPTION	DATE	BY	REVISION
1	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	1
2	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	2
3	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	3
4	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	4
5	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	5
6	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	6
7	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	7
8	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	8
9	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	9
10	ISSUED FOR CONSTRUCTION	7/8/93	J. L. ...	10

**CONCRETE WORK**  
 ALL PENETRATIONS SHALL BE MADE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.  
 ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.  
 ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.  
 ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE DESIGN & CONSTRUCTION SPECIFICATIONS.




**ST. LUCIE PLANT  
PRESSURIZER CODE SAFETY VALVE LEAKAGE**

**PRIOR TO 1992**

- **Use Of Crosby Valve Company (OEM) For Overhaul Of Valves To Assure Consistency And Expert Workmanship**
- **Revised Valve Testing Methodology To Test At NOP/NOT Conditions (At Wylie Test Labs) And Strengthen Acceptance Criteria For Leakage**
- **Evaluated Nozzle Loads With Respect To Vendor Recommended Values**
- **Converted To Flexi-Disc Design**

# FLEXI-DISC CONVERSION





**ST. LUCIE PLANT  
PRESSURIZER CODE SAFETY VALVE LEAKAGE**

**1992 LEAKAGE EVENTS**

**Unit 1**

- Gradual Increase In Leakage To Quench Tank
- Operational Difficulties In Maintaining Quench Tank Level & Temperature
- Shutdown On Sept. 14th To Replace Valve V1202
- Instrumented Nozzles To Determine Loading

**Unit 2**

- Gradual Increase In Leakage To Quench Tank
- Operational Difficulties In Maintaining Quench Tank Level & Temperature
- Shutdown On Nov 24, 1992 & Replaced Valves V1201 & V1202
- Optimized SRV Tailpipe Spring Can Support

## NON-LEAKING PLANTS WITH CROSBY SAFETY VALVES

PLANTS\INFO	SEAT LEAKAGE	VALVE/SIZE LOOP SEAL NSS	VALVE TRIM	MAX NOZZLE LOADS (% OF CROSBY ALLOWABLES)	SEAT LK TEST PRES. (% OF LIFT)	SRV AMBIENT CONDITIONS (°F)	COMMENTS
PLANT #1 (Two Units)	NO	3-CROSBY 6M6 DRAINED WESTINGHOUSE	FLEXI-DISC 2 <small>Performed testing of Flexi-Disc 2 with Crosby at Wyle</small>	<50%	95% ON STM	120	<ol style="list-style-type: none"> <li>1. REDUCED NOZ. LOADS (major effort)</li> <li>2. ADDED FLEXI-DISC 2</li> <li>3. REDUCED AMBIENT TEMP.- ADDED HVAC DUCT</li> <li>4. IMPROVED MAINT. &amp; TESTING                             <ul style="list-style-type: none"> <li>- 95% LK TEST ON STM - ZERO LK,</li> <li>- OPTICAL FLATS AT 1 LIGHT BAR</li> <li>- TEST AT WYLE, CROSBY REP. SOMETIMES</li> </ul> </li> </ol>
PLANT #2	NO	CROSBY 3k,6 NONE WESTINGHOUSE 400 MWE	FLEXI-DISC 2 INSTALLED 1990	<100%	93% ON STM	140	<ol style="list-style-type: none"> <li>1. REDUCED NOZ. LOADS (removed rigid support, added snubbers)</li> <li>2. ADDED FLEXI-DISC 2</li> <li>3. AMBIENT TEMP REDUCTION - NONE</li> <li>4. INCREASED TESTING REQM'TS:                             <ul style="list-style-type: none"> <li>- 93% LK TEST ON STM - ZERO LK.</li> <li>- OPTICAL FLATS (optional)</li> <li>- TEST AT WEST. WITH CROSBY REP.</li> </ul> </li> </ol>
PLANT #3 (Two Units)	NO	3-CROSBY 6M6 1-DRAINED 2-HOT WESTINGHOUSE	FLEXI-DISC 2	<50% ADDED FLEX JOINT	93% ON STM		<ol style="list-style-type: none"> <li>1. DRAINED LOOP SEALS, AND LEAKAGE STARTED. ADDED FLEXIBLE JOINT</li> <li>2. CHANGED TO FLEXI-DISC 2</li> <li>3. TESTING AND MAINT:                             <ul style="list-style-type: none"> <li>- 93% LK TEST ON STM</li> <li>- OPTICAL FLATS</li> <li>- CHANGED TO WEST. (PRICE &amp; SERV)</li> </ul> </li> </ol>
PLANT #4 (Two Units)	NO	3 CROSBY 6M6 DRAINED WESTINGHOUSE	FLEXI-DISC 2	<50%	??	145-155	<ol style="list-style-type: none"> <li>1. SRV SEAT LEAKAGE HAS NOT BEEN A PROBLEM</li> <li>2. MAINTENANCE AND TESTING:                             <ul style="list-style-type: none"> <li>- 93% LK TEST ON STEAM</li> <li>- TEST AT WYLE, WITH CROSBY REP.</li> </ul> </li> </ol>
PLANT #5	MINIMAL OR NONE	2-CROSBY 4M,6 NONE B&W RUPTURE DISK	FLEXI-DISC 1 INSTALLED 1982	0% TEE WITH RUPTURE DISC	93% ON STM	120-140	<ol style="list-style-type: none"> <li>1. PIPE MODS - REMOVED TAILPIPING, 1978 REMOVED LOOP SEALS AND INSTALLED TEES WITH RUPTURE DISC</li> <li>2. ADDED FLEXI-DISC 1</li> <li>3. AMBIENT TEMP REDUCTION - NONE</li> <li>4. INCREASED TESTING REQM'TS:                             <ul style="list-style-type: none"> <li>- 93% LK TEST ON STM - ZERO LK.</li> <li>- OPTICAL FLATS (optional)</li> <li>- TEST AT WYLE, USE IN-HOUSE MAINT.</li> </ul> </li> </ol>
PLANT #6	MINOR, IMPROVED	CROSBY 6M6 DRAINED WESTINGHOUSE	FLEXI-DISC 1	<100%	94% ON STM	100	<ol style="list-style-type: none"> <li>1. MODIFIED PIPE TO IMPROVE ALIGNMENT</li> <li>2. SRV'S SIT ON PLATFORM PINNED TO PRESSURIZER</li> <li>3. AMBIENT TEMP REDUCTION - NONE</li> <li>4. INCREASED LEAK TEST PRESS TO 94% ON NITROGEN WITH 10 BUB/MIN</li> <li>5. TESTING LOC. - WYLE LABS WITH REP.</li> </ol>

**ST. LUCIE PLANT  
PRESSURIZER CODE SAFETY VALVE LEAKAGE**

**LONG TERM ACTIONS**


- **Maintenance/Engineering/Staff Component Specialist Cross Functional Team Formed To Focus On Resolution**
  
- **Industry Analysis**
  1. **Six Utilities (Crosby Valves) Identified With Successful Results**
  2. **Identified Common Aspects Associated With Leakage Reduction**
    - **Consistent Maintenance & Testing Requirements**
    - **Flexi-Disc Valve Trim**
    - **Stable Valve Ambient Temperatures**
    - **Nozzle Loads < Crosby Allowable**



# ST. LUCIE UNIT 1

## PRESSURIZER SAFETY VALVE

### PIPE MODIFICATION



**ST. LUCIE PLANT  
PRESSURIZER CODE SAFETY VALVE LEAKAGE**

**ACTION PLAN**

- **More Stringent Leak Test Acceptance Criteria**
- **Remove Tailpipe Cold Spring And Modify Supports To Reduce Valve Nozzle Loads**
  - Unit 1 - 1993 Refueling Outage**
  - Unit 2 - 1994 Refueling Outage**
- **Modify Local Insulation To Reduce Adverse Temperature Effects ("Chimney Effects") On SRVs**
  - Unit 1 - 1993 Refueling Outage**
  - Unit 2 - 1994 Refueling Outage**
- **Review Results Of The Above Actions**

## **ST. LUCIE LESSONS LEARNED**

- **Team Remains Strong**
- **Plant Performance Remains Strong**
- **Plant Work Is Proactive & Conservative**

## **ENGINEERING PROCESS & PRODUCT IMPROVEMENT**

- **6/92 A/E Independence Complete**
- **70 - 80% Engineering Manhours By FPL**
- **Transitioning To Operations/Maintenance Products & Direct Support**
- **Meaning**
  - **People's Attitudes Must Change On Their Accountabilities & Products**
  - **Management Needs To Change Training Emphasis**

# ENGINEERING PROCESS & PRODUCT IMPROVEMENT

## PEOPLE EMPHASIS

New Accountability	Who Affects	Status	Value
Onsite Outage Package Implementation	Juno PEGs	10-15 People Each Site	<ul style="list-style-type: none"> <li>- Accountability</li> <li>- Feedback</li> </ul>
Supplement Site Engineering & Maintenance During Outages	All Juno Engineering	10-15 People Each Site	<ul style="list-style-type: none"> <li>- Direct Plant Support</li> <li>- People Development</li> </ul>
Onsite Leadership - Problem Solving - Assistant Outage Directors	Juno & Site Engineering	<ul style="list-style-type: none"> <li>- Unlatched CEA</li> <li>- 4 Outage Directors</li> <li>- ESI Role</li> </ul>	<ul style="list-style-type: none"> <li>- Technical Leadership</li> </ul>
Shift Training Emphasis From Design To Plant Operations	Engineering Management	<ul style="list-style-type: none"> <li>- 4 SRO Complete</li> <li>- 2 to 4 SRO '93</li> <li>- System Training</li> <li>- New Grad Training</li> </ul>	<ul style="list-style-type: none"> <li>- Plant Knowledge</li> </ul>



# ENGINEERING PROCESS & PRODUCT IMPROVEMENT

## PRODUCT EMPHASIS

Customer	Product	Status	Value
Maintenance	PSL Custom Vendor Manuals	50 Complete PSL	- Improved Troubleshooting & PMs
	Setpoint Document	Complete 12/93 Both Sites	- Defined Basis - One Document
	Maintenance Specifications	16 Complete Both Sites	- Independent Maintenance Action Within Design Basis
	Engineering Basis For PMs	Start 7/93 Both Sites	- Better PMs
Operations	PTN Split & Enhance P&IDs	PTN Complete	- Legibility - Accuracy
	PTN As Built Drawing Backlog	PTN Complete	- Improved Drawings, Quality
	DBDs	PTN Complete 15/40 PSL	- Problem Solving - Operation Training
	Plant Change/Modification Packages (PCMs)		
	3 New Design Output Products: • IEE • MEP • DCR	Complete	- Improved Responsiveness

