

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9002020031 DOC. DATE: 90/01/26 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 AUTH. NAME AUTHOR AFFILIATION
 SCHWABENBAUER Carolina Power & Light Co.
 RICHEY, R.B. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-021-00: on 891227, ESSFA due to loss of main feedwater caused by personnel error.

W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Application for permit renewal filed. 05000400

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-1 LA BECKER, D		1	1		PD2-1 PD		1	1
INTERNAL:	ACRS MICHELSON		1	1	ACRS MOELLER		2	2	
	ACRS WYLIE		1	1	AEOD/DOA		1	1	
	AEOD/DSP/TPAB		1	1	AEOD/ROAB/DSP		2	2	
	DEDRO		1	1	NRR/DET/ECMB 9H		1	1	
	NRR/DET/EMEB9H3		1	1	NRR/DET/ESGB 8D		1	1	
	NRR/DLPQ/LHFB11		1	1	NRR/DLPQ/LPEB10		1	1	
	NRR/DOEA/OEAB11		1	1	NRR/DREP/PRPB11		2	2	
	NRR/DST/SELB 8D		1	1	NRR/DST/SICB 7E		1	1	
	NRR/DST/SPLB8D1		1	1	NRR/DST/SRXB 8E		1	1	
	REG FILE 02		1	1	RES/DSIR/EIB		1	1	
	RGN2 FILE 01		1	1					
EXTERNAL:	EG&G WILLIAMS, S		4	4	L ST LOBBY WARD		1	1	
	LPDR		1	1	NRC PDR		1	1	
	NSIC MAYS, G		1	1	NSIC MURPHY, G.A		1	1	
	NUDOCS FULL TXT		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 37 ENCL 37

AO-4

CP&L

Carolina Power & Light Company

P. O. Box 165 • New Hill, N. C. 27562

R. B. RICHEY
Manager
Harris Nuclear Project

JAN 26 1990
Letter Number: HO-900023 (0)

U.S. Nuclear Regulatory Commission
ATTN: NRC Document Control Desk
Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1
DOCKET NO. 50-400
LICENSE NO. NPF-63
LICENSEE EVENT REPORT 89-021-00

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,



R. B. Richey, Manager
Harris Nuclear Project


RBR:dgr

Enclosure

cc: Mr. R. A. Becker (NRR)
Mr. S. D. Ebnetter (NRC - RII)
Mr. J. E. Tedrow (NRC - SHNPP)

9002020031 900126
PDR ADOCK 05000400
S PDC

MEM/LER-89-021/1/OS1



LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) SHEARON HARRIS NUCLEAR POWER PLANT - UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 4 0 0	PAGE (3) 1 OF 0 3
---	---	-----------------------------

TITLE (4) **Engineered Safety System Feature Actuation Due to the Loss of Main Feedwater Caused by Personnel Error**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)							
1	2	7	8	9	0	2	1	0	0	0	1	2	6	9	0	N/A	0 5 0 0 0

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 1 1 2	<input type="checkbox"/> 20.402(b)	<input checked="" type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)

NAME Richard Schwabenbauer - Regulatory Compliance Technician	TELEPHONE NUMBER
	AREA CODE: 9 1 1 9 NUMBER: 3 1 6 1 2 - 1 2 1 6 1 9

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
B	KIN	IISIV	TIO210	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
---	--	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The plant was operating in Mode 1, POWER OPERATION, at 12 percent reactor power on December 27, 1989. The plant was in the process of increasing power following a turbine trip test. The 1A-NNS Main Feedwater (MFW) pump was in service. Steam Generator (SG) water levels were being manually controlled by the plant operators. At 1650 hours, the 1A-NNS MFW pump tripped on low-flow. The pump's recirculation valve was not capable of opening fast enough to maintain adequate water flow through the pump as feedwater flows were being manually adjusted. This resulted in a loss of MFW and an automatic start of both motor driven Auxillary Feedwater (MDAFW) pumps occurred. The AFW actuation also causes an isolation of SG sampling lines. One of the sample valves closed but reopened and could not be manually closed. The operators manually reduced load and took the turbine generator off line. The turbine driven Auxillary Feedwater (TDAFW) pump was actuated manually to help stabilize SG water levels. There was no turbine or reactor trip as a result of this event.

At 1655 hours, the operators started the 1B-NNS MFW pump to control SG water level and then proceeded to secure the AFW pumps.

The cause of the event was personnel error on the part of the operator in cutting back feedwater flow too fast which in turn caused the 1A-NNS MFW pump to trip on low-flow.

Corrective actions will include the repair of the sampling valve, appropriate procedure revision, training of applicable personnel, and a review of the MFW pump recirculation control and low-flow trips.

There were no safety consequences as a result of this event as the AFW pumps started as required supplying water to the SGs. This event is being reported in accordance with 10CFR50.73(a)(2)(iv) as an Engineered Safety System Feature actuation.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) SHEARON HARRIS NUCLEAR POWER PLANT -- UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 4 0 0	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 2 1	- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description:

The plant was operating in Mode 1, POWER OPERATION, at 12 percent reactor power on December 27, 1989. The plant was in the process of increasing power following a turbine trip test. Both the 1A-NNS and 1B-NNS Condensate and Condensate Booster pumps were running with the 1A-NNS Main Feedwater (MFW) pump in service. The 1B-NNS MFW pump was not in service at the time due to the low power level and Steam Generator (SG) water levels were being manually controlled by plant operators.

Operating personnel were in the process of transferring feedwater flow from the by-pass flow control valves to the main feedwater regulating valves (MFRV). During this evolution, total water flow was sufficient for the 1A-NNS MFW pump recirculation valve to go shut at its normal flow set point. This increased water flow to the SGs. The plant operator noticed that SG water levels were increasing rapidly and began throttling back on the feedwater regulating valves to decrease water flow to the SGs. The pump's recirculation valve was not capable of opening fast enough to maintain adequate water flow through the pump to prevent a pump trip on low-flow.

At 1650 hours, the 1A-NNS MFW pump tripped on low-flow. This resulted in a total loss of feedwater to the SGs and an automatic start of both motor driven Auxiliary Feedwater (AFW) pumps. Plant operators then manually ran back the main turbine generator to under 10 percent load and opened the output breakers. They also started the turbine driven AFW pump to help stabilize SG water levels.

At 1655 hours, plant operators started the 1B-NNS MFW pump to control SG water levels and then proceeded to secure the AFW pumps.

There was no turbine or reactor trip as a result of this event. All plant safety systems responded as required with the exception of valve LSP-226 (MANUFACTURER--TARGET ROCK, MODEL #1032001-4-8-3/4-S) which is in the Steam Cycle Sampling System. The valve closed as required but reopened and could not be reclosed. This valve is an isolation valve for 1C-SN SG tube outlet to sampling panel which closes on an AFW actuation.

Cause:

The cause of the event was personnel error on the part of the operator. While the applicable operating procedure does not prohibit the simultaneous transfer to all three MFRVs, simultaneous transfer of all three is more difficult. While the evolution can be accomplished on the plant simulator, it is very difficult in actual plant practice. In the course of the evolution, the operator was forced to drastically reduce feedwaterflow to prevent a turbine trip due to high SG water level (P-14 interlock). The recirculation flow control for the MFW pump is not modulated, the recirculation path is either

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) SHEARON HARRIS NUCLEAR POWER PLANT - UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 4 0 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 2 1	- 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

fully open or closed based on the low-flow set point and reset point. The flow reduction occurred so quickly that the recirculation flow control valve could not open before the time delay on the low flow trip.

Analysis:

There were no safety consequences as a result of this event as the AFW pumps started as required supplying water to the SGs. This particular event is only possible during low power operations where the flow through the MFW pump is just above the recirculation valve set point.

Depending on power level, the loss of a MFW pump could result in a reactor trip due to low SG water level.

This event is being reported in accordance with 10CFR50.73(a)(2)(iv) as an Engineered Safety System Feature (ESF) actuation.

There have not been any previous similar events reported where operator action caused a loss of MFW and ESF actuation.

Correction Action:

1. A work request WR&A 89-BANZ1 has been generated to repair valve 1SP-226. The sample line has been isolated by another valve until the repair can be completed.
2. General Procedure (GP)-005, Power Operation Mode 2 to Mode 1, will be revised to require that the transfer to the MFRV's will not be done simultaneously for all three SGs.
3. An evaluation will be done of the relative times for the MFW pump low-flow trip time delay and the response time of the recirculation flow control valve.
4. Training will be done for applicable personnel on this event.

EIIS Code Information:

Main Turbine	TA
Main Generator	TB
Condensate Pump	SD
Condensate Booster Pump	SD
Main Feedwater Pump	SJ
Main Feedwater Regulating Valve	SJ
Steam Generator	SB
Auxiliary Feedwater Pump	BA
Engineered Safety System Feature	JE
Steam Cycle Sampling System	KN