

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9601180391 DOC. DATE: 90/01/12 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 AUTH. NAME AUTHOR AFFILIATION
 VERRILLI, M. Carolina Power & Light Co.
 ROBINSON, W.R. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 95-014-00: on 940424, RHR sys components removed from service as directed during testing, while required for operability. Cause by procedure inadequacies. Test will be revised to correct procedure by 960215.W/960112 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Application for permit renewal filed.

05000400

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	PD2-1 PD		1	1	LE,N		1	1
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1	FILE CENTER		1	1
	NRR/DE/ECGB		1	1	NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1	NRR/DRCH/HHFB		1	1
	NRR/DRCH/HICB		1	1	NRR/DRCH/HOLB		1	1
	NRR/DRCH/HQMB		1	1	NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1	NRR/DSSA/SRXB		1	1
	RES/DSIR/EIB		1	1	RGN2 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE, J H		2	2
	NOAC MURPHY, G.A		1	1	NOAC POORE, W.		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 26

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T



Carolina Power & Light Company
PO Box 165
New Hill NC 27562
JAN 12 1996

William R. Robinson
Vice President
Harris Nuclear Plant

U.S. Nuclear Regulatory Commission
ATTN: NRC Document Control Desk
Washington, DC 20555

Serial: HNP-96-006
10CFR50.73

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1
DOCKET NO. 50-400
LICENSE NO. NPF-63
LICENSEE EVENT REPORT 95-014-00

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report concerns a condition that existed while performing surveillance testing in April of 1994, during refueling outage 5, which resulted in the Residual Heat Removal System being inoperable for a short period. This inoperability condition constitutes a violation of Technical Specifications.

Sincerely,

MV

Enclosure

c: Mr. S. D. Ebnetter (NRC - RII)
Mr. N. B. Le (NRC - PM/NRR)
Mr. D. J. Roberts (NRC - HNP)

9601180391 960112
PDR ADOCK 05000400
S PDR

180013

IF22
11

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Harris Nuclear Plant Unit-1

DOCKET NUMBER (2)

50-400

PAGE (3)

1 OF 3

TITLE (4)

Residual Heat Removal System components were removed from service as directed during testing, while required for operability, resulting in a Technical Specification violation.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
4	24	94	95	-- 014	-- 00	1	12	96		05000
									FACILITY NAME	DOCKET NUMBER
										05000

OPERATING MODE (9)	POWER LEVEL (10)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more) (11)							
6	0%	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input checked="" type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 20.2203(a)(2)(vi)
									<input type="checkbox"/> 50.73(a)(2)(viii)
									<input type="checkbox"/> 50.73(a)(2)(ix)
									<input type="checkbox"/> 73.71
									<input type="checkbox"/> OTHER
									<input type="checkbox"/> Specify in Abstract below or in NRC Form 366A

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER (Include Area Code)
Michael Verrilli Sr. Analyst - Licensing	(919) 362-2303

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On April 24, 1994, while in refueling outage 5, the Residual Heat Removal Pump (RHR) control power fuses were removed as procedurally directed during surveillance testing. With the plant in Mode-6 (Refueling) and refueling cavity water level less than 23 feet, both RHR loops are required to be operable. Harris Plant Technical Specification (TS) Interpretation #90-1 provides additional guidance on RHR system operability and states that one RHR train is allowed to be removed from service as long as it is "capable of being manually aligned to the Reactor Coolant System and started from the main control board." With RHR pump control power fuses removed one at a time during testing, action outside the main control room would have been necessary to start the pump, thus resulting in a violation of RHR system TS operability requirements.

This condition was identified on September 30, 1995, during refueling outage 6, when Operations personnel performing the same RHR system testing, recognized that compliance with the surveillance procedural steps would result in a violation of TS requirements for RHR system operability. To avert this condition, testing was rescheduled and satisfactorily completed at a later time when the plant was in Mode-5 (Cold Shutdown), when TS allow a two hour inoperability period for surveillance testing. The cause of this event was procedural inadequacies, in that specific procedure steps directed the removal of RHR pump control power without considering the operability impact while in Mode-6 with cavity water level less than 23 feet. Corrective action included revising the deficient procedure.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Shearon Harris Nuclear Plant - Unit #1	50-400	95	014	00	2 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION:

On April 24, 1994, during refueling outage 5, with the plant in Mode-6 (Refueling), surveillance testing to verify the operability of Residual Heat Removal (RHR) System (EIIS Code: BP, CKV) check valves was in progress (OST-1508). As directed by OST-1508 procedure steps, the control power fuse was removed from the "A" Residual Heat Removal (RHR) pump (EIIS Code: BP, P) for approximately 21 minutes and then the "B" RHR pump for approximately 22 minutes (one at a time) to support testing. With the plant in Mode-6 with refueling cavity water level less than 23 feet, TS 3.9.8.2 requires both trains of RHR to be operable. Harris Plant TS Interpretation #90-1 provides additional guidance on RHR system operability for Mode-6 operation and states that one RHR train is allowed to be removed from service as long as it is "capable of being manually aligned to the Reactor Coolant System and started from the main control board." With control power fuses removed from either RHR pump, action outside the main control room would have been necessary to start the pump, thus resulting in a violation of RHR system TS operability requirements.

This condition was identified on September 30, 1995, during refueling outage 6 when operations personnel performing the same RHR surveillance test recognized that compliance with sections 7.3.2 and 7.4.2 of OST-1508, which directed the removal of control power fuses from the "A" and "B" RHR pumps, would result in a violation of TS requirements for RHR system operability. To avert this condition, sections 7.3.2 and 7.4.2 of OST-1508 were rescheduled and satisfactorily completed at a later time when the plant was in Mode-5 (Cold Shutdown), when TS allow a two hour inoperability period for surveillance testing. Subsequent review of previous performances of OST-1508 revealed the above described TS violation that occurred in April of 1994 during refueling outage 5. An extensive operability / reportability evaluation was performed, which concluded on December 14, 1995, that this condition did violate the requirements of TS 3.9.8.2 and Harris Plant TS Interpretation #90-01.

CAUSE:

The cause of this event was procedural inadequacies, in that specific procedure steps directed the removal of RHR pump control power fuses without considering the operability impact while in Mode-6 with cavity water level less than 23 feet. Due to the fact that the TS violation occurred 18 months prior to the investigation, contributing factors were difficult to determine, but had operations personnel performing the test in 1994 displayed the questioning attitude that resulted in identifying the procedure deficiency during the recent testing in 1995, the event may have been prevented.

SAFETY SIGNIFICANCE:

There were no significant safety consequences as a result of this event. One train of RHR was available and in operation to remove decay heat and the other train could have been restored in a short period of time by re-installing the pump control power fuses if needed.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		OF	
Shearon Harris Nuclear Plant - Unit #1	50-400	95	014	00	3	OF	3

TEXT *if more space is required, use additional copies of NRC Form 366A* (17)

PREVIOUS SIMILAR LERs:

No similar LERs have been reported pertaining to an inoperable RHR train during Mode-6 operation.

CORRECTIVE ACTIONS PLANNED:

Operation Surveillance Test OST-1508 will be revised to correct the procedure deficiency prior to its next use. This revision will be completed by February 15, 1996.

EIIS CODES:

Residual Heat Removal System - BP Component Codes: RHR Pump - P, Check Valves - CKV