CATEGORY

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSIO FACIL:5 AUTH.N VERRILL DONAHUE RECIP.	N NBR:9605210247 0-400.Shearon Harri AME AUTHOR A I,M. Carolina ,J.W. Carolina NAME RECIPIEN	DOC. is Nuc AFFILI Power Power NT AFF	DATE: lear H ATION & Liq & Liq ILIATI	96/05/16 Power Plan ght Co. ght Co. ION	NOTARIZE t, Unit l	D: NO , Carol	ina	DOCKET # 05000400	•
SUBJECT	: LER 96-002-05:on	96011	7,fail	ure to pe.	rform req	uired			C
	surveillance test identified.Caused	ing d by p	uring ersonr	planned material planned material planned material planned material planned material planned material planned m	aint outa Personnel	ge in O involv	ct 199 ed	94	A
	counseled.W/96051	.6 ltr	•				. 1		т
DISTRIB	UTION CODE: IE22T	COPIE	S RECE	IVED:LTR	ENCL	SIZE	.]		
TITLE:	50.73/50.9 Licensee	e Even	t Repo	ort (LER),	Incident	Rpt, et	tc.	·····	E
NOTES: A	pplication for perm	it re	newal	filed.				05000400	G
									0
	RECIPIENT	COPI	ES	RECIP	PIENT	COPI	IES		-
	ID CODE/NAME	LTTR	ENCL	ID COL	DE/NAME	LTTR	ENCL		ĸ
	PD2-1 PD	1	1	LE,N		1	1		Y
INTERNAL:	ACRS	1	1	AEOD/SPI	ARAB	2	2		-
	AEOD/SPD/RRAB	ī	ī	FILE CEN	TER	์เ	ĩ		
	NRR/DE/ECGB	ī	ī	NRR/DE/E	ELB	ī	ĩ		1
	NRR/DE/EMEB	1	ī	NRR/DRCH	I/HHFB	ī	ī		
	NRR/DRCH/HICB	1	ī	NRR/DRCH	I/HOLB	1	ī		
	NRR/DRCH/HOMB	1	1	NRR/DRPM	VPECB	1	ī		
	NRR/DSSA/SPLB	ī	ī	NRR/DSSA	SRXB	ĩ	ī		D
	RES/DSIR/EIB	ī	ī	RGN2 F	ILE 01	ī	ī		
			-		•-		-		0
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BR	YCE,J H	2	2		~
	NOAC MURPHY, G.A	1 ·	l	NOAC POC	RE,W.	1	1		C
	NRC PDR	1	1	NUDOCS F	ULL TXT	1	1		тт
									υ

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWFN 5D-5(EXT. 415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

ي transa farena farena artean arte

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 26

· · · · ·

.

e s e se

يعفر الأبريون الأعب

many and an enter a control Rate

М

Ε

Ν

т



Carolina Power & Light Company Harris Nuclear Plant PO Box 165 New Hill NC 27562 MAY 1 6 1996

U.S. Nuclear Regulatory Commission ATTN: NRC Document Control Desk Washington, DC 20555 Serial: HNP-96-084 10CFR50.73

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1 DOCKET NO. 50-400 LICENSE NO. NPF-63 LICENSEE EVENT REPORT 96-002-05

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed revision to Licensee Event Report 96-002 is submitted. This revision reports additional Technical Specification Testing deficiencies identified during the on-going Technical Specification testing program review.

Sincerely,

J. W. Donahue General Manager Harris Plant

MV

Enclosure

c: Mr. J. B. Brady (NRC - HNP) Mr. S. D. Ebneter (NRC - RII) Mr. N. B. Le (NRC - PM/NRR)

9605210247 960516 PDR ADUCK 05000400 S PDR

16:00

U: S. Nuclear Regulatory Commission Document Control Desk / HNP-96-084 Page 2 of 2

Ms. P. B. Brannan cc: Mr. R. K. Buckles (LIS) Mr. W. R. Campbell (BNP) Mr. J. M. Collins Mr. J. P. Cowan Mr. G. W. Davis Ms. S. D. Floyd Ms. S. F. Flynn Mr. H. W. Habermeyer, Jr. Mr. G. D. Hicks (BNP) Mr. M. D. Hill Mr. W. J. Hindman Mr. R. M. Krich (RNP) Ms. W. C. Langston Mr. C. W. Martin (BNP) Mr. R. D. Martin Mr. J. P. McKone Mr. J. W. Moyer (RNP) Mr. P. M. Odom (RNP) Mr. W. R. Robinson Mr. G. A. Rolfson Mr. C. T. Sawyer Mr. R. S. Stancil Mr. G. M. Stokes Mr. J. P. Thompson (BNP) Mr. T. D. Walt HNP Real Time Training INPO NLS File: HI/A-2D Nuclear Records

- 1 #

the way and a second of the second

•																••
NRC FORM	A 366			U.S. NUC	LEAR REG	GULATOR	Y COMM	ISSION			AP	PROVED BY O	MB NO.	3150-0	0104	
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)							ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATOR INFORMATION COLLECTION REQUEST: 500 HRS. REPORTED LESSONS LEARNED AN INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTR FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AN RECORDS MANAGEMENT BRANCH (T-5 F33, U.S. NUCLEAR REGULATORY COMMISSIO WASHINGTON, DC 205550001, AND TO THE PAPERWORK REDUCTION PROJECT (315 0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							MANDATOR LEARNED ARI TO INDUSTRY RMATION AND Y COMMISSION PROJECT (3150 3.		
FACILITY NAME (1)							KET	NUMBER	(2)		<u></u>	PAG	(3)			
	Harris Nuclear Plant Unit-1										5	0-400			1 01	= 9
TITLE (4)									<u>II</u>		<u></u>			<u> </u>	<u> </u>	
Failure to	o prop	oerly p	erform	Technical S	Specifica	ation su	rveillan	ce test	ing.							
EVENT	DATE	(5)		LER NUMBER	(6)	REP	ORT DAT	E (7)			0	THER FACILIT	IES INV	OLVED	(8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISIO NUMBE	n Month	I DAY	YEAR	FACI	UTY	NAME			DOCKET	050	2R 00
4	16	96	96	002	05	5	16	96	FACI	UTY	NAME			DOCKET NUMBER		
OPERATI	NG		THIS R	EPORT IS SUB	MITTED P	URSUAN	<u>,</u> т то тн	I E REQUI	REME	NT	S OF 10	CFR §: (Che	ck one c	or more)) (11)	
MODE (9)	<u> </u>	20.	2201(b) 2203(a)(1)		20.22	03(a)(2)(v	/)		×	50.73	a)(2)(i) a)(2)(ii)		50	.73(a)	(2)(viii) (2)(x)
POWER LEVEL (1	}	100%	20.	2203(a)(2)(i)		20.220	D3(a)(3)(i	i)	-+		50.73(a)(2)(iii)		73	.71	
			20.	2203(a)(2)(ii)		20.220	03(a)(4)			50.73(a)(2)(iv)			OT	OTHER		
			20.	2203(a)(2)(iv)		50.36	c)(2)		-+		50.73(a)(2)(vii)		or in NR	C For	n 366A
NAME	LICENSEE CONTACT FOR THIS LER (12)															
N	Aichae	el Verri	illi Sr	. Analyst - l	_icensing	9						(919)	362-2	303		
·			COMP	LETE ONE LINE	FOR EAG	сн сомр	ONENT F	AILURE	DESC	CRIE	BED IN .	THIS REPORT	(13)			
CAUSE	SYST	rem	COMPON	ENT MANUFAC	TURER	EPORTABLE TO NPRDS)RTABLE CAUS			E SYSTEM COMPONENT			MANUFACTURER			PORTABLE O NPRDS
									- 1				Í			
		SU	PPLEME	NTAL REPORT	EXPECT	ED (14)					EXF	ECTED	MONTH	D	AY	YEAR
X YES (If yes,	comple	te EXPE	ECTED S	UBMISSION D	ATE).		NO				SUBI DA	MISSION TE (15)	5	2	23	96
ABSTRACT	(Limit	t to 140	00 space	es, i.e., approxi	imately 15	single-sp	aced typ	ewritter	lines	s) ('	16)					
On Janua testing du was shut requireme 1084 werd 1CS-746 In Septem Mini-Flow OST-1084 Flow Isol	On January 17, 1996, during a Technical Specification testing program review, a failure to perform required surveillance testing during a planned maintenance outage in October, 1994 was identified. Specifically, on October 30, 1994, the plant was shut down and taken to Mode-5 (Cold Shutdown). This outage exceeded 72 hours and per Technical Specification requirements Engineered Safety Feature slave relay testing was required. To satisfy this requirement OST-1083 and OST- 1084 were satisfactorily completed, however the slave relay circuits for the CSIP Alternate Mini-Flow Isolation Valves, 1CS-746 and 1CS-752 were not tested due to an error that occurred during a procedure revision in June 1993. In September 1992, a plant modification was completed on the Charging/Safety Injection Pump (CSIP) Alternate Mini-Flow System that necessitated revisions to Operations Surveillance Test procedures OST-1083 and OST-1084. These revisions were completed in June 1993 and removed the slave relay testing for CSIP Alternate Mini- Flow Lord and LOS 746 error LOS 746 or CSIP Alternate Mini-															
procedure procedure 6 on Sept required to procedure Seven add	e OST- e revis ember upon i e revis litiona	-1809. ion pro 8, 19 dentific ions an	The cocess for 95. The cation and the pinical S	cause of the or OST-1083 his test verified of the deficient continuation Specification	Technica and OS ied the o ency. A of an in testing o	al Specif ST-1084. operabilit dditiona -progres leficienc	ication OST- y of the l correc s Techn ies (iter	violation 1809 v ese circontive active ical Sp ns 12-1	on was sicults, tions becifi	as j ucc thu ind cati	person essfull us no i cluded ion tes were	nel error dur y performed mmediate co personnel c ting program identified du	ring the during orrectiv ounseli n revie uring th	June g Refue e action ng, ap w.	1993 eling on wa prop	Outage as riate
comprehe	nsive	Techni	ical Sp	ecification te	esting pro	ogram re	eview a	nd are	bein	g re	eported	by this sup	plemen	ital rep	oort.	

ł

-

ł

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (I)	DOCKET		LER NUMBER (6)	PAGE (3)			
	50.400	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Shearon Harris Nuclear Plant - Unit #1	50-400	96	002	05		OF	a

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION:

On January 17, 1996, a failure to perform Technical Specification surveillance testing during an October 1994 planned maintenance outage was identified. The identification of this condition was a result of an on-going comprehensive Technical Specification testing program review that began in September 1995 following submittal of LER 95-07.

Specifically, on October 30, 1994, the plant was shut down and taken to Mode-5 (Cold Shutdown) for a planned maintenance outage. This outage exceeded 72 hours and therefore, per Technical Specification 4.3.2.1 requirements, Engineered Safety Feature (ESF) slave relay testing was required for the 13 ESF relays delineated in Table 4.3-2 that had not been tested in the last 92 days due to being at full power operations. To satisfy this requirement OST-1083 and OST-1084 were completed on November 3, 1994. However, the slave relay circuits for the CSIP Alternate Mini-Flow Isolation Valves (1CS-746 and 1CS-752, EIIS Code BQ-ISV) were not tested due to an error that occurred during procedure revisions performed in June 1993 on Engineered Safety Feature (ESF) 18-Month Slave Relay Operations Surveillance Test procedures OST-1083 and OST-1084. This error involved inappropriately removing the slave relay testing for the 1CS-746 and 1CS-746 and 1CS-752 circuits from OST-1083 and OST-1084 and transferring the testing requirement to procedure OST-1809 (Refueling Water Storage Tank switchover to the Containment sumps), which is also an 18-month ESF response time test. OST-1809 was not performed following the October maintenance outage, thus resulting in the testing omission and Technical Specification violation.

During the investigation of this event, personnel performing the Technical Specification testing program review verified that OST-1809 had been successfully performed during Refueling Outage 6 on September 8, 1995, which verified the operability of the affected circuits.

The June 1993 revisions to OST-1083 and OST-1084 were performed to incorporate a plant modification (PCR-6547) on the Charging/Safety Injection Pump (CSIP) Alternate Mini-Flow lines. This modification removed the previously installed relief valves and provided an "open" signal to 1CS-746 and 1CS-752 upon receipt of a Safety Injection signal.

This condition was determined to be a violation of the Technical Specification surveillance test periodicity requirement and is being reported per 10CFR50.73(a)(2)(i)(b).

The following additional Technical Specification testing deficiencies have been identified by the on-going comprehensive Technical Specification testing program review:

- Slave relays (K635 & K640) for the Auxiliary Feedwater (AFW) Flow Control Valves (EIIS BA-FCV) were not tested within their required quarterly surveillance interval following Refueling Outage (RFO) 5 in 1994 through RFO 6 in October 1995. This was a result of inadequate technical reviews associated with the plant modification (PCR-6502) that installed the auto-open signal to these valves. PCR-6502 specified the slave relay surveillance testing interval as once per 18 months per Technical Specification 4.7.1.2, but failed to identify the quorterly requirement contained in Technical Specification 4.3.2.1. Both of these relays were subsequently tested following RFO 6, which verified their operability. This condition was identified on February 1, 1996 with the plant operating in Mode-1 at 100% power.
- 2. Testing for manual Safety Injection (SI, EIIS-BQ) and Containment Spray (CS, EIIS-BE) actuation has not fully tested all switch contacts within the required 18 month surveillance test interval per Technical Specification 4.3.2.1. The Operations Surveillance Test Procedures (OST-1825 & OST-1826) that verify the operability of the actuation circuits, only test one of the two manual actuation switches for each signal once per 18 months, thus resulting in the Technical Specification violation. The alternate test switch has been satisfactorily tested approximately once per 36 months due to test performance staggering. Based on this previous testing, the SI and CS switches are currently operable. However, one set of CS switches will become inoperable on March 3, 1996 and one SI switch will become inoperable on March 19, 1996. This condition has existed since initial development of OST-1825 & OST-1826 and was identified on February 12, 1996 with the plant operating in Mode-1 at 100% power.

FORM 366A (4-95)

	TEXT CONTI	NUATION						
	FACILITY NAME (I)	DOCKET		<u>u</u>	R NUMBER (6	L PERCHAN		PAGE (3)
	Shearon Harris Nuclear Plant - Unit #1	50-400	YEAR 96		NUMBER	NUMBER 05	3	OF
TEXT P	1 more space is required, use additional copies of NRC Form 366AJ (17)	<u></u>					<u> </u>	
3.	Quarterly surveillance testing was not performed for the Valve (1CS-196) Slave Relay (K601) (EIIS Code BQ-IS should have been tested during the performance of OST and 1CS-196 was under clearance at the time of the considered satisfactory by the operations control room so OST-1086. The acceptance criteria, which was changed to test the 1CS-196 slave relay, so no Equipment Inop would have required subsequent testing. The operabilit OST-1086 in December 1995. This condition was identi- 1 at 100% power.	he "B" Chargin V,RLY) during (-1086 in Augu test. This was staff due to a d during a recen perable Record y of the slave 1 ified on Februar	g/Safet Refuel st of 1 as note eficience t proce was g relay w ry 17,	y Inj ing C 995, d in cy in edure enera as su 1996	ection P Dutage 6 but the ' the pro- the acce revision, ted for the ccessfull with the	ump Mir in 1995. 'B" CSIF cedure, I ptance cr did not racking j y verified plant ope	ii-Flo This was but th riteria specif purpo l by p erating	w Isol slave inope e test sectic y the ses, w perform g in M
4.	Eleven Maintenance Surveillance Test (MST) Procedures effluent pathway on a loss of power for the associate Technical Specification 4.3.3.10. This affected six ra omission was created when the MSTs were inappropriat that were thought to be redundant and unnecessary. I Technical Specification testing requirements for the rad requirements for these radiation monitors were removed time frame of the deficiency, the condition constitutes a This condition was identified on February 14, 1996 with	s were identified adiation monito ely revised in l nattention to de liation monitor from Technica violation and i the plant opera	d that conitor (rs and 993 in ctail an circuitr l Speci s there tting in	lid no EIIS their an e d an y can ficati fore i Mod	ot verify Code II related ffort to a incompl used the ons in N included le-1 at 10	automatic -MON) pathways liminate ete under deficienc fay 1995 in this L 00% pow	isola as re s. T proce rstand cy. T , but ER su er.	tion of equired his tes dure s ing of The tes due to applem
5.	Proper overlap testing has not been performed for a Ventilation System (EIIS-VG) originating from a high ra OST-1048 tests this feature, but does not include a partic Fuel Pool Radiation Monitor (RM-1FR-3567A-SA, EIIS Monitor (RM-1FR-3564A-SA). This condition has exist on February 19, 1996 with the plant operating in Mode satisfied by the current operability of other FHB radiatio	n actuation of adiation alarm s ular section of o S Code IL-MO ed since initial e-1 at 100% pc n monitors.	the F ignal, cable (# N) and develop ower.	uel I as pe /1291 the oment Tech	Handling r Technio 3M-SA) South Sp of OST nical Spe	Building cal Speci between ent Fuel -1048 an ecification	g Eme fication the N Pool d was n com	ergenc on 4.9 orth S Radia identi oplianc
6.	Logic testing for the Control Room Emergency Filtr inadequately verified all automatic fan start signals asso and 1826 have properly verified that the fans automatic however, the operability of a parallel circuit path that p been verified during past testing. This condition has ex procedures and constitutes a violation of Technical Spec was identified on February 22, 1996 with the plant opera	ation Fans (R- ciated with a C ally start upon provides an aut isted since initi- ification 4.3.2. ating in Mode-1	2 "A" ontrol i receipt omatic al deve 1. surv at 100	and Room of a start lopm cillan 0% po	"B", E I Isolatio safety in signal o ent of th ice requi	IIS Code n Actuati njection a n high ra e applica rements.	e VI- on. actuati adiatic ble su This	FAN) OST-1 on sig on has irveilla condi
7.	Logic testing for the Reactor Auxiliary Building Electric: (1CZ-7 & 1CZ-8, EIIS Code VF-V) has not properly v valves receive a thermal overload bypass signal from Signal and a signal from the Emergency Safeguards operability these circuits from the Emergency Safeguards bypass circuit for Control Room Isolation has not been This constitutes a violation of Technical Specification 4. since initial surveillance procedure development and was Mode-1 at 100% power.	al Equipment P erified the oper two parallel so Sequencer. Su ds Sequencer. verified when 3.2.1 surveillar s identified on F	rotectic ability urces; urveilla Howey the sig ace req Februar	on Ro of ea a Co nce (yer, a gnal i uiren y 26,	oom Inlet ach actua introl Ro testing h portion is genera ients. T 1996 w	Isolation tion circu om Vent as prope of the th ted from his condi ith the pl	Valv lit par liatior rly ve herma high tion h ant op	es th. The sola erified lover radiat as exi peratin
8.	Trip Actuating Device Operational Testing has not bee signal following a safety injection actuation. OST-1825 Main Feedwater Pumps trip, but due to the process invo and installing jumpers in Auxiliary Relay Panel (ARP-10 has not been verified. This testing deficiency has ex constitutes a violation of Technical Specification 4.3.2.1	n adequately per actuates the saf blved during thi bly EIIS Code SJ tisted since init surveillance re	erforme ety injo s testin -PL), s ial sur quirem	ed fo ection ig, wi a sect veilla ents.	r the Ma switch hich inclu- tion of ir ince proof This cor	in Feedy and then udes liftin ternal with tedure du tedure with	vater verifi ng sev iring i evelop as ide	Pump es that /eral le in ARI oment ntified

∾∎ 193 ∎

* · · · ·

1145

1 46° 18

1.00. K 377 WA 92 -

· -1

2

NRC FORM 366A (4-95)

≠, 4 4 4 4 ** ter in tak ۲

•

֥

ĥ

NRC FO	RM 366A			<u> </u>	U.S	. NUCLEAR R	EGULATO	RY COMM	LISSION			
14-221	LICENSEE EVENT	REPORT (LER)										
	FACILITY NAME (1) DOCKET LER NUMBER (5) PAGE (3)											
			YEAR	SEQUENTIAL REVISION NUMBER NUMBER								
	Shearon Harris Nuclear Plant - Unit #1	50-400	96	·· 002	••	05	4	OF	9			
TEXT Ø	more space is required, use additional copies of NRC Form 3664/ (\1)	<u>1</u>	u			<u></u>	<u></u>					
9.	Ten Maintenance Surveillance Test Procedures were id test or control room annunciation verification on the effl IL) as required by Technical Specification 4.3.3.11, Tab of the applicable surveillance test procedures and was id 1 at 100% power.	lentified that did luent channels of ole 4.3-9. This c entified on March	not p four ondition h 11,	erform a c separate rac on has exist 1996 with t	han diati ted he j	nel out o ion mon since ini plant ope	of ser itors (tial de erating	vice a (EIIS (evelop) g in M	larm Code ment lode-			
10.	Surveillance testing has not been performed to proper Emergency Safeguards Sequencer (ESS) Panels. (EIIS C components start from the sequencer's load block pro- preventing non-essential safety loads from energizing d existed since initial surveillance procedure developmed surveillance requirement 4.8.1.1.2. This condition wa Mode-1 at 100% power, and at 1500 hours both Emer Technical Specification 4.0.3 was entered, which allow Special surveillance test procedures (OST-9018T and OS hours on the next day, March 22, 1996, testing to demo entered Technical Specification 3.0.3, which required commenced a load decrease to comply with this required Mode-3 was achieved. Testing was completed to verify 22, 1996 and for the B-train sequencer at 1430 on Marc	ly verify the op Code EK-PL,RLN Ogram by blocki luring load block ent and constitu- s identified on N orgency Sequence wed 24 hours to ST-9019T) were onstrate sequence shutdown to M ement. At 2139 proper operation th 23, 1996.	erabili Y) Th ng no is I th ites a March ers we demo develor ode-3 b, the n of th	ity of four nese relays rmal proce rough 8. violation 21, 1996 ere declare oped to per rability was by 2200 H plant was e A-train s	teen fun ss Thi of with crab for is no nour take	blockin ction to demand s testing Technica h the pla noperabl ility of m this ta t comple rs. At n off lin encer at	ig rel ensure signa g defic al Sp ant op e. Du the se esting. etc, so 1804, ne and 2336	ays in e that ils and ciency ecifica peratin ue to equence. At 1 o the I the I d at 2 on M	the ESF by has ition g in this, cers. 1500 plant plant 152, arch			
.1.	Surveillance testing has not been performed to verify pro Dampers (CV-D1, CV-D3, CV-D5, CV-D7 / EIIS Code Emergency Safeguards Sequencer and directly from the a testing did not verify operability of the signal circuitry or of a parallel path within the start signal circuitry from t dampers were actually open. This condition was ide shutdown in Mode-5 (Cold Shutdown). This const requirement 4.6.2.3. To verify operability of these dat 1996. This testing identified that two of the post-acci closed. Following lubrication of one damper and a min actuator, satisfactory results were obtained and the dan service on March 28, 1996.	oper operation of VA-DMP). The associated fan co- riginating from the he four fan cool- entified on Marce titutes a violation mpers, testing we ident dampers d nor modification mpers and their a	f the C ese da oler st ie sequ er uni h 26, on of as der id not to inc associa	Containmen impers rece arting circu iencer, fail ts and did 1996, at Technical veloped and fully oper crease the o ted fan co	t Fa ive iitry ed t not Sp d po n as outp oler	in Coole an open . Previo o consid properly ich time ecification erformed s require out of th units w	r Pos signa ous su er the verif the on su l on l ed and vere r	t-Accid I from Irveilla exists fy that plant Irveilla March I retune er dan returne	dent the ance ence t the was ance 27, rned nper od to			
2.	Surveillance testing has not been performed to verify pro Services Chilled Water Chillers (WC2A-SA &B-SB, EII Emergency Safeguards Sequencers. Test procedures condition was identified on April 16, 1996 with the deficiency has existed since initial surveillance proceed Specification surveillance requirement 4.8.1.1.2.	oper operation of S Code: KM -CI have not docum plant operating fure developmen	f one i HU) fi in ented in Me it and	relay contac rom starting verificatio ode-1 at 10 constitutes	et th g un n c 00% g a	at inhib itil load of this p 6 power violatio	its the block roces . Tl n of	Esser #8 on s. his tes Techr	ntial the This sting nical			
13.	Surveillance testing has not been performed to verify precycle feature for starting the Essential Services Chilled The anti-recycle feature prevents more than one chiller purposes. This anti-recycle feature is bypassed upon Safeguards Sequencer. Verification of this bypass func condition was identified on April 16, 1996 with the deficiency has existed since initial surveillance proceed Specification surveillance requirement 4.8.1.1.2.	proper operation 1 Water Chillers r start within a receipt of an a stion has not been plant operating dure development	of a (WC2 30 minutoma n inclu in Mont and	relay conta A-SA &B- inute period atic start si uded in pas ode-1 at 1 constitutes	ict i SB, d fo igna igna it su 00% s a	that byp EIIS Co or equip: 1 from 1 rveillan 5 power violatio	asses ode K ment the F ce tes . TI n of	the a M-CH protect imerge sting. ' his tes Techr	anti- IU). xtion ency This sting nical			

1

NRC FORM 366A (4-95)

Ľ

. .

•

.

NRC FOR	M 366A		-			U.S.	NUCLEAR R	EGULATO	RY COMM	ISSION	
(4-95)	LICENSEE EVENT										
	· · · TEXT CONTI	NUATION									
L											
	· · · · · · · · · · · · · · · · · · ·		YEAR		SEQUENTIA		REVISION				
	Shearon Harris Nuclear Plant • Unit #1	50-400	96	••	002		05	5	OF	9	
TEXT Ø	more space is required, use additional copies of NRC Form 366AJ (17)		!!								
14.	Surveillance testing has not been performed to verify swapover logic. The Containment Spray Pump Refuel 71SB) receive an automatic shut signal when their respo position as indicated via contacts on their full open lim using a switched jumper that simulates limit switch oper been verified. This condition was identified on April 17 This testing deficiency has existed since initial surveil	proper operation ing Water Stora ective Containm it switches. Th ation. Therefor 7, 1996 with the lance procedure	n of the ge Tan ent Sun is limit e, conti e plant develo	e C np sw inui ope	Contain Suction Suction vitch fu ity thro erating nent an	men Val n Va ncti ough in N d co	t Spray ves (10 lves rea on has the lim fode-1 onstitute	auton CT-26S ich the been v it swit at 100 s a vi	A &1 A &1 e full overified ch has % pov olation	ump CT- open d by not wer. n of	
15.	Technical Specification surveillance requirement 4.3.2.1. Surveillance testing has not been performed to verify proper operation of the Containment Spray Pump sump suction valves (1CT-105SA &1CT-102SB, EIIS Code BE- V) following actuation of relay K741. These valves receive an automatic open signal on Refueling Water Storage Tank (RWST) Lo-Lo level via slave relays K739 and K741. A parallel path exists from each of these relays and past surveillance testing has only verified proper operation of the suction valves from the K739 relay. This condition was identified on April 17, 1996 with the plant operating in Mode-1 at 100% power. This testing deficiency has existed since initial surveillance procedure development and constitutes a violation of Technical Specification surveillance requirement 4.3.2.1.										
16.	Surveillance testing has not been performed to verify proper operation of the Computer Room Dampers adjacent to the Main Control Room, following a Control Room Isolation Signal. These dampers (CK-D7-1&2, CK-D4-1&2, CK-D8-1&2 and CK-B11-1&2, EIIS Code VI-DMP) receive a signal from relay K603 to place the Computer Room in Recirculation, but have not been included in previous surveillance testing. This condition was identified on April 17, 1996 with the plant operating in Mode-1 at 100% power. This testing deficiency has existed since initial surveillance procedure development and constitutes a violation of Technical Specification surveillance requirement 4.3.2.1.										
17.	Surveillance testing has not been performed to verify p various Computer and Communication Room HVAC con These components receive actuation signals following a 0 previous surveillance testing. This condition was identif 100% power. This testing deficiency has existed since violation of Technical Specification surveillance requirem	proper operation aponents in addi Control Room Is ied on April 17 initial surveillar nent 4.3.2.1.	of the tion to olation 1996 ce pro	the Sig with ced	ontrol dampe gnal, bu h the p ure de	Roo ers li ut ha lant veloj	m Isola isted in ive not l operatin pment a	tion S item # been in ng in I and co	ignal 16 abc aclude Mode- nstitute	for ove. d in 1 at es a	
21.	Surveillance testing has not been performed to verify properties adjacent to the Main Control Room, following a Contesting have only been verified by observation of "not-s 26, 1996 with the plant operating in Mode-1 at 100% surveillance procedure development and constitutes a v 4.3.2.1. Due to an administrative oversight during the contest was not included in Revision #3 to this LER as it to the reportability determination process has been enhanced (Note: Failure to initially identify this reportable conditional numerical sequence of identified deficiencies. Items 18	roper operation owing a Control trol Room Isola hut" indication. 6 power. This iolation of Tech on-going Technic should have bee ed to prevent re ition and includ - 20 will be incl	of the Room tion Sig This testing nical S cal Spec n to m currenc le it in uded in	Con Iso gnal co g d Spec cific eet e. n R n a	mputer lation S l and c ndition eficienc cificatio cation the 30 evision future	Roo Signa lurin was cy ł on s testi day -day revi	om and al. Thes ag previ- s identif has exis urveillan ng progra reporti- caused sion to	Comm e dam ous su ied on ted sin nce re ram re ng req a bre this Ll	nunica pers ((rveilla Febru nce in quiren view, uirem ak in ER.)	tion CK- ince iary itial nent this ent. the	

NRC FORM 366A (4-95)

* *

'n

y V

٤

• ---

à

.

• • • • • • • •

· · · ·

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

FACILITY HAME (1)	DOCKET		LER NUMBER (6)	PA	PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		or	•
Shearon Harris Nuclear Plant - Unit #1	50-400	96	002	05	б	UF	ษ

TEXT (If more space is required, use additional copies of NRC Form 366AU (17)

CAUSE:

The cause of the original Technical Specification violation was personnel error during the June 1993 procedure revision process for OST-1083 and OST-1084. The testing requirements for the slave relay circuits for the CSIP Alternate Mini-Flow Isolation Valves (1CS-746 and 1CS-752) were inappropriately transferred to OST-1809, which was not identified or scheduled as a Mode-5 "event related" surveillance test.

Cause For Additional Items Identified:

Item 1:

The failure to adequately test the K635 and K640 slave relays for the AFW Flow Control Valves was caused by inadequate technical reviews associated with plant modification PCR-6502. This resulted in deficient surveillance test procedures developed to verify the operability of the automatic open signal for the flow control valves on a quarterly basis.

Items 2, 3, 4, 5:

Each of these items were caused by inadequate surveillance test procedures that resulted from incorrectly interpreting how to implement Technical Specification testing requirements. The test procedures for the Safety Injection and Containment Spray manual actuation switches, as well as the FHB Emergency Ventilation system, were based upon this incorrect interpretation, and have been deficient since initial development. The radiation monitor MST revisions completed in 1993, were intentionally performed to eliminate what was considered to be redundant and unnecessary testing steps. This decision was also based on the incorrect testing requirement interpretation, as was the revision to OST-1086 that resulted in the acceptance criteria section not listing 1CS-196, and subsequently resulting in the failure to test the valve.

Items 6, through 17 and 21:

Each of the additional items contained in the revisions to this LER were identified as a result of the on-going Technical Specification testing program review and were caused by inadequate surveillance test procedures. In the case of item #11, the two post-accident dampers failed to fully open during testing due to improper actuator sizing and inadequate lubrication and preventive maintenance methods.

SAFETY SIGNIFICANCE:

There were no adverse safety consequences as a result of this event. The CSIP Alternate Mini-Flow Isolation Valve circuits were tested satisfactorily on September 8, 1995 to verify operability. This testing provides confidence that had an accident occurred requiring CSIP mini-flow protection due to the re-pressurization of the Reactor Coolant System during a safety injection, the isolation valves would have opened to prevent pump damage.

There were no adverse safety consequences as a result of the additional items contained in this LER revision. In each case where applicable, subsequent testing was performed that verified the operability of the effected component or circuit. In the case of item #11, where two of the Containment Fan Cooler Post-Accident Dampers failed to completely open during testing, consequences are still under investigation and will be provided in a supplement to this report. These dampers are required to be open in a post-accident condition within containment to allow a high velocity fan discharge flow to selected areas of containment to accelerate temperature mixing and heat removal. Assuming the failure of these two dampers to open during an accident scenario, combined with the postulated worst case single failure of one safety related electrical supply bus, preliminary engineering review has determined that adequate air flow would still exist to ensure containment cooling. This is based on the availability of one train of Containment Spray and the fact that one fan would remain operable in each Containment Fan Cooler unit. The discharge air flow from each fan would not exit through the post-accident dampers, but would still provide air mixing in containment via the seismic class 1 concrete air shafts.

PREVIOUS SIMILAR EVENTS:

Previous events have been submitted as LERs related to surveillance testing deficiencies caused by procedural inadequacies. LER 95-07, which was submitted on September 28, 1995, contained a corrective action to perform a comprehensive Technical Specification testing program review and it was during this review process that the CSIP Alternate Mini-Flow Isolation Valve condition was identified. This review is being performed by a multi-discipline team and is still in progress.

The additional items reported in this supplement were identified as a result of the on-going Technical Specification testing program review.

and the standard of the standard often standard of the standard often standard of the standard of the standard of the standard

N



NRC FORM 366A 14-951 LICENSEE EVENT REPORT (LER) TEXT CONTINUATION FACILITY NAME (1) DOCKET YEAR 50-400 Shearon Harris Nuclear Plant - Unit #1 96 .-TEXT Of more space is required, use additional copies of NRC Form 366AU (17) Item 6: MST-I0359 and MST-I0361 were revised on February 21, 1996 and successfully performed. This verified the operability of the parallel R-2 fan start circuit on high radiation. Item 7: OST-9017T was developed and successfully performed on February 27, 1996. This verified the operability of the thermal overload bypass circuit used during the Control Room Isolation Signal when generated from high radiation. To ensure compliance, future testing of this circuit will be incorporated with a revision to the appropriate maintenance surveillance test procedures or a newly developed operations surveillance test procedure. Item 8: OST-1825 and OST-1826 will be revised to properly test appropriate internal wiring in ARP-10. Item 9: чн Дуга Immediate corrective actions included declaring the affected radiation monitors inoperable and placing the deficient MST procedures on administrative hold until they could be revised. These procedures were subsequently revised and performed as needed to properly demonstrate the operability of the radiation monitors. This was completed on March 14, 1996. Item 10: Immediate corrective actions for this item included declaring both Emergency, Safeguards Sequencers inoperable and complying with the testing and plant shutdown requirements of Technical Specification 4.0.3 and 3.0.3. Testing was completed to verify operability of the A-train sequencer at 2336 on March 22, 1996 (OST-9018T) and for the B-train sequencer at 1430 on March 23, 1996 (OST-9019T). To ensure compliance, the appropriate surveillance test procedures will be revised to include future testing of the blocking relays.

Item 11:

Following corrective maintenance, which included a modification to increase the actuator spring rate for damper 1CV-D1, testing was satisfactorily performed on March 28, 1996 and the post accident dampers and their associated fan cooler units were returned to service. Preventive maintenance for these dampers was enhanced by generating a checklist (CL-ME0023) that includes requirements for periodic lubrication and inspection. This was completed on 4/19/96. To ensure compliance, the appropriate surveillance test procedures will be revised to include future testing of the post-accident dampers.

U.S. NUCLEAR REGULATORY COMMISSION

8

REVISION NUMBER

05

PAGE (3)

OF

9

LER NUMBER (6)

SEQUENTIAL

NUMBER

002

Items 12 & 13:

Immediate corrective actions for these items included declaring both Essential Services Chilled Water Chiller units inoperable. Testing (OST-9020T and EPT033) was then satisfactorily completed on April 16, 1996 to verify operability of both chiller units. To ensure compliance, the appropriate surveillance test procedures will be revised to include future testing of the chiller unit inhibit and anti-recycle bypass functions.

Item 14:

No immediate operability concern existed as a result of this condition due to the performance of a special test (OST-1809T) performed on June 6, 1995. To ensure compliance, the appropriate surveillance test procedure(s) will be revised to include future testing of the limit switch function/continuity.

FORM 366A (4-95)

l	NRC FORM	366A
Ш	11 001	

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET		LER NUMBER		PAGE (3)			
Shearon Harris Nuclear Plant • Unit #1	50.105	YEAR	SEQUENTIAL NUMBER		REVISION NUMBER		<u> </u>	
	50-400	96	002	••	05	9	UF	9

TEXT Of more space is required, use additional copies of NRC Form 366AJ (17)

Item 15:

ź

No immediate operability concern existed as a result of this condition due to the performance of quarterly surveillance testing (OST-1083 &1084) performed on March 26, 1996, which verified actuation of valves 1CT-102 and 1CT-105. To ensure compliance, the appropriate surveillance test procedure(s) will be revised to include future testing of the actuation signal from both slave relays.

Item 16 & 17:

Testing was performed on April 17, 1996 to verify the proper operation of the Computer and Communication Room HVAC components following a Control Room Isolation Signal (MST-I0362). To ensure compliance, the appropriate surveillance test procedure(s) will be revised to include future testing of these dampers.

Item 21:

Testing was performed on February 26, 1996 to verify proper operation of dampers CK-D11-1&2 and CK-D12-1&2 (OST-9017T). To ensure compliance, the appropriate surveillance test procedure(s) will be revised to include future testing of these dampers.

EIIS CODES:

High Head Safety Injection: BQ Auxiliary Feedwater Flow Control Valves: BA-FCV Containment Spray: BE Containment Ventilation: VA Fuel Handling Building Ventilation: VG Control Room Emergency Ventilation: VI Reactor Auxiliary Building Ventilation: VF Main Feedwater: SJ Radiation Monitoring: IL Emergency Sequencers: EK

FORM 366A (4-95)

· · · . .

4 * * * * . · · ·

. .

.

•