

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9612270151 DOC. DATE: 96/12/23 NOTARIZED: NO DOCKET #  
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400  
 AUTH. NAME AUTHOR AFFILIATION  
 VERRILLI, M. Carolina Power & Light Co.  
 DONAHUE, J.W. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 96-022-00: on 961122, wiring discrepancy was found in auxiliary building ventilation sys circuitry. Caused by personnel error. Training on this event will also be performed for appropriate maintenance. W/961220 ltr. C  
A  
T  
E

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. E

NOTES: Application for permit renewal filed. 05000400 G

	RECIPIENT ID CODE/NAME	COPIES LTRR ENCL	RECIPIENT ID CODE/NAME	COPIES LTRR ENCL	
	PD2-1 PD	1 1	LE, N	1 1	O
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	Y
	AEOD/SPD/RRAB	2 2	FILE CENTER	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EEEB	1 1	1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1	
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1	
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1	
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1	D
	RES/DET/EIB	1 1	RGN2 FILE 01	1 1	O
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1	O
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1	C
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	U

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTRR 26 ENCL 26

A04



Carolina Power & Light Company  
Harris Nuclear Plant  
PO Box 165  
New Hill NC 27562

MAR 20 1996

U.S. Nuclear Regulatory Commission  
ATTN: NRC Document Control Desk  
Washington, DC 20555

Serial: HNP-96-210  
10CFR50.73

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1  
DOCKET NO. 50-400  
LICENSE NO. NPF-63  
LICENSEE EVENT REPORT 96-022-00

Sir or Madam:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report describes a wiring discrepancy found in the Reactor Auxiliary Building Ventilation System.

Sincerely,

J. W. Donahue  
Director of Site Operations  
Harris Plant

MV

Enclosure

c: Mr. J. B. Brady (HNP Senior NRC Resident)  
Mr. S. D. Ebnetter (NRC Regional Administrator, Region II)  
Mr. N. B. Le (NRC - NRR Project Manager)

9612270151 961223  
PDR ADOCK 05000400  
S PDR

IE'22/1

U. S. Nuclear Regulatory Commission  
Document Control Desk / HNP-96-210  
Page 2 of 2

cc: Mr. R. T. Biggerstaff  
Ms. P. B. Brannan  
Mr. H. K. Chernoff (RNP)  
Mr. B. H. Clark  
Mr. J. M. Collins  
Mr. G. W. Davis  
Ms. S. F. Flynn  
Mr. H. W. Habermeyer  
Mr. M. D. Hill  
Mr. W. J. Hindman  
Ms. C. W. Hobbs (HEEC)  
Ms. W. C. Langston  
Mr. C. W. Martin (BNP)  
Mr. R. D. Martin  
Mr. J. W. McKay  
Mr. P. M. Odom (RNP)  
Mr. W. R. Robinson  
Mr. G. A. Rolfson  
Mr. R. F. Saunders  
Mr. R. S. Stancil  
Mr. C. N. Sweely  
Mr. M. A. Turkall  
Mr. J. P. Thompson (BNP)  
Mr. T. D. Walt  
Mr. R. L. Warden (RNP)  
HNP Real Time Training  
INPO  
Harris Licensing File  
Nuclear Records

**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Harris Nuclear Plant Unit-1

DOCKET NUMBER (2)

50-400

PAGE (3)

1 OF 3

TITLE (4)

Wiring discrepancy found in Reactor Auxiliary Buiding Ventilation System circuitry.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	22	96	96	-- 022	-- 0	12	23	96		
									FACILITY NAME	DOCKET NUMBER
									FACILITY NAME	DOCKET NUMBER
										05000

  

OPERATING MODE (9)	1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more) (11)							
POWER LEVEL (10)	100%	20.2201(b)	20.2203(a)(2)(v)	<input checked="" type="checkbox"/>	50.73(a)(2)(i)	50.73(a)(2)(viii)			
		20.2203(a)(1)	20.2203(a)(3)(i)		50.73(a)(2)(ii)	50.73(a)(2)(x)			
		20.2203(a)(2)(i)	20.2203(a)(3)(ii)		50.73(a)(2)(iii)	73.71			
		20.2203(a)(2)(ii)	20.2203(a)(4)		50.73(a)(2)(iv)	OTHER			
		20.2203(a)(2)(iii)	50.36(c)(1)		50.73(a)(2)(v)	Specify in Abstract below or in NRC Form 366A			
		20.2203(a)(2)(iv)	50.36(c)(2)		50.73(a)(2)(vii)				

LICENSEE CONTACT FOR THIS LER (12)

NAME

Michael Verrilli Sr. Analyst - Licensing

TELEPHONE NUMBER (Include Area Code)

(919) 362-2303

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).

NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On November 22, 1996, with the plant operating in Mode 1 at 100% power, a wiring lead was found incorrectly terminated in the Reactor Auxiliary Building Ventilation System. This lead was landed on the wrong relay terminal on August 27, 1996 during installation of a plant modification. The incorrect wiring configuration did not result in any plant transients, alarms or actuations, but did provide a parallel power supply source to two relays which are required to deenergize following a safety injection signal. With the lead landed in the wrong location, the parallel power source would become energized upon receipt of a certain main control room alarm. On November 12, 1996, this alarm occurred resulting in energizing the two relays. With these relays energized from the parallel power supply source, twenty-six A-train dampers that isolate the non-safety related portions of the RAB Ventilation system from the safety-related portion, would not have closed to perform their safety function following a safety injection signal. The relays remained energized until the wiring discrepancy was discovered and corrected on November 22, 1996. The corresponding B-train dampers were operable throughout this period and would have performed the safety related isolation function.

This event was caused by personnel error on the part of the maintenance technician that incorrectly terminated the wiring lead and the quality control technician that verified the work to be correct.

Immediate corrective actions included properly terminating the wiring lead and counseling the involved individuals. Training on this event will also be performed for appropriate maintenance and quality control personnel.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Shearon Harris Nuclear Plant - Unit #1	50-400	96	022	00	2 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**EVENT DESCRIPTION:**

On November 22, 1996, with the plant operating in Mode 1 at 100% power, a wiring lead from annunciator relay E1(2/3151) was found incorrectly terminated in Auxiliary Relay Panel 2A-SA in the Reactor Auxiliary Building Ventilation System circuitry (EHS Code:VF-RLY). This lead was incorrectly landed on terminal #2 of relay G1(52X2/3177) instead of terminal #1 on August 27, 1996 during installation of a plant modification. The incorrect wiring configuration did not result in any plant transients, alarms, or actuation, but did allow a parallel power supply to the G1 and J1(52X1/3177) relays. With the lead landed in the wrong location, the parallel power source would become energized upon receipt of a RAB Ventilation System alarm located in the main control room on the Auxiliary Equipment Panel (AEP-1).

This path remained deenergized during the time period that no alarm signal was present. However, on November 12, 1996, at approximately 1759 hours, a clearance was placed on one of the twenty-seven A-train RAB Ventilation System dampers that isolate the non-safety related portions of the RAB Ventilation system from the safety-related portion following a safety injection signal. This caused the E1 annunciator relay to energize as expected, which providing a HVAC trouble alarm on AEP-1. This energized the parallel path to the G-1 and J-1 relays. With these two relays energized the other twenty-six A-train RAB dampers would not have closed to perform their safety function following a safety injection signal.

On November 22, 1996 the RAB normal exhaust fans were secured to allow un-related maintenance. Operations personnel observed that the A-train RAB isolation dampers did not shut as expected with all fans secured. Investigation into this condition revealed the wiring discrepancy in ARP 2A-SA. At 1443 hours, the lead was landed correctly restoring the ability of the A-train RAB dampers to perform their safety function following a safety injection signal.

The period of time between November 12, 1996 (1759 hours) and November 22, 1996 (1443 hours) when the lead was incorrectly landed and the relays were energized, exceeded the seven day allowed outage time for the RAB Emergency Exhaust System per Technical Specification 3.7.7.

**CAUSE:**

The cause of this event was personnel error on the part of the maintenance technician that incorrectly terminated the wiring lead in ARP 2A-SA and the quality control technician that verified the work to be correct. Proper self-checking techniques were not applied. Both individuals are experienced utility personnel and the work package that was being used provided adequate guidance.

**SAFETY SIGNIFICANCE:**

The safety consequences associated with this event were minimal. The wiring discrepancy affected only the A-train RAB Ventilation System dampers. The B-train dampers were available to perform the safety function of isolating the non-safety related portion of the system from the safety-related portion.

This condition is being reported in accordance with 10CFR50.73.a.2.i.B. as a violation of Technical Specification 3.7.7.

**PREVIOUS SIMILAR EVENTS:**

There have been no previous similar personnel error events reported due to incorrectly landed leads which resulted in disabling a safety function and subsequent Technical Specification violation.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Shearon Harris Nuclear Plant - Unit #1	50-400	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		96	022	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**CORRECTIVE ACTIONS COMPLETED:**

1. The wiring discrepancy in ARP 2A-SA was discovered and corrected on November 22, 1996.
2. A review of other leads landed while installing the plant modification in August 1996 was performed during the event investigation. No other problems were identified.
3. The Maintenance and QC individuals involved were counseled following the event.

**CORRECTIVE ACTIONS PLANNED:**

1. The involved individuals will provide training on this event to other appropriate Maintenance and QC personnel. This training will be completed by January 31, 1997.