# CATEGORY 1

### REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR	9704030123 DOC.DATE: 97/03/31 NOTARIZED: NO	DOCKET #
FACIL:50-400	Shearon Harris Nuclear Power Plant, Unit 1, Carolina	05000400
AUTH.NAME	AUTHOR AFFILIATION	
VERRILLI,M.	Carolina Power & Light Co.	
DONAHUE, J.W.	Carolina Power & Light Co.	
RECIP.NAME	RECIPIENT AFFILIATION	

SUBJECT: LER 97-003-00:on 970227, steam generator low level protection circuitry outside design basis occurred. Caused by inadequate failure modes & effects analysis performed as-built piping configuration for S/G level. Review performed. W/970331 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR \_ ENCL \_ SIZE: \_\_\_\_\_ TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Application for permit renewal filed.

	RECIPIENT	COPII	ES	RECIPIENT	COP	ES	0
	ID CODE/NAME PD2-1 PD	LTTR 1	ENCL 1	ID CODE/NAME LE,N	LTTR 1	ENCL l	R
ΤΝΠΕΡΝΛΪ	ACRS	1	ı	AEQD <del>/S</del> PD/RAB	2	2	Y
2112221123	AEOD/SPD/RRAB	ī	1 /	FILE CENTER	ī	ī	
	NRR/DE/ECGB	ī	1 6	NRR/DE/EELB	ĩ	1	_
	NRR/DE/EMEB	1	1	NRR/DRCH/HHFB	1	1	1
	NRR/DRCH/HICB	1	1	NRR/DRCH/HOLB	1	1	•
	NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1	
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1	-
	RES/DET/EIB	1	1	RGN2 FILE 01	1	1	D
		7	-	TIMCO DOVOR I U	٦	1	0
EXTERNAL:	L ST LOBBI WARD	1	1	DITCO BRICE, O H	1	* 7	
	NOAC POORE,W.	T	T	NOAC QUEENER, DS	Ť	1 -	Ċ
	NRC PDR	1	1	NUDOCS FULL TXT	1	1	<u> </u>

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

AOY

C

Α

т

Ε

G

U

M

Ε

Ν

т

05000400



Carolina Power & Light Company Harris Nuclear Plant PO Box 165 New Hill NC 27562

MAR 31 1997

U.S. Nuclear Regulatory Commission ATTN: NRC Document Control Desk Washington, DC 20555 Serial: HNP-97-071 10CFR50.73

IE22 |

# SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1 DOCKET NO. 50-400 LICENSE NO. NPF-63 <u>LICENSEE EVENT REPORT 97-003-00</u>

#### Sir or Madam:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report describes a condition determined to be outside the design basis of the plant, related to Steam Generator low level protection circuitry.

Sincerely,

J. W. Donahue Director of Site Operations Harris Plant

MV

c:

Enclosure

Mr. J. B. Brady (HNP Senior NRC Resident) Mr. L. A. Reyes (NRC Regional Administrator, Region II) Mr. N. B. Le (NRC - NRR Project Manager)

970403C123 970331 PDR ADUCK 05000400 S PDR

030043

U. S. Nuclear Regulatory Commission Document Control Desk / HNP-97-071 Page 2 of 2

Mr. T. C. Bell bcc: Mr. H. K. Chernoff (RNP) Mr. B. H. Clark Mr. J. M. Collins Mr. G. W. Davis Ms. S. F. Flynn Ms. J. P. Gawron (BNP) Mr. H. W. Habermeyer Mr. M. D. Hill Mr. W. J. Hindman Ms. C. W. Hobbs (HEEC) Mr. R. M. Krich Ms. W. C. Langston Mr. C. W. Martin (BNP) Mr. R. D. Martin Mr. J. W. McKay Mr. P. M. Odom (RNP) Mr. W. R. Robinson Mr. G. A. Rolfson Mr. R. F. Saunders Mr. C. N. Sweely Mr. M. A. Turkal (BNP) Mr. T. D. Walt Mr. R. L. Warden (RNP) HNP Real Time Training INPO Harris Licensing File Nuclear Records

NRC FO	RM 366	;		U.S	S. NUCLEA	AR REGI	LATORY	COMM	ISSION	<u> </u>	AP	PROVED BY O	MB NO.	3150-0	104		
495)					EXPIRES 04/30/98												
				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 500 HRS. REPORTED LESSONS LEARNED ARE													
	•	PICEN	ISEE I	e v Eiý i	r REPC	JRT (	(LER)			FORWARD	D COMMENT	S REGARDING BURI	EN ESTIM	ATE TO TH	E INFORM	ATION AND	
		(Se d	e revers ligits/cha	se for re aracters	equired n ; for each	umber 1 block)	of			WASHINGTON, DC 205550001, AND TO THE PAPERWORK REDUCTION PROJECT (3150 0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
FACILITY	NAME (1)					<u></u>				DOCKET	NUMBER (	2)			PAGE (3	)	
	Harri	s Nucle	ar Plan	t Unit	-1	*				;	5	0-400			OF 4	ŀ	
TITLE (4)					<u></u>					1				<u>u</u>			
Steam	Gener	ator lov	w level	protec	tion circ	uitry c	outside	design	basis	•			٩				
ËVE	NT DAT	E (5)		LER NU	MBER (6)	<u> </u>	REPO	RTDAT	E (7)	1	0	THER FACILITI	ES INV	OLVED (	3)		
MONTH	DAY	YEAR	YEAR	SEQUE	NTIAL IBER	REVISION NUMBER	монтн	DAY	YEAR	FACILITY	YNAME			DOCKET	IUMBER		
2	27	97	97	00	)3	00	3	31	97	FACILITY	Y NAME			DOCKET			
00504	TINO			PORTIS		TED PUI	SUANT	TO THE	REQUI	REMENT	S OF 10	CFR 5: (Chec	k one o	r more)	(11)	, 	
MOD	E (9)	1	20.2	201(b)			20.220	3(a)(2)(v	}		50.73(	a)(2)(i)		50.	73(a)(2	)(viii)	
POV	/ER	100%	20.2	203(a)(	1)		20.220	3(a)(3)(i)		X	50.73(	a)(2)(ii)		50.	73(a)(2	)(x)	
LEVEL	. (10)		20.2	203(a)(	2)(i)		20.220	3(a)(3)(ii)	)		50.73(	a)(2)(iii)		73.	71		
			20.2	203(a)(	2)(ii)		20.220	3(a)(4)			50.73(	a)(2)(iv)			1EK n Abetre	et helou	
			20.2	203(a)(	2)(10) 2)(iu)		50.36(0	1(1)			50.73	$\frac{3}{2}$		or in NRC	Form 3	66A	
		: •=====		205(8/(	2/(//		FE CON	TACT FO	R THIS		130.73(						
NAME						LIOLIIC				TEL	EPHONE N	JMBER (Include Are	a Code)				
	Micha	ael Veri	illi Sr.	Analy	vst - Lice	ensing						(919)	362-2	303			
		···· T	COMP	LETE ON	IE LINE FO	DR EACH	I COMPO	NENT F	AILURE	DESCR	IBED IN	THIS REPORT (	13)		1		
CAUSE	SI	STEM	COMPONE	NT M/	ANUFACTURI	ER REP To	ORTABLE NPRDS		CAU	SE I	System	COMPONENT	MANU	FACTURER	REPO TO	RTABLE NPRDS	
÷													Î				
-	_																
YES		SI	JPPLEME	NTAL R	EPORT EX	PECTED	) (14)				EXF SUB	PECTED	MONTI	H DA	Y	YEAR	
(if ye	s, comp	lete EXP	ECTED S	UBMISS	ION DATE	:).					DA	TE (15)					
ABSTRA	CT (Lin	nit to 140	00 space	s, i.e., a	pproximat	ely 15 s	ingle-spa	ced type	written	lines) (	(16)			-			
On Feb General satisfy Westing redunda	ruary 2 for (S/C the des ghouse ant pro-	27, 199 G) uppe ign requ Nuclear tection o	7, with r instrum uiremen r Safety channels	the plat ment lin ts of IE Adviso to be	nt operation ne tap ar EEE Stan ory Lette capable	ting in rangen idard 2 r (NSA of prov	mode 1 nent for 79-1971 AL) 96-0 viding p	at 100 S/G flo . This 004, "C rotectiv	% pov ow and concl Control re actio	ver, en l narro usion v and P on even	gineerir w range was read rotectio when	ng review con e level chann ched followin n Interaction degraded by	nclude els do ng a re ", whi a seco	d that the not corview of ch requend rand	ne Stea nplete ires lom fa	am ly ilure.	
Due to commo system constitu system	the arr n tap c circuiti tes ope at appi	angeme onnection ry logic eration of roximate	nt of the on with , a pote outside t ely 1513	e S/G u a S/G : ntial sc he desi hours	upper ins narrow r enario ex ign basis on Febr	strumer ange le xists th of the uary 2	nt line ta evel cha at result plant a 7, 1997	ap conn nnel, co ts in the nd was	ection ombine s/G report	for S/ ed with low-lov ed to t	G steam the log w level he NRC	a flow instru- gic utilized in reactor trip l c via the emo	ments, the re- being u ergency	which eactor p inavaila y notific	share rotectible.	a ion This	
, This co configu	ndition ration	was ca for S/G	used by level in	an ina strume	dequate ntation d	failure luring i	modes initial p	and eff lant cor	ects ar	alysis on.	perforn	ned on the as	-built	piping			
Immedi	ate cor	rective	actions	include	d elímin	ating th	ie poter	tial fail	ure sc	enario	by plac	ing the Stear	n Flov	v - Feed	l Flow	,	

Immediate corrective actions included eliminating the potential failure scenario by placing the Steam Flow - Feed Flow selector switch on the main control board to the "Channel III" position and placing caution tags on the switch. A review was also performed of other protection channels to ensure that protection and control interaction requirements were met. No additional discrepancies were identified during this review. Planned corrective actions will include a permanent resolution to the identified design deficiency.

. AN 112

1

•

NRC	FORM	366A
<b>f4-95</b>	)	

### LICENSEE EVENT REPORT (LER) **TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET		LER NUMBER (5)	PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 0		
Shearon Harris Nuclear Plant • Unit #1	50-400	97	003	00		UF	4

TEXT Of more space is required, use additional copies of NRC Form 366AU (17)

### **EVENT DESCRIPTION:**

On February 27, 1997, with the plant operating in mode 1 at 100% power, a review performed by Harris Nuclear Plant (HNP) Engineering personnel concluded that the Steam Generator (S/G, EIIS Code: JB) upper instrument line tap arrangement for S/G steam flow and narrow range level channels (EIIS Code JB-FT,LT) does not completely satisfy the design requirements of IEEE Standard 279-1971.

The failure to satisfy these requirements was identified during a review of Westinghouse Nuclear Safety Advisory Letter (NSAL) 96-004, "Control and Protection Interaction" dated August 14, 1996. NSAL 96-004 identified a design configuration involving the failure of a common tap for S/G steam flow and narrow range level which could cause an undesired control/protection interaction scenario. The specific condition described in NSAL 96-004 was not applicable at HNP, however, during the review of this document, the following design deficiency was identified:

At HNP, each S/G has four narrow range level channels which provide input to a 2 out of 3 logic for the S/G low-low level reactor trip signal. (reference attached drawing) Each S/G also has two steam flow transmitters that share a common tap with two of the narrow range level channels. These two steam flow transmitters provide input to the steam flow-feedwater flow mismatch logic and can be selected to provide input to the S/G Water Level Control System. The Technical Evaluation contained in NSAL 96-004 specifically states that "two steam flow channels are provided for each loop, only one of which shares a tap connection with a narrow range steam generator level channel in a three level channel system." IEEE Standard 279-1971, section 4.7.3, requires that "where a single random failure can cause a control system action that results in a generating station condition requiring protective action and can also prevent proper action of a protection system channel designed to protect against the condition, the remaining redundant protection channels shall be capable of providing the protective action even when degraded by a second random failure"

Investigation concluded that, due to the arrangement of the S/G upper instrument line tap connection for the two S/G steam flow channels, which share a common tap connection with a S/G narrow range level channel, if the steam flow selector switch is placed in channel IV, the coincidence logic will not cause a S/G low-low level reactor trip during the following scenario:

- Ø Steam Generator upper tap or impulse line used by Channel I Steam Generator Level and the Channel IV Steam Flow channel ruptures causing the level signal to fail high.
- 0 A second random failure occurs on Channel II or Channel III.

In this scenario only one S/G low-low level reactor trip channel is available, which is not sufficient to actuate the 2 of 3 reactor trip logic. During this postulated scenario, the rupture causes a false high S/G level signal and a false low steam flow signal. If this steam flow signal is selected as input to the S/G water level control system on the steam flow selector switch, the feed regulating valve will start to shut to match feedwater flow to the apparent steam flow signal. The actual level in the affected SG will start to decrease and the reactor trip will not be received as required when the SG level drops.

This scenario requires a specific level instrument on the SG to sustain the pipe failure. The postulated second random failure must occur specifically on at least one of two remaining level instruments. Finally, the control input to the SG water level control system must be selected to a specific input (Channel IV). All three of these must occur for the scenario to occur.

This condition constitutes operation outside the design basis of the plant and was reported to the NRC via the emergency notification system at approximately 1513 hours on February 27, 1997.

	NRC	FOR14	366A
J	14-95	1	

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET		LER NUMBER (5	)		PAGE (3)	
	50.000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		05	
Shearon Harris Nuclear Plant - Unit #1	50-400	97 .	- 003 -	00	3	OF	4

TEXT (If more space is required, use additional copies of NRC Form 366AJ (17)

### CAUSE:

This condition was caused by an inadequate failure modes and effects analysis performed on the as-built piping configuration for S/G level instrumentation by the S/G vendor and HNP Engineering. This analysis was performed in August 1985 during initial plant construction.

# SAFETY SIGNIFICANCE:

There were no actual consequences associated with this condition. The probability of this scenario occurring and not being identified and corrected by operator action was determined to be very unlikely (7.4E-7 per year) using probabilistic safety analysis estimates. In addition, numerous automatic plant protective features (ie., OT-Delta T Reactor Trip, High Power (Neutron Flux) Reactor Trip, Pressurizer High Pressure Reactor Trip, Pressurizer PORVs, etc..) would remain available to mitigate the consequences of this failure scenario with no operator action. This provides confidence that the Reactor Coolant System would remain intact and that no core damage would occur.

This is being reported per 10CFR50.73.a.2.ii as a condition outside the design basis of the plant.

# PREVIOUS SIMILAR EVENTS:

Westinghouse Nuclear Safety Advisory Letter (NSAL) 96-004 was issued on August 14, 1996. This document alerted industry personnel of a control and protection interaction design deficiency associated with Steam Generator instrumentation tap/impulse line configuration. Though the specific condition identified in NSAL 96-004 was not applicable to HNP, the design deficiency identified in this LER was found during NSAL 96-004 review. There have been no previous similar HNP LERs related to deficient S/G instrumentation design/configuration.

# **CORRECTIVE ACTIONS COMPLETED:**

- 1. The Steam Flow Selector Switch on the main control board was taken to Channel III, which eliminates the potential failure scenario. Caution tags have been placed on the Steam Flow Selector switch as an interim administrative control to ensure that Operations personnel maintain the switch in channel III or control feedwater flow in manual.
- 2. A review was performed during the investigation of this condition for other protection channels, to ensure that protection and control interaction requirements were met. No additional discrepancies were identified during this review.

# CORRECTIVE ACTIONS PLANNED:

1. A permanent resolution for the identified design deficiency will be implemented by July 15, 1997.

• 

· · · 

•

÷ -. . .

.

· ,

•

\*



Press . . . . . .

• • • • • • 

.