

50-237

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: J.G. KEPPLER

FROM: COMMONWEALTH EDISON CO  
MORRIS, ILLINOIS  
B.B. STEPHENSON

DATE OF DOCUMENT  
7/5/77

DATE RECEIVED  
7/11/77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 CC

DESCRIPTION

LICENSEE EVENT REPORT FOR R.O.# 77-23, ON  
6/5/77 CONCERNING THE 12% APRM UPSCALE ROD  
BLOCK TRIP SETTING BEING AT 12.5% FOR APRM  
CHANNEL ONE.

(1P & 2P) **ACKNOWLEDGED**

PLANT NAME: DRESDEN # 2  
.SAB

**DO NOT REMOVE**

ENCLOSURE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Davis</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Diggs</i>
W/ / CYS	
ACRS <i>16</i> CYS HOLDING/SENT <i>AS CAP B</i>	

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE					
NRC PDR					
I & E (2)					
MIPC					
SCHROEDER/IPPOLITO					
HOUSTON					
NOVAK/CHECK					
GRIMES					
BUTLER					
HANAUER					
TEDESCO/MACCARY					
EISENHUT					
BAER					
SHAO					
VOLLMER/BURGH					
KREGER/J. COLLINS					

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: <i>Morris 7/6/</i>					
TIC:					
NSIC:					

*P/D*  
*7/11* 771930417 *B*

1950

1950

1950

2



Commonwealth Edison  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

Regulatory Docket File

BBS LTR #77-600

July 5, 1977



Mr. James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence Report #50-237/1977-23.  
This report is being submitted to your office in accordance with the  
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

A handwritten signature in cursive script, appearing to read 'B.B. Stephenson'.


B.B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:kc


Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File Copy/NRC

771930417







EVENT DESCRIPTION (Continued)

setpoint drift was found to have occurred only once in the past two years of Unit 2/3 operation. (#50-237/1977-23)

CAUSE DESCRIPTION (Continued)

was returned to  $11.5 \pm .5\%$ . Based upon the very small setpoint error observed, and upon the infrequent nature of this occurrence, no further corrective action is deemed necessary.



11-11-11  
11-11-11  
11-11-11