

A 04/12/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-220

REC: GRIER B H
NRC

ORG: SCHNEIDER R R
NIAGARA MOHAWK PWR

DOC DATE: 04/07/78
DATE RCVD: 04/10/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RD 50-220/78-14, REV 1) ON 03/07/78
CONCERNING PERFORMANCE OF SURVEILLANCE TEST N1-ST-M4 FOUND THAT THE FUEL
TRANSFER PUMP ON 012 D/G WOULD NOT FILL THE DAY TANK... W/ATT LERS 78-016 AND
78-017.

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: W

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF LEAR**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
~~I & E**W/2 ENCL~~
SCHROEDER/IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAO**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
HOUSTON**W/ENCL
GRIMES**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL:

LPDR'S
OSWEGO, NY**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+2P

CONTROL NBR: 781010044

***** THE END *****



NY NIAGARA
MOHAWK

NMP-0143

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

April 7, 1978

APR 10 PM 4 49

REGISTRATION
SERVICES UNIT

REGISTRATION
SERVICES
MARCH

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit Licensee Event Reports, LER 78-14, Revision 1, which is in violation of Section 3.6.3, and LER 78-16 and LER 78-17, which are in violation of Section 3.6.2, of the Technical Specifications.

These reports were completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

mtm

Enclosure (3 copies)

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

781010044

4002
5
1/1

REGULATORY DOCKET FILE COPY



1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35



1
2
3
4
5

.....

.....

.....

.....

.....

.....

.....

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE NYNMP 1, LICENSE NUMBER 000-000000-0000, LICENSE TYPE 4111111, CAT 58

REPORT SOURCE L, DOCKET NUMBER 05000220, EVENT DATE 033178, REPORT DATE 040778

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10): During steady state operation, performance of surveillance test N1-ISP-RE18, found RE18C with a setpoint of 129 inches wc. Required setpoint of the low low low Rx Level switch is 125 inches wc +2.0/-2.6. This condition resulted in minimal safety implications. The drift was in a more conservative direction and redundant instrumentatation was available.

SYSTEM CODE IB, CAUSE CODE E, CAUSE SUBCODE E, COMPONENT CODE INSTRU, COMP. SUBCODE S, VALVE SUBCODE Z, LER/RO REPORT NUMBER 78, SEQUENTIAL REPORT NO. 016, OCCURRENCE CODE 03, REPORT TYPE L, REVISION NO. 0, ACTION TAKEN EZ, EFFECT ON PLANT Z, SHUTDOWN METHOD Z, HOURS 0000, ATTACHMENT SUBMITTED N, NPFD-4 FORM SUB. Y, PRIME COMP. SUPPLIER N, COMPONENT MANUFACTURER B080

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27): The change in setpoint experienced on the Barton Model 288 level switch was due to instrument drift. RE18C was reset at 125.0 inches wc. Current surveillance testing schedules are adequate to insure early detection of future instrument drifts.

FACILITY STATUS E, % POWER 099, OTHER STATUS NA, METHOD OF DISCOVERY B, DISCOVERY DESCRIPTION Surveillance Testing

ACTIVITY RELEASED OF RELEASE Z, AMOUNT OF ACTIVITY NA, LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 000, TYPE Z, DESCRIPTION NA

PERSONNEL INJURIES NUMBER 000, DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z, DESCRIPTION NA

PUBLICITY ISSUED N, DESCRIPTION NA, NAME OF PREPARER Dennis K. MacVittie, PHONE: 315-343-2110 ext 1558

1



1

LICENSEE EVENT REPORT

CONTROL BLOCK: [][][][][][][][] 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 4 | 0 | 1 | 7 | 8 | 8 | 0 | 4 | 0 | 7 | 7 | 8 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 | During steady state operation, performance of surveillance test N1-ISP-
03 | RE04, found RE04B with a setpoint of 3.42 PSI, and RE04D at 3.58 PSI.
04 | Required setpoint of these drywell high pressure switches is 3.50 PSI
05 | +/-0.053 PSI. This condition resulted in minimal safety implications.
06 |
07 |
08 |

09 | SYSTEM CODE | I | B | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | E | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16
17 | LER/RO REPORT NUMBER | 7 | 8 | 21 | EVENT YEAR | 7 | 8 | 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 7 | 24 | OCCURRENCE CODE | 0 | 3 | 28 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
18 | ACTION TAKEN | E | 18 | 33 | FUTURE ACTION | Z | 19 | 34 | EFFECT ON PLANT | Z | 20 | 35 | SHUTDOWN METHOD | Z | 21 | 36 | HOURS | 0 | 0 | 0 | 0 | 37 | ATTACHMENT SUBMITTED | N | 23 | 40 | NRPD-4 FORM SUB. | Y | 24 | 42 | PRIME COMP. SUPPLIER | N | 25 | 43 | COMPONENT MANUFACTURER | B | 0 | 8 | 0 | 26 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 | These changes in setpoints experienced on Barton Model 289 pressure
11 | indicating switches were due to instrument drift. RE04B was reset to
12 | 3.47 PSI, and RE04D was reset to 3.46 PSI. Current surveillance
13 | testing schedules are adequate to insure early detection of future
14 | instrument drifts.

15 | FACILITY STATUS | E | 28 | 7 | 8 | % POWER | 0 | 5 | 7 | 29 | 9 | 10 | 12 | OTHER STATUS | NA | 30 | 44 | METHOD OF DISCOVERY | B | 31 | 45 | DISCOVERY DESCRIPTION | Surveillance Testing | 32 | 80

16 | ACTIVITY RELEASED | Z | 33 | 7 | 8 | CONTENT OF RELEASE | Z | 34 | 9 | 10 | AMOUNT OF ACTIVITY | NA | 35 | 44 | LOCATION OF RELEASE | NA | 36 | 45 | 80

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | 7 | 8 | TYPE | Z | 38 | 9 | 11 | DESCRIPTION | NA | 39 | 13 | 80

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | 7 | 8 | DESCRIPTION | NA | 41 | 11 | 12 | 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | 7 | 8 | DESCRIPTION | NA | 43 | 9 | 10 | 80

20 | PUBLICITY ISSUED | N | 44 | 7 | 8 | DESCRIPTION | NA | 45 | 9 | 10 | 80

10
11
12
13
14
15