

E 03/10/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL 50-220

REC: GRIER B H  
NRC

ORG: SCHNEIDER R R  
NIAGARA MOHAWK PWR

DOCDATE: 03/01/78  
DATE RCVD: 03/07/78

DOCTYPE: LETTER NOTARIZED: NO  
SUBJECT:

COPIES RECEIVED  
LTR 0 ENCL 1

LICENSEE EVENT REPT (RO 50-220/78-07) ON 02/06/78 CONCERNING DURING  
STEADY STATE OPERATAION, AN INSPEC OF THE LIQUID WASTE SURGE TANK  
FOUND SEVERAL PINHOLE LEAKS...W/ATT LERS 78-008, 78-009 AND 78-010.

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: DL

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ~~LEAR~~\*\*W/4 ENCL

INTERNAL:

REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
SCHROEDER/IPPOLITO\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
KNIGHT\*\*W/ENCL  
HANAUER\*\*W/ENCL  
EISENHUT\*\*W/ENCL  
SHAO\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
HOUSTON\*\*W/ENCL  
GRIMES\*\*W/ENCL  
BUTLER\*\*W/ENCL  
TEDESCO\*\*W/ENCL  
BAER\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
ROSA\*\*W/ENCL

EXTERNAL:

LPDR'S  
OSWEGO, NY\*\*W/ENCL  
TIC\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P+4P

CONTROL NBR: 780680045

\*\*\*\*\* THE END \*\*\*\*\*



11

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy auditing of the accounts.

In the second section, the author outlines the various methods used to collect and analyze financial data. This includes reviewing bank statements, credit card records, and other financial documents. The goal is to identify any discrepancies or irregularities that may indicate potential fraud or errors.

The third part of the document provides a detailed breakdown of the company's revenue and expenses over a specific period. It includes a table showing the following data:

Category	Amount
Revenue	\$12,500.00
Expenses	\$8,750.00
Net Profit	\$3,750.00

The final section of the document concludes with a summary of the findings and recommendations. It states that the financial records appear to be accurate and that there are no significant concerns. However, it advises that regular audits should be conducted to ensure ongoing compliance and accuracy.

March 1, 1978

Mr. Boyce H. Grier  
 Director  
 United States Nuclear Regulatory Commission  
 Region I  
 631 Park Avenue  
 King of Prussia, PA. 19406



RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the following Licensee Event Reports:

- LER 78-07, which is in violation of Section 6.9.2b(4) of the Technical Specifications
- LER 78-08, which is in violation of Section 3.6.2 of the Technical Specifications
- LER 78-09, in accordance with the Technical Specifications
- LER 78-10, which is in violation of Section 3.6.2 of the Technical Specifications

These reports were completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

R.R. Schneider  
 Vice President -  
 Electric Production

mtm

Attachments (3 copies)

xc: Director, Office of I&E (30 copies)  
 Director, Office of MIPC (3 copies)

780680045

A002/s \*  
 o/i



20 20

17  
17-17-6

17-17-6

17-17-6  
17-17-6  
17-17-6  
17-17-6  
17-17-6  
17-17-6

17-17-6

17-17-6

17-17-6

17-17-6

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 57 58  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
 01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 2 | 0 | 6 | 7 | 8 | 8 | 0 | 2 | 2 | 8 | 7 | 8 | 9  
7 8 60 61 68 69 74 75 80  
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During steady state operation, an inspection of the liquid waste surge  
 03 | tank found several pinhole leaks. There were no measurable losses of  
 04 | liquid but leaks could be identified by dried deposit tracks on the  
 05 | side of the tank. This is reportable per T.S. 6.9.2b(4). This  
 06 | condition resulted in minimal safety implications.  
 07 |  
 08 | \_\_\_\_\_  
7 8 9 80

09 | SYSTEM CODE | M | A | 11 | CAUSE CODE | B | 12 | CAUSE SUBCODE | C | 13 | COMPONENT CODE | A | C | C | U | M | U | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |  
7 8 9 10 11 12 13 18 19 20  
 LER/RO REPORT NUMBER | 17 | EVENT YEAR | 7 | 8 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 0 | 7 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |  
 ACTION TAKEN | X | 18 | FUTURE ACTION | F | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | P | 2 | 7 | 0 | 26 |  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | A 50,000 gal aluminum B-209 tank built by Pittsburg-Des Moines Steel Co.  
 11 | was constructed with walls 0.1875 inches thick. During assembly, weld-  
 12 | ing and grinding reduced the thickness in spots to half of this value  
 13 | apparently leaving pinhole leaks. A tank liner is being considered as  
 14 | a permanent solution, currently usage is strictly controlled.  
7 8 9 80

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 9 | 9 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | C | 31 | DISCOVERY DESCRIPTION | Tank Inspection | 32  
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39  
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43  
7 8 9 11 12 80

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45  
7 8 9 10 80

NAME OF PREPARER Dennis K. MacVittie

PHONE: 315-343-2110 ext. 1558



[The page contains extremely faint and illegible text, likely bleed-through from the reverse side of the document. The text is scattered across the page and does not form any recognizable words or sentences.]

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(01) | N | Y | N | M | P | I | \_\_\_\_\_ (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | \_\_\_\_\_ (3) | 4 | 1 | 1 | 1 | 1 | \_\_\_\_\_ (4) | \_\_\_\_\_ (5)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T (01) | \_\_\_\_\_ (6) | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | \_\_\_\_\_ (7) | 0 | 2 | 1 | 0 | 7 | 8 | \_\_\_\_\_ (8) | 0 | 2 | 2 | 8 | 7 | 8 | \_\_\_\_\_ (9)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(02) | During steady state operation, performance of surveillance test NI-ISP- |

(03) | RE22, found RE22C with a setpoint of 103.5 PSID, RE22E at 103.0 PSID, |

(04) | and RE22F at 103.5 PSID. Required setpoint for these main steam line |

(05) | high flow indicating switches is 105 PSID +/- 1 PSID. This condition |

(06) | resulted in minimal safety implications. The three instruments drifted |

(07) | in a more conservative direction. |

(08) | \_\_\_\_\_ |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(09) | I | B | \_\_\_\_\_ (11) | E | \_\_\_\_\_ (12) | E | \_\_\_\_\_ (13) | I | N | S | T | R | U | \_\_\_\_\_ (14) | S | \_\_\_\_\_ (15) | Z | \_\_\_\_\_ (16)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

(17) LER/RO REPORT NUMBER (78) \_\_\_\_\_ (23) \_\_\_\_\_ (24) 008 \_\_\_\_\_ (27) \_\_\_\_\_ (28) 03 \_\_\_\_\_ (30) L \_\_\_\_\_ (31) \_\_\_\_\_ (32) 0

(18) E \_\_\_\_\_ (19) Z \_\_\_\_\_ (20) Z \_\_\_\_\_ (21) Z \_\_\_\_\_ (22) 0000 \_\_\_\_\_ (23) N \_\_\_\_\_ (24) Y \_\_\_\_\_ (25) N \_\_\_\_\_ (26) B080 \_\_\_\_\_ (27)

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(10) | The deviation in setpoints experienced on the Barton Model 278 Differen- |

(11) | tial Pressure Indicating Switches was due to instrument drift. RE22C |

(12) | was reset at 105.5 PSID, RE22E at 105.0 PSID, and RE22F at 104.7 PSID. |

(13) | Current surveillance testing schedules are adequate to insure early |

(14) | detection of future instrument drifts. |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(15) | E | \_\_\_\_\_ (28) | 0 | 9 | 9 | \_\_\_\_\_ (29) | NA \_\_\_\_\_ (30) | B | \_\_\_\_\_ (31) | \_\_\_\_\_ (32) | Surveillance Testing |

(16) | Z | \_\_\_\_\_ (33) | Z | \_\_\_\_\_ (34) | \_\_\_\_\_ (35) | NA \_\_\_\_\_ (36) | NA \_\_\_\_\_ (37) | \_\_\_\_\_ (38) |

(17) | 0 | 0 | 0 | \_\_\_\_\_ (37) | Z | \_\_\_\_\_ (38) | NA \_\_\_\_\_ (39) |

(18) | 0 | 0 | 0 | \_\_\_\_\_ (40) | NA \_\_\_\_\_ (41) |

(19) | Z | \_\_\_\_\_ (42) | NA \_\_\_\_\_ (43) |

(20) | N | \_\_\_\_\_ (44) | NA \_\_\_\_\_ (45) |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASER OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

PERSONNEL INJURIES NUMBER DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER: Dennis K. MacVittie PHONE: 315-343-2110 ext 1558

CP-7926



12 28

12 28

12 28

12 28

12 28

12 28

12 28



# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [N][Y][N][M][P][I] [2] [0][0] - [0][0][0][0][0][0] - [0][0] [3] [4][1][1][1][1][1] [4] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [5]

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
[0][1] REPORT SOURCE [L] [6] [0][5][0][0][0][2][2][0] [7] [0][2][2][1][7][8] [8] [0][2][2][8][7][8] [9]

DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] During routine station operation with the TIP detectors withdrawn, ex-  
[0][3] plosive charges in the TIP shear valves were replaced with new charges.  
[0][4] Following replacement, it was found that the ohmmeter continuity test  
[0][5] for acceptable electric contact was unsatisfactory. The normal TIP tube  
[0][6] isolation system was operable at this time. An evaluation of the safety  
[0][7] implications is being conducted.

[0][9] [X][X] [11] [B] [12] [A] [13] [X][X][X][X][X][X] [14] [Z] [15] [Z] [16]

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20

[17] LER/RO REPORT NUMBER [7][8] [ ] [ ] [0][0][9] [ ] [0][1] [T] [ ] [ ] [0]

ACTION TAKEN 33 [F] [18] ACTION 34 [Z] [19] EFFECT ON PLANT 35 [Z] [20] SHUTDOWN METHOD 36 [Z] [21] HOURS 37 [0][0][0][0] [22] ATTACHMENT SUBMITTED 40 [Y] [23] NPRD-4 FORM SUB. 42 [N] [24] PRIME COMP. SUPPLIER 43 [N] [25] COMPONENT MANUFACTURER 44 [G][0][8][0] [26] 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] It was found that the actual electrical connections as originally wired  
[1][1] were not as described in the Maintenance Procedure or in a re-  
[1][2] vised GE drawing. The wiring was changed to agree with the revised GE  
[1][3] dwg and all four of the old squib devices were detonated successfully.

[1][5] [E] [28] [0][9][9] [29] NA [30] [B] [31] Surveillance Testing [32]

FACILITY STATUS 7 8 % POWER 9 10 OTHER STATUS 13 METHOD OF DISCOVERY 45 DISCOVERY DESCRIPTION 46

[1][6] [Z] [33] [Z] [34] NA [35] NA [36]

ACTIVITY RELEASED 9 10 AMOUNT OF ACTIVITY 44 LOCATION OF RELEASE 45

[1][7] [0][0][0] [37] [Z] [38] NA [39]

PERSONNEL EXPOSURES NUMBER 9 10 TYPE 11 DESCRIPTION 13

[1][8] [0][0][0] [40] NA [41]

PERSONNEL INJURIES NUMBER 9 10 DESCRIPTION 13

[1][9] [Z] [42] NA [43]

LOSS OF OR DAMAGE TO FACILITY TYPE 9 10 DESCRIPTION 13

[2][0] [N] [44] NA [45]

PUBLICITY ISSUED 9 10 DESCRIPTION 13



11  
12  
13

14  
15  
16

17  
18  
19  
20  
21  
22

23

24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

February 28, 1978

Mr. Boyce H. Grier  
Director  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA. 19406

RE: Docket No. 50-220  
LER 78-09/01T-0  
Nine Mile Point Nuclear Station Unit #1

Dear Mr. Grier:

During routine station operation with the TIP detectors withdrawn, explosive charges in the TIP System shear valves were replaced with new charges. The explosive operated TIP shear isolation valves are a back-up system to be used for isolation of the TIP tubes in the event it is not possible to withdraw the detector so the normal automatic isolation system may function.

Following replacement, performance of Maintenance Procedure, N1-IMP-TIP-3 found that the ohmmeter continuity test for acceptable electric contact was unsatisfactory. The normal TIP tube isolation system was operable at this time.

It was found that the actual electrical connections to the explosive charges were not as described in the Maintenance Procedure. General Electric NED Product Service was informed of the problem and given the numbers of the drawings used to wire the system. A revision to the drawing, which had originally been issued in February 1968, was located. The configuration shown in this revision would cause the charges to fire.

The wiring for firing the charges in the TIP System was changed to match that shown in the revised drawing. All of the old charges were test fired using the wiring scheme shown in the revised drawing. They all fired successfully.

A review of the Pre-Operational Test of our Liquid Poison System showed that the explosive shear valves in that system had been operationally tested prior to startup.

In addition to the wiring problems uncovered, it was found that the 2 AMP fuses required in the squib circuits were instant blow devices instead of the slow blow type specified by the vendor. All of the fuses in the monitor/control units were replaced with new devices.

An evaluation of the safety implications is being conducted.



2  
10

11

12

13

14

15

16

17

18

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

⑦ 0 ⑧ 1 | N | Y | N | M | P | 1 | ② 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | ③ 4 | 1 | 1 | 1 | 1 | ④ \_\_\_\_\_ | ⑤ \_\_\_\_\_  
7 8 9 14 15 25 26 30 57 58  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
⑦ 0 ⑧ 1 | L | ⑥ 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | ⑦ 0 | 2 | 0 | 4 | 7 | 8 | ⑧ 0 | 2 | 2 | 8 | 7 | 8 | ⑨ \_\_\_\_\_  
7 8 60 61 68 69 74 75 80  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

⑦ 0 ⑧ 2 | During steady state operation, performance of surveillance test N1-ISP-  
⑦ 0 ⑧ 3 | RE04, found RE04D with a setpoint of 3.65 PSI. T.S. 3.6.2 requires the  
⑦ 0 ⑧ 4 | drywell high pressure switches to have a setpoint of 3.50 PSI +/- 0.053  
⑦ 0 ⑧ 5 | PSI. This condition resulted in minimal safety implications. Redun-  
⑦ 0 ⑧ 6 | dant instrumentation was available.  
⑦ 0 ⑧ 7 | \_\_\_\_\_  
⑦ 0 ⑧ 8 | \_\_\_\_\_  
7 8 9 80

⑦ 0 ⑧ 9 | I | B | ⑪ E | ⑫ E | ⑬ I | N | S | T | R | U | ⑭ S | ⑮ Z | ⑯ \_\_\_\_\_ | Z | ⑰ \_\_\_\_\_ | ⑱ 0 |  
7 8 9 10 11 12 13 18 19 20 32  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
⑰ LER/RO REPORT NUMBER | ⑳ 7 | ㉑ 8 | \_\_\_\_\_ | ㉒ 0 | 1 | 0 | \_\_\_\_\_ | ㉓ 0 | 3 | \_\_\_\_\_ | L | \_\_\_\_\_ | ㉔ 0 |  
21 22 23 24 26 27 28 29 30 31 32  
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
⑳ ACTION TAKEN | ㉒ Z | ㉓ \_\_\_\_\_ | ㉔ Z | ㉕ \_\_\_\_\_ | ㉖ 0 | 0 | 0 | 0 | \_\_\_\_\_ | N | ㉗ Y | \_\_\_\_\_ | N | \_\_\_\_\_ | B | 0 | 8 | 0 |  
33 34 35 36 37 40 41 42 43 44 47  
FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

⑦ 1 ⑧ 0 | RE04D, a Barton Model 289 pressure indicating switch drifted from a  
⑦ 1 ⑧ 1 | setpoint of 3.55 PSI. It was reset to 3.50 PSI. Current surveillance  
⑦ 1 ⑧ 2 | testing schedules are adequate to insure early detection of future  
⑦ 1 ⑧ 3 | instrument drifts.  
⑦ 1 ⑧ 4 | \_\_\_\_\_  
7 8 9 80

⑦ 1 ⑧ 5 | E | ⑳ 0 | 9 | 3 | ㉑ NA | B | ㉒ \_\_\_\_\_ | Surveillance Testing ㉓ \_\_\_\_\_  
7 8 9 10 12 13 44 45 46 80  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

⑦ 1 ⑧ 6 | Z | ㉔ \_\_\_\_\_ | Z | ㉕ \_\_\_\_\_ | NA | \_\_\_\_\_ | NA | \_\_\_\_\_ | \_\_\_\_\_ | \_\_\_\_\_  
7 8 9 10 11 44 45 80  
ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

⑦ 1 ⑧ 7 | 0 | 0 | 0 | ㉖ Z | ㉗ \_\_\_\_\_ | NA  
7 8 9 11 12 13 80  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

⑦ 1 ⑧ 8 | 0 | 0 | 0 | ㉘ \_\_\_\_\_ | NA  
7 8 9 11 12 80  
PERSONNEL INJURIES NUMBER DESCRIPTION

⑦ 1 ⑧ 9 | Z | ㉙ \_\_\_\_\_ | NA  
7 8 9 10 80  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

⑦ 2 ⑧ 0 | N | ㉚ \_\_\_\_\_ | NA  
7 8 9 10 80  
ISSUED DESCRIPTION PUBLICITY

NAME OF PREPARER D.K. MacVittie

PHONE: 315-343-2110 x 1558

NRC USE ONLY

GPO 017-926

2000