



LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7825 Technical Specification Involved 4.7.A.2.i

Reported Under Technical Specification 6.7.2.a(9)

Date of Occurrence 9/17/78 Time of Occurrence 0900 Unit 3

Identification and Description of Occurrence:

Four MSIV's, FCV-1-14, 1-26, 1-51 and 1-52, exceeded the leakage allowed by T.S. 4.7.A.2.i during local leak rate testing. The following are the leak rates:

FCV-1-14	1843.4169 SCFH	FCV-1-51	50.7488 SCFH
FCV-1-26	442.4096 SCFH	FCV-1-52	1997.1238 SCFH

Conditions Prior to Occurrence:

Unit shutdown for refueling. The reactor head was off.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Repair and retest to be done.

Apparent Cause of Occurrence:

Unknown at this time.

Analysis of Occurrence:

None

Corrective Action:

Valves will be repaired and satisfactorily retested prior to return to service of the unit.

Failure Data:

BFRO-50-259/7723
BFRO-50-260/789

Tennessee Valley Authority - Browns Ferry Nuclear Plant

