

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: _____

7812190111

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7831 Technical Specification Involved 6.7.2.A.6

Reported Under Technical Specification 6.7.2.A.6

Date of Occurrence 11/28/78 Time of Occurrence _____ Unit 3

Identification and Description of Occurrence:

All LPRM connections were incorrect.

Conditions Prior to Occurrence:

Stable power operation at 36 percent.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

N/A.

Apparent Cause of Occurrence:

Incorrect hook up of LPRM connectors during refueling outage.

Analysis of Occurrence:

Occurrence was caused by procedural deficiency but problem was detected by test designed to discover such mistakes. There were no effects on public health or safety.

Corrective Action:

Short term: Shutdown unit and correct connection.

Long term: Clarify procedure and add QA hold points.

Failure Data:

None

Tennessee Valley Authority - Browns Ferry Nuclear Plant