



11  
12  
13

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 793 Technical Specification Involved 3.3.A.2.e

Reported Under Technical Specification 6.7.2.A(2)

Date of Occurrence 2-14-79 Time of Occurrence 0440 Unit 2

Identification and Description of Occurrence:

Rod position information was lost for all rods on the bottom half of the vertical core display.

Conditions Prior to Occurrence:

Normal operation at 3218 MWt.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Power supply replaced within 3 hours. LCO requires shutdown if not corrected within 24 hours.

Apparent Cause of Occurrence:

Failed fan on power supply caused overheating of power supply and trip out on load limit.

Analysis of Occurrence:

Current rod positions were stored in process computer and no rod moves were made during the period the display was inoperable.

Corrective Action:

New power supply installed within 3 hours.

Failure Data:

None previously.