

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 6 | 7 | 0 | 4 | 1 | 1 | 7 | 9 | 8 | 0 | 5 | 0 | 7 | 7 | 9 | 9
 7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 | During normal operation, a heat detector alarmed and would not clear. The alarm would
 0 3 | have masked signals from other detector which are required to be operational by T.S.
 0 4 | 3.11.C.1. There were no effects on public health or safety. There are no redundant
 0 5 | systems. Similar event BFRO-50-259/7610.
 0 6 | _____
 0 7 | _____
 0 8 | _____

SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE | REVISION NO. | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE
 0 9 | A | B | 11 | A | 12 | C | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16 | 0 | 7 | 9 | 0 | 0 | 4 | 0 | 3 | L | 0
 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32
 ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
 C | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | L | 25 | K | 1 | 2 | 0 | 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 | The heat detector was damaged by personnel performing modifications in the area. The
 1 1 | detector was replaced. A fire watch was posted in the interim. The detector was a
 1 2 | Kidde model 897096. Due to the nature of this failure, followup action is not indi-
 1 3 | cated.
 1 4 | _____

FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
 1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | A | 31 | Alarm received in control room | 32
 7 8 9 10 12 13 44 45 46 80

ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
 1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
 7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER | TYPE | DESCRIPTION
 1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
 7 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER | DESCRIPTION
 1 8 | 0 | 0 | 0 | 40 | NA | 41
 7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE | DESCRIPTION
 1 9 | Z | 42 | NA | 43
 7 8 9 10 80

PUBLICITY ISSUED | DESCRIPTION
 2 0 | N | 44 | NA | 45
 7 8 9 10 80

7905110201

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 794 Technical Specification Involved T.S. 3.11.C.1

Reported Under Technical Specification T. S. 6.7.2.b(2)

Date of Occurrence 4/11/79 Time of Occurrence 1845 Unit 3

Identification and Description of Occurrence:

U-3 Control room received the following alarms:
(XA 39-111A Rx building 593 elev. 593 R21 panel 25-311) common alarm
(TA 39-110 Rx building 593) heat element or power failure)

Conditions Prior to Occurrence:

Normal operations

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Posted fire watch.

Apparent Cause of Occurrence:

Heat detector was damaged by personnel performing modifications in the area.
Either by installing scaffolds or pulling cables.

Analysis of Occurrence:

Detector failure was due to damage by personnel.

Corrective Action:

Heat detector was replaced.

Failure Data:

NA