## LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 796 Technical Specification Involved 3.7.H.
Reported Under Technical Specification 6.7.2.b(2)
Date of Occurrence 5/7/79 Time of Occurrence 1100 Unit 3
Identification and Description of Occurrence:
Operations personnel observed erratic indications on the torus hydrogen sensor ${\rm H_2M-7}$ The system was declared inoperable.
Conditions Prior to Occurrence:
Normal operation.
Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.
Apparent Cause of Occurrence:
Defective hydrogen sensor.
Analysis of Occurrence:
Corrective Action:
Replaced hydrogen sensor.
Failure Data:

Tennessee Valley Authority - Browns Ferry Núclear Plant

259/7815 and 259/7820.

