

(777) - Update Report - Previous Report **LICENSEE EVENT REPORT**
Date 8/22/79

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 0 0 0
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT. 52

0 2 L 0 5 0 0 0 2 9 6 7 0 7 2 3 7 9 8 1 1 0 7 7 9 0 1
REPORT NO. DOCKET NUMBER EVENT DATE REPORT DATE

EFFECT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 3 During normal operation while performing SI 4.2.B-7, the setpoint for pressure switch
 0 4 68-96 switch 1, Reactor Low Pressure, was found set above the T.S. limit of 500
 0 5 +/-15 psig (Table 3.2.B). The actual value found was 558 psig. The redundant switch
 0 6 was operable. There was no hazard to the public health or safety. Previous occur-
 0 7 rences: 259/7824, 259/777, and 259/772.

0 9 I A X Z I N S T R U S Z
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 LTR NO. REPORT NUMBER 7 9
 21 22 23 24 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

E Z Z 0 0 0 0 Y N L B 0 8 0
ACTION CATEGORY EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM NO. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for the out-of-tolerance condition of the Barton Model 288 was instrument
 1 1 drift. The switch was readjusted to the proper setpoint and functionally tested for
 1 2 repeatability. This is not a generic problem (three previous occurrences - one in
 1 3 1978 and two in 1977).

1 5 E 0 9 3 NA B Surveillance testing
FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 Z Z NA NA
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 0 0 0 Z NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 0 0 0 NA
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 Z NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 N NA
PUBLICITY ISSUED DESCRIPTION

DUPLICATE
 7908280695
 NRC USE ONLY

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7910 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 7/23/79 Time of Occurrence 9:00 a.m. Unit 3

Identification and Description of Occurrence:

The setpoint for PS-68-96 was found to be 558 psig. The T.S. limit is 500 +/-15 psig.

Conditions Prior to Occurrence:

Normal operation.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

The redundant switch was tested satisfactorily.

Apparent Cause of Occurrence:

Instrument drift.

Analysis of Occurrence:

None.

Corrective Action:

Readjusted and functionally tested switch for repeatability. This is not a generic problem (one in 1978 and two in 1977).

Failure Data:

259/7824, 259/777, and 259/772.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor.

*Revision: 



10/10/10