

LICENSEE EVENT REPORT

CONTROL NO. (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | B | R | F | 2 | 7 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 2

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 0 | 0 | 1 | 7 | 9 | 8 | 1 | 0 | 2 | 9 | 7 | 9 | 0

02 | During normal operation, Rod Block Monitor (RBM) "A" was made nonfunctional due to a shorted lamp base. RBM "B" was damaged in the repairing of RBM "A." Both channels were nonfunctional for approximately six hours. Administrative controls were initiated in accordance with T. S. table 3.2.C.7.d. There was no hazard to the public health or safety. There have been no previous occurrences.

09 | I | B | 11 | A | 12 | A | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 | 17 | 7 | 9 | 18 | 0 | 2 | 2 | 19 | 0 | 3 | 20 | L | 21 | 0 | 22 | Y | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9

10 | A short circuit occurred when changing a lamp bulb in RBM "A." RBM "B" was damaged while repairing RBM "A." The power supplies in both channels were repaired and returned to service in approximately six hours. Employees have been cautioned to exercise care to prevent recurrence.

15 | E | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator Observation | 32

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39


18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | N | 44 | NA | 45

7911010391

NRC USE ONLY



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 7922 Technical Specification Involved Table 3.2.C.7.d

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 10/1/79 Time of Occurrence 0230 Unit 2

Identification and Description of Occurrence:

Rod Block Monitor (RBM) "A" malfunctioned due to shorting a lamp bulb during changeout. RBM "B" was damaged in the process of repairing RBM "A." Both channels were out of service approximately six hours.

Conditions Prior to Occurrence:

Unit 1 @ approximately 802 MWe.
Unit 2 @ approximately 1095 MWe.
Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe:

The action specified in note 7(d) of Table 3.2.c. in the technical specification was initiated immediately.

Apparent Cause of Occurrence:

Human error.

Analysis of Occurrence:

None

Corrective Action:

The assemblies damaged were repaired, functionally tested, and returned to service. Employees were cautioned to exercise more care during operation and maintenance activities.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: ASD

