

Update Report - Previous Report LICENSEE EVENT REPORT

Date 6/5/79

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5

CON'T

0 1 | L | 6 | 5 | 0 | 0 | 0 | 0 | 2 | 9 | 6 | 7 | 0 | 5 | 0 | 7 | 7 | 9 | 6 | 1 | 1 | 0 | 7 | 7 | 9 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, an erratic indication of the torus hydrogen sensor,

0 3 | H2M-76-38, was observed. The system was declared inoperable and a 30-day operating

0 4 | limit was established per T.S. 3.7.H.4. There was no redundant system. There was

0 5 | no hazard to the public health or safety. Previous events: 259/7815 and 259/7820.

0 6

0 7

0 8

0 9 | S | E | E | I | N | S | T | R | U | E | Z

17 | 7 | 9 | 0 | 0 | 6 | 0 | 3 | L | I

A | F | Z | Z | 0 | 0 | 0 | 0 | Y | Y | N | G | 0 | 8 | 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The hydrogen sensor, GE part number 47E226428G2, was replaced and tested satisfactory

1 1 | while the unit was down for other maintenance. Design change request 1194 will

1 2 | replace present monitoring system.

1 3

1 4

1 5 | E | 0 | 8 | 0 | NA | A | Operator observation

1 6 | Z | Z | NA | NA

1 7 | 0 | 0 | 0 | Z | NA


1 8 | 0 | 0 | 0 | NA

1 9 | Z | NA

2 0 | N | NA

7911140 353

NRC USE ONLY



LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 796 Technical Specification Involved 3.7.H.

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 5/7/79 Time of Occurrence 1100 Unit 3

Identification and Description of Occurrence:

Operations personnel observed erratic indications on the torus hydrogen sensor H₂M-76-38. The system was declared inoperable.

Conditions Prior to Occurrence:

Normal operation.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe:

A 30-day operating limit was established in accordance with T.S. 3.7.H.4.

Apparent Cause of Occurrence:

Defective hydrogen sensor.

Analysis of Occurrence:

None

Corrective Action:

Replaced hydrogen sensor. Design change request 1194 will replace the General Electric hydrogen monitoring system with a system whose sensors are external to the primary containment. Primary containment modification is being completed on unit 3 during the present refueling outage.

Failure Data:

259/7815 and 259/7820

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

12