

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5				
71	8	LICENSEL CODE						14		LICENSE NUMBER										25		LICENSE TYPE					30			57	CAT	58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	9	6	7	1	2	0	7	7	9	8	0	1	0	4	8	0	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During unit 3 refueling outage RCIC failed to reach rated flow as per T.S. 3.5.F.1. (1) |

03 | There was no danger to health or safety of public and no significant resulting events.

0	4	No previous occurrences. HPCI was verified operable.
---	---	--

05 _____

0	6	
---	---	--

07 _____

0	1	
7	8	9

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT		COMP. SUBCODE		VALVE SUBCODE	
C	E	E		F		I	N	S	T	R	U
11	12	13	14	15	16	17	18	19	20	21	22
EVENT YEAR		REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION			
7	9			0	2	6		0	3		0
23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
A	Z	Z	Z	Z		0	0	0	0	Y	
18	19	20	21	22	23	24	25	26	27	28	29
NPRO-4 FORM NO.		PRIME COMP. SUPPLIER		COMP. NEW MANUFACTURER							
Y	N	W	2	9	0						
24	25	26	27	28	29						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

10 | The RCIC EGM box had a defective high trim potentiometer. The EGM box was replaced.

11 | Type EGM: Model 8270-849. No recurrence control required.

1	2	
---	---	--

13

1 4 _____

1 5 FACILITY STATUS (28) H 29 0 0 0 0 % POWER NA OTHER STATUS (30) B DISCOVERY DESCRIPTION (32) Operator observed

ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	6	Z	(33)	Z (34) NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		
64		
65		
66		
67		
68		
69		
70		
71		
72		
73		
74		
75		
76		
77		
78		
79		
80		
81		
82		
83		
84		
85		
86		
87		
88		
89		
90		
91		
92		
93		
94		
95		
96		
97		
98		
99		
100		

1	7	0	0	0	(37)	Z	(38)	NA
7	8	9	10	11	12	13		
PERSONNEL INJURIES								
NUMBER DESCRIPTION (41)								

NUMBER		DESCRIPTION
1	2	
0	0	0
0	0	40
		NA

TYPE		DESCRIPTION
Z	(17)	NA

PUBLICITY
 ISSUED DESCRIPTION: (45)
 2 0 N 44 NA
 NRC USE:

NAME OF PREPARER _____

PHONE: 8001 090 407

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7926 Technical Specification Involved T.S. 3.5.F.1.(1)

Reported Under Technical Specification 6.7.2.b.2

Date of Occurrence 12/7/79 Time 1140 Unit 3

Identification and Description of Occurrence:

RGIC failed to reach rated flow.

Conditions Prior to Occurrence:

Unit 1 @ 83%.

Unit 2 @ 80%.

Unit 3 @ 0% refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

HPCI proved operable.

Apparent Cause of Occurrence:

EGM box failed due to a defective high trim potentiometer.

Analysis of Occurrence:

There was no danger to health or safety of the public, no activity release, no damage to plant equipment.

Corrective Action:

The EGM box was replaced.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

