

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 | A | L | B | R | F | 3 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | | (5)
 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T REPORT SOURCE (L) (6) | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 6 | (7) | 1 | 2 | 3 | 0 | 7 | 9 | (8) | 0 | 1 | 2 | 5 | 8 | 0 | (9)
 7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(02) | With unit 3 in a shutdown condition Technical Specification 3.9.A.4.b does not allow |
 (03) | startup with the Bus Tie Board deenergized. The Bus Tie Board was deenergized due to |
 (04) | feeder cable failure. There was no danger to health or safety of public. No redundant |
 (05) | systems. No previous occurrences. |
 (06) | |
 (07) | |
 (08) | |

SYSTEM CODE (E) (B) (11) CAUSE CODE (E) (12) CAUSE SUBCODE (A) (13) COMPONENT CODE (E) (L) (E) (C) (O) (N) (14) COMP. SUBCODE (Z) (15) VALVE SUBCODE (Z) (16)
 7 8 9 10 11 12 13 18 19 20
 (17) LER/RO REPORT NUMBER (8) (0) (21) (22) (23) SEQUENTIAL REPORT NO. (0) (0) (1) (24) OCCURRENCE CODE (0) (3) (25) REPORT TYPE (L) (26) REVISION NO. (0) (27)
 ACTION TAKEN (C) (18) FUTURE ACTION (Z) (19) EFFECT ON PLANT (A) (20) SHUTDOWN METHOD (B) (21) HOURS (0) (3) (8) (8) (22) ATTACHMENT SUBMITTED (Y) (23) NPRO-4 FORM SUB. (Y) (24) PRIME COMP. SUPPLIER (L) (25) COMPONENT MANUFACTURER (T) (3) (1) (4) (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(10) | The feeder cable to the Bus Tie Board failed due to a fault. An instruction has been |
 (11) | written and the work is in progress to install overhead cables to bypass the bad cable |
 (12) | sections. Triangle, 500 MCM cable. No recurrence control required. |
 (13) | |
 (14) | |

FACILITY STATUS (G) (28) % POWER (0) (0) (0) (29) OTHER STATUS (NA) (30) METHOD OF DISCOVERY (Z) (31) DISCOVERY DESCRIPTION (NA) (32)
 7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (NA) (35) LOCATION OF RELEASE (NA) (36)
 7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER (0) (0) (0) (37) TYPE (Z) (38) DESCRIPTION (NA) (39)
 7 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER (0) (0) (0) (40) DESCRIPTION (NA) (41)
 7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE (Z) (42) DESCRIPTION (NA) (43)
 7 8 9 10 80

PUBLICITY ISSUED (Y) (44) DESCRIPTION (Unit 3 outage) (45)
 7 8 9 10 68 69 80

8001290 598

10

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 801 Technical Specification Involved 3.9.A.4.b
Reported Under Technical Specification 6.7.2.b.(2)
Date of Occurrence 12/30/79 Time of Occurrence 2230 Unit 3

Identification and Description of Occurrence:

With unit 3 in a shutdown condition Technical Specifications do not allow startup with the bus tie board deenergized.

Conditions Prior to Occurrence:

Unit 1 @ 82%.
Unit 2 @ 97%.
Unit 3 @ 0%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Unit in shutdown condition.

Apparent Cause of Occurrence:

The Bus-Tie-Board was deenergized due to feeder cable failure.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

An instruction has been written to install overhead cables to bypass the bad sections of cable.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision



