

11-11-52



11-11-52

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8006 Technical Specification Involved 3.6.F.5

Reported Under Technical Specification 6.7.2.B.2

Date of Occurrence 2/3/80 Time of Occurrence 1420 Unit 2

Identification and Description of Occurrence:

2A Reactor Recirculation Pump was accidentally tripped while running electrical checks on 2B Recirculation Pump resulting in both pumps being out of service.

Conditions Prior to Occurrence:

Unit 1 @ 0% refueling outage.

Unit 2 @ 50% 2B recirculation pump out of service.

Unit 3 @ 85%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

NA

Apparent Cause of Occurrence:

The label on Recirculation Pump Trip breakers (labeled "A" and "B") was misinterpreted to indicate pump breakers. The labeling system of these breakers denotes logic division "A" or "B."

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

Recirculation Pump Trip breakers are being relabeled to indicate pump and logic division associated with each breaker.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

11-11-52