

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8006 Technical Specification Involved 3.5.B.3
Reported Under Technical Specification 6.7.2.b (2)
Date of Occurrence 2/17/80 Time of Occurrence 1130 Unit 3

Identification and Description of Occurrence:

Flow test MRI-303 was being run on the RHR pump seal coolers when it was noted that the EECW flow did not meet the minimum requirement of 4 gpm.

Conditions Prior to Occurrence:

Unit 1 - scheduled refueling outage
Unit 2 - hot shutdown
Unit 3 - 100% steady state power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.
SI's run to verify that redundant systems were operable per T.S. 3.5.B.3

Apparent Cause of Occurrence:

Shells and mud restricted flow through valve in the pump seal cooler system.

Analysis of Occurrence:

No danger to health or safety of the public, no release of activity, no damage to plant or equipment, no significant resulting chain of events.

Corrective Action:

Valve was disassembled and line cleaned and flushed. Other heat exchangers will be tested under the periodically scheduled MRI 303.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 



19 11 19