





LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8011 Technical Specification Involved 3.5.B.1 (2) and 3.5.A.1 (2)

Reported Under Technical Specification 6.7.2.b.2.

Date of Occurrence 2/17/80 Time of Occurrence 0454 Unit 2

Identification and Description of Occurrence:

480 V RMOV Board 2B failed to transfer properly during manual transfer. The board was immediately re-energized. The failure to transfer caused the board to be de-energized for a brief period of time. Among the loads lost was RPS MG Set 2B.

Conditions Prior to Occurrence:

Unit 1 @ 0% refueling outage.

Unit 2 @ 0% Hot Shutdown

Unit 3 @ 99%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

NA

Apparent Cause of Occurrence:

The failure was caused by dirty moveable contacts on the normal feeder breaker.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

The contacts were cleaned and transfer verified operable.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 

