

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [A][L][B][R][F][2] [2][0][0]-[0][0][0][0][0]-[0][0] [3][4] [1][1][1][1] [4] [5]

CON'T REPORT SOURCE [L][6] [0][5][0][0][0][2][6][0] [7][0][2][1][6][8][0] [8][0][3][3][1][8][0] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0][2] Due to a procedural inadequacy, the intent of SI 4.2.13-44 was not met because RHR's C pump was in operation in the torus cooling mode when then the SI was performed. This [0][3] prevented receipt of all the required acknowledgements associated with the testing [0][4] of the RHR or CS pumps running auto blowdown permissive logic of ADS. There was [0][5] no hazard to the health or safety of the public. No previous occurrences. [0][6] Redundance not required. [0][7]

[0][9] SYSTEM CODE [Z][Z] (11) CAUSE CODE [D] (12) CAUSE SUBCODE [Z] (13) COMPONENT CODE [Z][Z][Z][Z][Z][Z] (14) COMP. SUBCODE [Z] (15) VALVE SUBCODE [Z] (16)

(17) LER NO REPORT NUMBER [8][0] (21) (22) EVENT YEAR [] (23) SEQUENTIAL REPORT NO. [0][1][4] (24) OCCURRENCE CODE [0][3] (28) REPORT TYPE [L] (30) REVISION NO. [0] (32) ACTION TAKEN [G] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0][0][0][0] (22) ATTACHMENT SUBMITTED [Y] (23) NPD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [Z] (25) COMPONENT MANUFACTURER [Z][9][9][9] (47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1][0] Intent of surveillance test was not met due to procedural inadequacy for the experienced [1][1] plant configuration. Procedure to be revised. SI 4.2.B-44 was performed completely [1][7] on 2/17/80 at 22:45 and daily thereafter until unit was in C/S condition. [1][3] [1][4]

[1][5] FACILITY STATUS [G] (28) % POWER [0][0][0] (29) OTHER STATUS NA (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION Reviewer Observation (32)

[1][6] ACTIVITY CONTENT [Z] (33) RELEASED OF RELEASE [Z] (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)

[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION NA (39)


[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION NA (41)

[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION NA (43)

[2][0] PUBLICITY ISSUED [N] (44) DESCRIPTION NA (45)

NAME OF PREPARER _____

PHONE: _____ 800 407 0289



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8014 Technical Specification Involved 4.5.E.2
Reported Under Technical Specification 6.7.2.b(3)
Date of Occurrence 2/16/80 Time of Occurrence 2245 Unit 2

Identification and Description of Occurrence: Due to procedural inadequacy, the intent of SI 4.2.B-44 was not met because RHR pump "C" was running in torus cooling mode when the SI was being performed. This prevented the receipt of all required acknowledgements associated with the testing of RHR and CSS pumps running auto blowdown permissive logic of ADS.

Conditions Prior to Occurrence:
The unit was shutdown and in hot standby condition at greater than 122 PSIG following a scram at 1328 on 2/15/80. HPCI was declared inoperable at 1830 on 2/16/80 because of a cracked pedestal.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

T. S. 4.5.E.2 required SI 4.2.B-44 to be run.

Apparent Cause of Occurrence:

Procedural inadequacy.

Analysis of Occurrence:

There was no damage to plant equipment, no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

Applicable procedures will be revised.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

