

### LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] | A | L | B | R | F | 3 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | [ ] | [ ] | (5)

7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
[0][1] | REPORT SOURCE [L] (6) | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 6 | (7) | 0 | 5 | 1 | 2 | 8 | 0 | (8) | 0 | 6 | 1 | 0 | 8 | 0 | (9)

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
[0][2] | During normal operation while performing S.I. 4.5.F.1 d&e, RCIC tripped on overspeed

[0][3] | due to loss of speed control. Reference T.S. 3.5. F.2. HPCI was proven operable.

[0][4] | There was no danger to health or safety of the public. No previous occurrences.

[0][5] |

[0][6] |

[0][7] |

[0][8] |

[0][9] | SYSTEM CODE [C][E] (11) | CAUSE CODE [E] (12) | CAUSE SUBCODE [F] (13) | COMPONENT CODE [I][N][S][T][R][U] (14) | COMP. SURCODE [X] (15) | VALVE SUBCODE [Z] (16)

(17) LER/RO REPORT NUMBER [8][0] | EVENT YEAR [8][0] | SEQUENTIAL REPORT NO. [0][1][4] | OCCURRENCE CODE [0][3] | REPORT TYPE [L] | REVISION NO. [0]

ACTION TAKEN [C] (18) | FUTURE ACTION [Z] (19) | EFFECT ON PLANT [Z] (20) | SHUTDOWN METHOD [Z] (21) | HOURS (22) [0][0][0][0] | ATTACHMENT SUBMITTED [Y] (23) | NPD-4 FORM SUB. [N] (24) | PRIME COMP. SUPPLIER [L] (25) | COMPONENT MANUFACTURER [M][4][5][5] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
[1][0] | A diode (VR9) in the EGM box failed due to end of life. The EGM box was replaced and

[1][1] | calibrated. Motorola diode, type IN2816B. No recurrence control required.

[1][2] |

[1][3] |

[1][4] |

[1][5] | FACILITY STATUS [E] (28) | % POWER [1][0][0] (29) | OTHER STATUS NA (30) | METHOD OF DISCOVERY [B] (31) | DISCOVERY DESCRIPTION Found during S.I. 4.5.F.1 d & e (32)

[1][6] | ACTIVITY CONTAINED [Z] (33) | RELEASED OF RELEASE [Z] (34) | AMOUNT OF ACTIVITY NA (35) | LOCATION OF RELEASE NA (36)


[1][7] | PERSONNEL EXPOSURES NUMBER [0][0][0] (37) | TYPE [Z] (38) | DESCRIPTION NA (39)

[1][8] | PERSONNEL INJURIES NUMBER [0][0][0] (40) | DESCRIPTION NA (41)

[1][9] | LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) | DESCRIPTION NA (43)

[2][0] | PUBLICITY ISSUED [N] (44) | DESCRIPTION NA (45)  
**8006170 592**

NAME OF PREPARER \_\_\_\_\_ PHONE \_\_\_\_\_



LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8014 Technical Specification Involved 3.5.F.2

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 5/12/80 Time of Occurrence 1015 Unit 3

Identification and Description of Occurrence:

While performing S.I. 4.5.F.1 d&e RCIC tripped on overspeed due to loss of speed control.

Conditions Prior to Occurrence:

Unit 1 @ 98%

Unit 2 @ 99%

Unit 3 @ 100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

HPCI proven operable.

Apparent Cause of Occurrence:

Loss of speed control was due to the end of life of a diode in the EGM box.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

The EGM box was replaced and calibrated.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 

