

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
 7 8 9 14 15 25 26 30 37 CAT 38  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE  
 CON'T  
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 6 | 7 | 0 | 5 | 2 | 7 | 8 | 0 | 8 | 0 | 6 | 2 | 5 | 8 | 0 | 9  
 2 8 60 61 68 69 74 75 80  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | During normal operation the drywell sump flow transmitter FT-77-16 was discovered

0 3 | to have an output signal shift. Reference T.S. 3.6.C.1. No redundant systems.

0 4 | No danger to health or safety of public. Previous occurrence: 259/73007.

0 5 |

0 6 |

0 7 |

0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SURCODE		VALVE SUBCODE		
M	C	E		E		I	N	S	T	R	U	T	Z	
(11)		(12)		(13)		(14)				(15)	(16)			
EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO				
8	0	—		0	1	9	/	0	3	L	—	0		
(17) LER/RD REPORT NUMBER		(21)		(22)		(23)		(24)		(25)		(26)		
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
C	Z	Z	Z	0	0	0	0	Y	N	L	G	0	8	0
(18)	(19)	(20)	(21)	(22)	(23)		(24)	(25)	(26)	(27)	(28)	(29)	(30)	

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Flow transmitter, FT-77-16, suffered a zero shift each time sump pumps were run.
1	1	Cause of shift unknown. GE type GEMAC, Model 555111BDAA3AAA, flow transmitter was
1	2	replaced and instrument loop calibrated. No recurrence control planned due to low
1	3	incident rate.
1	4	

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	0	9	9	NA	A	Operator observed	
7	8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	Z	NA	NA				
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		TYPE		DESCRIPTION					
1	7	0	0	0	0	NA			
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		TYPE		DESCRIPTION					
1	8	0	0	0	0	NA			
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	NA						
7	8	9	10	11	12	13	14	15	16
PUBLICITY		DESCRIPTION							
2	0	N	NA						
7	8	9	10	11	12	13	14	15	16
ISSUED									
2	0	N	NA						
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER

PHONE:



2000

LER SUPPLEMENTAL INFORMATION

BFRO-50-296 / 8019 Technical Specification Involved 3.6.C.1

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 5/27/80 Time of Occurrence 0200 Unit 3

Identification and Description of Occurrence:

Drywell sump flow transmitter FT-77-16 was discovered to suffer a zero shift each time the sump pump was run.

Conditions Prior to Occurrence:

Unit 1 @ 97%

Unit 2 @ 98%

Unit 3 @ 99%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Sump pumps locked out until flow transmitter returned to service.

Apparent Cause of Occurrence:

Cause of zero shift unknown.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

The transmitter was replaced and loop calibrated.

Failure Data:

BFRO-50-259/73007

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 



Handwritten scribbles and marks in the top right corner.