





LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 80 20 Technical Specification Involved 3.9.B.2

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 6/9/80 Time of Occurrence 2130 Unit 3

Identification and Description of Occurrence:

3B diesel generator auxiliary oil pump tripped out. The overloads were replaced and the motor restarted at 1610. The motor later tripped again. 3B diesel generator was declared inoperable at 2310 hrs.

Conditions Prior to Occurrence:

Unit 1 @ 99%

Unit 2 @ 95%

Unit 3 @ 96%

Action specified in the Technical Specification Surveillance Requirements not due to inoperable equipment. Describe.

The other 3 diesel generators, CS and RHR (LPCI and containment cooling), were proven operable.

Apparent Cause of Occurrence:

The auxiliary oil pump motor tripped due to bearing failure.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury, and no danger to the health or safety of the public.

Corrective Action:

The auxiliary oil pump motor was replaced.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 